

**CALIBRATOR CATHODE FOLLOWER
RESISTOR ADDED TO ASSURE
+100V CF OUTPUT LEVEL**

See SQB

M1001

Effective Prod s/n 398

Usable in field instruments s/n 101-397

DESCRIPTION:

To enable the setting of the cathode voltage of the Calibrator Cathode Follower at the required 100v level, a resistor was added from +225v to the grid of the Cathode Follower.

Parts Removed:

Parts Added:

R681 1M 1/2w 10% 302-155

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Install R681, a 1Meg 1/2w resistor, between pin 1 of V246A and pin 6 of V670, located on the Power chassis.

**SWEEP REWIRING REQUIRES VALUE CHANGE
OF ADJUSTMENT CAPACITOR, C254**

INFORMATION ONLY

M1009

Effective Prod s/n 410

DESCRIPTION:

The addition of temflex tubing on 3 wires running from the Main Sweep Time/CM switch to the Sweep chassis necessitated changing the value of C254 from a 1.5-7pf ceramic capacitor to an 0.5-5pf variable tubular capacitor.

This mod is superseded by M1019.

Parts Removed:

Parts Added:

C254 1.5-7 pf var NPO 281-005

C254 0.5-5 pf tubular 281-002
Tubing, temflex no.7 (3-1/2")

**VERT AMP POWER SUPPLY DECOUPLING
RESISTORS WATTAGE RATING INCREASED**

See SQB

M1002

Effective Prod s/n 415

Usable in field instruments s/n 101-414

DESCRIPTION:

To increase the dissipation of the Plug-in and Vertical Amplifier decoupling resistors in the -150v, +100v and +350v supplies the wattage rating of R515, R516 and R518 was increased from 1/2 watt to 1 watt.

Parts Removed:

R515, R516, 100Ω 1/2w 10% 302-001
R518

Parts Added:

R515, R516, 100Ω 1w 10% 304-001
R518

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Replace R515, R516 and R518 (100Ω 1/2w resistors) with 100Ω 1w resistors. The resistors are located on the Vertical Amplifier chassis on ceramic strips directly above C650.

**SWEEP STABILITY DIVIDER
RESISTOR TOLERANCE TIGHTENED
TO IMPROVE STABILITY**

INFORMATION ONLY

M1004

Effective Prod s/n 416

DESCRIPTION:

The Sweep Stability divider resistor tolerance was changed to 5% to tighten the divider network specifications.

Parts Removed:

R47 470 k 1/2W 10% 302-474

Parts Added:

R47 470 k 1/2W 5% 301-474

**SWEEP GENERATOR CAPACITOR
ADDED TO IMPROVE SAWTOOTH
LINEARITY AT HIGH SWEEPSPEEDS**

See SQB

M1014

Effective Prod s/n 456

Usable in field instruments s/n 101-455

DESCRIPTION:

To improve linearity of the sawtooth waveform at high Sweep speeds, a capacitor was added between Miller Generator plates and the cathode of the Cathode Follower to maintain a near-constant current through the loads at all Sweep speeds.

Parts Removed:

Parts Added:


C96 82pf 500v 281-528

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Install C96, an 82pf 500v capacitor, between CSC-26 and CSD-27 on the Sweep chassis.



**VERTICAL AMPLIFIER DRIVER CIRCUITRY
REDESIGNED TO ELIMINATE PARASITIC
OSCILLATION FOR EASIER TIMING
AND TO INCREASE BANDWIDTH**

INFORMATION ONLY

M1029

Effective Prod s/n 582

DESCRIPTION:

To eliminate parasitic oscillations, driver components were changed and layout revised. This resulted in easier tuning and increased bandwidth.

A portion of this mod is superseded by M1085.

Parts Removed:

C520	0.01 μ f 400v	285-510
C901	1.5pf 500v	281-526
R528, R532	1k 1/2w 10%	302-102

Parts Added:

C520	0.01 μ f 500v	283-002
R528, R532	47 Ω 1/2w 10%	302-470

DELAY LINE DRIVER COMMON
CATHODE RESISTOR REPLACED TO
ELIMINATE OVER-COMPENSATION

INFORMATION ONLY

M1031

Effective Prod s/n 582

DESCRIPTION:

To remove the cause of over-compensation in the Delay Line driver, the common cathode resistor was reduced in value and tolerance. A 3.9Ω 1W 10% resistor was substituted for the 3.9Ω 1W 5% value at s/n 582. The 5% value became effective at approximately s/n 890.

Parts Removed:

R503 5.6Ω 1W 10% 307-002

Parts Added:

R503 3.9Ω 1W 5% 307-004

VERTICAL AMPLIFIER OUTPUT
PEAKING COILS DECREASED TO
MATCH NEW CONICAL CRT

INFORMATION ONLY

M1022

Effective Prod s/n 585

DESCRIPTION:

Values of the Vertical Amplifier output coils were reduced to compensate for the inherent interelectrode capacitance of the early CRT's.

Parts Removed:

L634, L635 $9.3\mu\text{H}$ fixed 108-069

Parts Added:

L634, L635 $8.8\mu\text{H}$ fixed 108-057

SWEEP CAL AND MAG GAIN
RANGE INCREASED

INFORMATION ONLY

M1019-1

Effective Prod s/n 613

DESCRIPTION:

The range of the adjustments for the Swp Cal and Mag Gain controls was increased by replacing them with components of twice their values.

Parts Removed:

R266 5k 311-011
R270 1k 311-006

Parts Added:

R266 10k 311-016
R270 2k 311-008

SWEEP MAGNIFIER TIMING AND LINEARIZATION IMPROVED WITH ADDED VARIABLE CAPACITORS

See SQB

M1019-2

Effective Prod s/n 613

Usable in field instruments s/n 101-612

DESCRIPTION:

To linearize and improve the Sweep timing in the 0.1 sec/cm and 0.2 μ sec/cm Magnifier positions, the mica plate resistors R278 and R286 were changed to tapped resistors, and two variable capacitors were added between the taps and cathodes of the Sweep Cathode Follower CRT drivers.

Parts Removed:


R278	25 k 8w 1%	310-503
R286	30k 5w 1%	310-504

Parts Added:

R278	6-25 k 7w 1%	310-506
R286	6-30k 7w 1%	310-507
C278, C286	3-12pf variable	281-009

INSTALLATION INSTRUCTIONS:

- Remove R276 (25 k 8w mica plate resistor) and R286 (30k 8w mica plate resistor), located on the ceramic strips above V265 and V272, respectively, on the Sweep chassis.
- Install R278, a 6-25 k tapped 7w 1% resistor, between CSE and CSF as shown in drawing.
- Install R286, a 6-30k tapped 7w 1% resistor, between CSE and CSF as shown in drawing.
- Install C278 and C286, 3-12pf variable capacitors, on CSE as shown in drawing.



**SWEEP HF TIMING CAPACITOR REPLACED
AND FEEDBACK CAPACITOR ADDED
TO INCREASE ADJUSTMENT RANGE**

INFORMATION ONLY

M1019-3

Effective Prod s/n 613

DESCRIPTION:

To give adequate range of adjustment for C254, it was changed to a 3-12 pf value and a compensating feedback capacitor was added to the divider circuit across R259.

Parts Removed:

C254 0.5-5 pf variable 281-002

Parts Added:

C254 3-12 pf variable 281-007
C258 1.5 pf 500v 281-526

**SWEEP HF COMPENSATION CAPACITOR
REPLACED TO EXTEND RANGE**

INFORMATION ONLY

M1035

Effective Prod s/n 613

DESCRIPTION:

To provide adequate range of adjustment for C267, capacitors C266 and C267 were replaced by a single 9-180 pf variable capacitor at C267. This change should be made at the time M1019 is performed.

Parts Removed:

C266 47 pf 500v 281-518
C267 8-50 pf var 281-022

Parts Added:

C267 9-180 pf var 281-023

**PATCH CORD ADDED TO ACCESSORIES
PACKAGE ALLOWS 'PATCH' OF
CAL VOLTAGE TO INPUT**

INFORMATION ONLY

M1038

Effective date 11-27-54

DESCRIPTION:

To allow the Cal voltage to be 'patched' to the input, a cord with banana connectors was added to the accessory package.

Parts Removed:

Parts Added:

W530, Cord, consisting of:

Plug, banana, female 134-013
Cable, test lead no.18 bk (16') 175-010

**POWER SUPPLY 'CURRENT-MEASURING'
PROTECTIVE RESISTOR REPLACED TO
PROVIDE PROPER DISSIPATION**

See SQB

M1041

Effective Prod s/n 696

Usable in field instruments s/n 101-695

DESCRIPTION:

To assure the proper dissipation rating of the 'Current-Measuring' protective resistor in the -150v and +100v supply section of the power supply, the 150v resistor R732 was replaced with two 10 Ω 1w resistors (R732 and R733) in parallel, and the +100v resistor R740 was increased to 1w.

Parts Removed:

R732	10 Ω 2w 10%	306-100
R740	10 Ω 1/2w 10%	302-100

Parts Added:


R732, R733,	10 Ω 1w 10%	304-100
R740		

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- Replace R732, 10 Ω 2w 10% resistor located on the ceramic strips above C740 on the power supply chassis, with two 10 Ω 1w 10% resistors in parallel.
- Replace R740, 10 Ω 1/2w 10% resistor located on the ceramic strips next to R732, with a 10 Ω 1w 10% resistor.



**VERTICAL AMPLIFIER OUTPUT
PEAKING COILS REPLACED TO
IMPROVE TRANSIENT RESPONSE**

INFORMATION ONLY

M1043

Effective Prod s/n 696

DESCRIPTION:

To supersede M1022 and improve transient response, peaking coils L634 and L635 were returned to their original values. A decrease in the interelectrode capacitances of the later conical CRT's made the change possible.

Parts Removed:

L634, L635 9.3 μ h fixed 108-069

Parts Added:

L634, L635 8.8 μ h fixed 108-057

**INTERNAL TRIGGER STABILITY IMPROVED
WITH ADDED PARASITIC SUPPRESSOR**

See SQB

M1049

Effective Prod s/n 833

Usable in field instruments s/n 101-832

DESCRIPTION:

To improve the internal trigger circuit stability, a parasitic suppressor R534 was added between the plate of the Internal Trigger Amplifier and the grid of the Internal Trigger Cathode Follower.

Refer to M1084 which should be installed with M1049.

Parts Removed:

Parts Added:

R534 47 Ω 1/2w 10% 302-470

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Install R534, a 47 Ω 1/2w 10% resistor, between pin 6 of V527 and pin 2 of V535 on the Driver chassis.

**INTERNAL TRIGGER BYPASS CAPACITOR
ADDED TO IMPROVE STABILITY**

See SQB

M1065

Effective Prod s/n 858

Usable in field instruments s/n 101-857

DESCRIPTION:

To improve the stability of the Internal Trigger Amplifier, the plate of V527R was bypassed to ground with an 0.005 μ f capacitor.

Parts Removed:

Parts Added:

C532	0.005 μ f	283-001
------	---------------	---------

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Install C532, an 0.005 μ f capacitor located on the Driver chassis, between pin 1 of V527 and a ground lug on the socket.

**MAIN SWEEP MULTI BAL CONTROL
ADDED TO PREVENT ERRONEOUS
RESETTING OF MAIN SWEEP**

INFORMATION ONLY

M1061

Effective Prod s/n 895

DESCRIPTION:

Erroneous resetttings of the main sweep was reduced by adding a balance control in the grid circuit of the Main Sweep Multivibrator. Additional circuit changes were required to allow the addition of the Multi Bal Control.

Parts Removed:

R32	1.5 k 1/2W 10%	302-152
-----	----------------	---------

Parts Added:

R32	820 Ω 1/2W 10%	302-821
R64	2.5 k 1/10W	311-010

**VERTICAL OUTPUT AMPLIFIER RESISTOR
TOLERANCE TIGHTENED TO IMPROVE
FREQUENCY RESPONSE AND UNIFORMITY**

INFORMATION ONLY

M1071

Effective Prod s/n 970

DESCRIPTION:

To obtain uniformity of frequency and transient response in the Output Vertical Amplifier, the damping resistors were changed from 10% to 5% tolerance.

Parts Removed:

R634, R635 820Ω 1/2w 10% 302-821

Parts Added:

R634, R635 820Ω 1/2w 5% 301-821

**DELAY LINE INDUCTORS REPLACED
WITH VARIABLES FOR EASIER HIGH
FREQUENCY ADJUSTMENT**

INFORMATION ONLY

M1051

Effective Prod s/n 997

DESCRIPTION:

To improve adjustment of the HF response of the delay line drivers the two fixed coils were replaced with variables and set in test. Adjustment access holes were made in the lower horizontal member of the Delay Line chassis.

Parts Removed:

Coil, fixed, CF562 (2) No number

Parts Added:

L900A, L901A 2.8-5.0μh 114-012

**SWEEP OUTPUT AMPLIFIER AND
CF TUBES REPLACED WITH AGED
6BQ7A's TO IMPROVE STABILITY**

INFORMATION ONLY

M1084

Effective Prod s/n 1030

DESCRIPTION:

To improve the stability of the Sweep Amp and CF, the raw tubes used were replaced with aged 6BQ7A's.

Parts Removed:

V265, V272 6BQ7A, raw 154-028

Parts Added:

V265, V272 6BQ7A, aged 157-022

**VERTICAL AMP DRIVER TUBES CHANGED TO
6CL6's AND DC FILAMENT SUPPLY ADDED
TO REDUCE DC DRIFT AND FILAMENT HUM**

See SQB

M1056

Effective Prod s/n 1059

Usable in field instruments s/n 101-1058

DESCRIPTION:

To eliminate residual Miller type feedback present in 6BQ7's, and reduce DC drift and filament hum, these changes were made to the Vertical Amplifier:

- 1) Driver tubes V508 and V509 were replaced with 6CL6's along with other components.
- 2) The 6CL6's were aged, DC balanced, and selected on the basis of their Gm which can range from 1.5 - 3. V508 and V509 should have equal gain.
- 3) The Driver Amp and Rectifier cables also underwent revision. A DC filament supply for V508 and V509 was added with its filter capacitor and resistor.

It was felt that R503, C503, R502 and R504 be changed in all instruments where their values are 3.9 Ω , 0.047 μ f, 10 Ω and 10 Ω respectively.

If the value of R503, connected between pins 8 of V508 and V509, was a 3.9 Ω or 5.6 Ω resistor it was removed along with C503, the 0.047 μ f capacitor connected in parallel with it. It was replaced by a series combination consisting of a 1.2k 1/2w 10% resistor (302-122) and a 100pf 500v capacitor (281-530) in parallel with another 100pf capacitor (281-580). The two 10 Ω resistors, connected between pins 3 of V508 and V509 to the ceramic strip, were replaced by two 39 Ω 1/2w resistors (302-390).

Parts Removed:

C500, C501	2.2pf 500v	281-500
R507, R508, R509, R510	10 Ω 1/2w 10%	302-100
R501	20k 8w 5% WW	308-011
V508, V509	6BQ7A	154-028
Socket, tube, STM9 (3)		136-014
Strip, ceramic, 11-notch		124-016

Parts Added:

C513	0.001 μ f 500v	283-000
C605	2x1000 μ f 15v	290-022
R501	15k 10w 5%	308-024
R511	10k 1w 10%	304-103
R512	39k 1/2w 10%	302-393
R513	1M 1/2w 10%	302-105
R650	220 Ω 2w 10%	306-221
SR650	Selenium	106-016
V508, V509	6CL6, selected	157-021
Socket, tube, STM9G (3)		136-015
Strip, ceramic, 4-notch (2)		124-012
Strip, ceramic, 7-notch		124-014

Parts Required for Field Installation:

Field Modification Kit 040-097

INSTALLATION INSTRUCTIONS:

Refer to kit instructions.

**INTERNAL TRIGGER AMPLIFIER
PARASITIC SUPPRESSOR RESISTOR VALUES
INCREASED TO ELIMINATE OSCILLATION**

See SQB

M1086

Effective Prod s/n 1065

Usable in field instruments s/n 101-1064

DESCRIPTION:

To eliminate possible oscillation in the Internal Trigger Amp, the values of the parasitic suppressors are increased from 47Ω to 150Ω.

Parts Removed:

R528, R532 47Ω 1/2w 10% 302-470

Parts Added:

R528, R532 150Ω 1/2w 10% 302-151

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Replace R528 and R532, 47Ω 1/2w 10% resistors located between contacts on C900 on the delay line and pins 2 and 9 of V527 on the Driver chassis, with 150Ω 1/2w 10% resistor.

**'HF SYNC' TRIGGERING POSITION
ADDED TO TRIGGERING MODE SWITCH**

See SQB

M1077-1

Effective Prod s/n 1075

Usable in field instruments s/n 101-1074

DESCRIPTION:

An additional wafer was added to the SW5 switch section to provide for HF SYNC triggering. In this position the signal bypasses the trigger amplifier and shaper stages and is applied to the grid of the +Multivibrator.

Also see M1088 and M1321.

Parts Removed:

SW1, SW5 TRIG SLOPE
and MODE 260-008

Parts Added:

SW1, SW5 TRIG SLOPE
and MODE 260-099

Parts Required for Field Installation:

See 'Parts Added' and kit listed below.

Field Modification Kit 040-149

INSTALLATION INSTRUCTIONS:

Refer to kit instructions.

**VERT SIG OUT POST ADDED TO FRONT
PANEL AS AN ADDITIONAL FEATURE**

INFORMATION ONLY

M1077-2

Effective Prod s/n 1075

DESCRIPTION:

Provides a Vert Sig Out binding post on the front panel. Components were added to the Vertical Amplifier, and the front panel was changed.

Parts Removed:

Panel, front 333-100

Parts Added:

Panel, front	333-138
Post, binding, 5-way	129-001
R535 47 Ω 1/2 W 10%	302-470
R539 15 k 2 W 10%	306-153
R540 1 M 1/2 W 10%	302-105
C540 0.022 μ F 400 V	285-515

**SWEEP AMP TUBE REPLACED TO IMPROVE
PERFORMANCE AND RELIABILITY**

INFORMATION ONLY

M1058

Effective Prod s/n 1126

DESCRIPTION:

For a more rugged, trouble-free performance, a 6CL6 replaces the 12BY7 at V282. The change required rewiring of the tube socket.

Parts Removed:

C284	8 pf 500 v	281-503
V282	12BY7	154-047

Parts Added:

C284	4.7 pf 500 v	281-501
V282	6CL6	154-031

**SWEEP RELIABILITY AND DC DRIFT
IMPROVED BY REPLACING V70
WITH A RUGGEDIZED TYPE 6CL6**

INFORMATION ONLY

M1060

Effective Prod s/n 1126

DESCRIPTION:

DC drift and reliability is improved by replacing the 12BY7, at V70, with a ruggedized type 6CL6. The change necessitated the rewiring of the tube socket.

It was later discovered that the 12BY7's would sync better at 30 MHz than the 6CL6's, and the instrument was restored to its original condition per M1092.

Parts Removed:

V70	12BY7	154-047
R69	1 k 1/2 W 10%	302-102
R70	47 k 1/2 W 10%	302-473

Parts Added:

V70	6CL6	154-031
R69	1.5 k 1/2 W 10%	302-152
R70	33 k 1 W 10%	304-333

**TRIGGER PEAKING COIL ADDED
TO INSURE HF SYNC AT 30MHz**

See SQB

M1088

Effective Prod s/n 1208

Usable in field instruments s/n 101-1207

DESCRIPTION:

To insure HF synchronization at 30MHz, a 1.1 μ H peaking coil was added in line between the cathode of the Internal Trigger Cathode Follower to the Trigger Slope switch.

This mod is included in Modification Kit 040-149. Also see M1321.

Parts Removed:

Rod, PB1B2 385-074

Parts Added:

L536 1.1 μ H 108-078

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- Locate the bare wire connected between the bakelite post and the ceramic strip on the bottom of the Vertical Amplifier chassis. This is part of the trigger pickoff lead, from V535 to the TRIGGER SLOPE switch.
- Unsolder the bare wire from the pin on the bakelite post.
- Solder one end of the 1.1 μ H coil to this pin.
- Solder the other end of the coil to the bare wire unsoldered in step b and trim the wire as necessary.

**SWEEP SYNC IMPROVED BY
RESTORING V7C TO A 12BY7**

See SQB

M1092

Effective Prod s/n 1220

Usable in field instruments s/n 1126-1219

DESCRIPTION:

M1060 replaced the 12BY7 at V70 with a 6CL6 and rewired the socket accordingly. It was later discovered that the 12BY7's would sync better at 30MHz than the 6CL6's, so the wiring and silkscreening at V70 were changed back to pre-M1060 condition.

Parts Removed:

V70 6CL6 154-031
R69 1.5 k 1/2 W 10% 302-152
R70 33 k 1 W 10% 304-333

Parts Added:

V70 12BY7 154-047
R69 1 k 1/2 W 10% 302-102
R70 47 k 1/2 W 10% 302-473

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- Replace 6CL6 (V70) with a 12BY7.
- Replace the 1.5 k 1/2 W resistor (R69), connected electrically to pin 7 of V70, with a 1 k.
- Replace the 33 k 1 W resistor (R70), connected electrically to pin 7 of V70, with a 47 k 1/2 W.

TIME DELAY RELAY REWIRED TO IMPROVE RELIABILITY

INFORMATION ONLY

M1100

Effective Prod s/n 1283

DESCRIPTION:



R708, a 12Ω 1w 10% resistor, is added to relay K700. This allows a voltage in excess of 6 volts to be applied to K700 relay, insuring a more positive operation at low AC line voltage. Also overcomes peculiar mechanical characteristics of the relay.

This mod is incorporated in Modification Kit 040-085. Also see M1104.

Parts Removed:

Parts Added:

R708 12Ω 1w 10% 304-120



SWEEP MULTI AND UNBLANKING
CF DECOUPLING ADDED TO
ELIMINATE VERTICAL RINGING

See SQB

M1110

Effective Prod s/n 1439

Usable in field instruments s/n 101-1438

DESCRIPTION:

Removed vertical ringing, which occurs within 100 μ sec after the start of the sweep, by adding RC decoupling networks to the plates of the Unblanking CF V55A and the Sweep Multi CF V58B.

Also see M1378.

Parts Removed:

Part Added:



C76, C841	0.005 μ f 500v	283-001
R76, R841	47 Ω 1/2w 10%	302-470

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- Install C76, 0.005 μ f 500v discap, from pin 6 of V58B to the ground lug on V58B socket.
- Replace a bare strap connecting pin 6 of V58B to the +225v supply with a 47 Ω 1/2w 10% resistor.
- Install C841, 0.005 μ f 500v discap, from pin 1 of V55A to the ground lug of V55A socket.
- Remove the ground strap from pin 9 of V55. Install a bare strap from pin 9 to the +350v supply. Install R841, 47 Ω 1/2w 10% resistor, between pin 9 and pin 1 of V55.



**SWEEP AMP DRIVER CF COMPENSATING
RESISTOR ADDED TO IMPROVE
STARTING CHARACTERISTICS**

See SQB

M1112

Effective Prod s/n 1439

Usable in field instruments s/n 101-1438

DESCRIPTION:

To decrease the starting time of the sweep in the fastest ranges, a resistor was added to the grid circuit of the Driver Cathode Follower V240B in series with C241.

Parts Removed:

Parts Added:



R244 2.2k 1/2w 10% 302-222

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- Remove the bare wire strap between CSG-4 and a ground lug on V240.
- Relocate one end of C241, a 4.7pf 500v capacitor, from CSH-4 to ground lug on V240.
- Install R244, a 2.2k 1/2w 10% resistor, between CSG-4 and CSH-4.



SWEEP CABLE STANDARDIZED**INFORMATION ONLY****M1125**

Effective Prod s/n 1514

DESCRIPTION:

To provide a common cable for the 531, 535, 541 and 545 Sweep chassis, the Sweep cable used in the 531 and 535 was made identical to that used in the 541 and 545 by effecting a change in the color-coding of a wire length terminating at the Vertical Position indicator neons and +225 v.

R627 was added between the common connections at NE628 and NE629 neons and +225 v. This resistor was introduced as a means of altering the voltage distribution so as to allow the change in the color-coding of the cable wire.

Parts Removed:**Parts Added:**

R627 1k 1/2w 10% 302-102

**DELAYING SWEEP HOLD-OFF
CAPACITOR REMOVED TO
IMPROVE TRIGGERING****INFORMATION ONLY****M1123**

Effective Prod s/n 1546

DESCRIPTION:

Removing C148D from the Delaying Sweep Timing switch allowed triggering sweep rates to improve from 30kc to 50kc. A later mod adds C148D back on the switch at the same location, but with a different value. See M1386.

Parts Removed:**Parts Added:**

C148D 47 pF 500 V 281-518

**6.3 V OUTPUT FUSE ADDED TO
PROTECT POWER SUPPLY CABLE**

INFORMATION ONLY

M1132

Effective Prod s/n 1621

DESCRIPTION:

A length of #24 wire, wound in a coil, replaces the solid wire between the ungrounded terminal of the Power pilot light and the 6.3 V Output terminal on the front panel. The wire fuse (F730) serves as a fuse in the event the 6.3 V binding post is shorted to ground.

M1210 supersedes M1132 by changing the wire size to #33 magnet wire. Both M1132 and M1210 were superseded by M1741.

Parts Removed:

Parts Added:

F730 a length of #24 tinned wire, having 4 to 6 turns and approximately 1/8 in. in dia and 1-3/8 in. in length

**'B+ DELAY RELAY' REPLACED
WITH MORE RELIABLE TYPE**

See SQB

M1107

Effective Prod s/n 1704

Usable in field instruments s/n 101-1703

DESCRIPTION:

The 'Leach' type relay used at K701 was replaced by a more reliable 'Clare' type relay. Extensive changes were made to component layout and bracket changes were made also. Minor changes were made to the Power Supply cable.

Parts Removed:

K701 4PDT, Leach 148-003
Bracket, relay and fan mtg 406-111

Parts Added:

K701 4PDT, Clare 148-004
Bracket, relay and fan mtg 406-164

Parts Required for Field Installation:

See 'Parts Added' and Modification Kit below.

Field Modification Kit 040-085

INSTALLATION INSTRUCTIONS:

Refer to kit instructions.

**MAIN SWEEP VERNIER CONTROL
ADDED TO IMPROVE ADJUSTMENT
OF MAIN AND DELAY SWEEP**

INFORMATION ONLY

M1153

Effective Prod s/n 1743

DESCRIPTION:

A miniature 500 Ω potentiometer replaced the selected value resistor at R99M. This was to facilitate adjustment of the Main Sweep to the same time as the Delaying Sweep, and also eliminated selecting a value for each instrument. The pot was mounted on the switch support plate, that is mounted between the TIME/CM and MULTIPLIER switches.

Parts Removed:

R99M 1/2W selected Test installed

Parts Added:

R99M	500 Ω miniature	311-056
Screw, 4-40 x 1/4 BHB	(4)	211-008
Lockwasher, int #4	(4)	210-004
Nut, hex, 4-40 x 3/16	(4)	210-406
Nut, hex, 1-72 x 5/32	(2)	210-438

**POWER SUPPLY CHASSIS
STANDARDIZED TO REDUCE
ASSEMBLY TIME AND COST**

INFORMATION ONLY

M1189

Effective Prod s/n 1777 (approx)

DESCRIPTION:

Power supply chassis silkscreening and assembly procedure was changed to allow a common chassis for the 535, 531, 541 and 545. A common silkscreening was used in the operation. Changes in 535 and 545 chassis resistor numbers were effected to make the change possible. R796 and R786 became R795 and R785 respectively; R761 and R725 became R762 and R724 respectively.

**SWEEP CHASSIS CHANGED
TO STANDARDIZE**

INFORMATION ONLY

M1193

Effective Prod s/n 1777 (approx)

DESCRIPTION:

The Sweep chassis was standardized with the 541 chassis through a common silkscreen. The two only differ in that the 541 chassis has R1053 mounted where a bakelite post is on the 531 front section of the chassis.

**POWER SUPPLY PARASITIC
OSCILLATIONS REDUCED WITH
ADDED SUPPRESSOR RESISTOR**

See SQB

M1201

Effective Prod s/n 2035

Usable in field instruments s/n 101-2034

DESCRIPTION:

Stability of the +225 v and -150 v supplies was improved by adding suppressor resistors to the grid circuits of V785B and V712B to reduce parasitic oscillation in these stages.

Parts Removed:

Parts Added:

R767, R713 1k 1/2w 10% 302-102

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- a) Replace the wire between pin-7 of V765B and the junction of C770 and R770 with R767, 1k 1/2W 10%.
- b) Replace the wire between pin-7 of V712B and the junction of C717 and R717 with R713, 1k 1/2W 10%.

**6.3 V OUTPUT FUSE F730
WIRE SIZE REDUCED TO
IMPROVE PROTECTION**

INFORMATION ONLY

M1210

Effective Prod s/n 2077

DESCRIPTION:

The wire used for F730 was changed from #24 tinned copper to #33 heavy EZ-SOL Magnet wire to improve the power supply cable protection. This mod supersedes M1132 and is superseded by M1741.

Parts Removed:

F730 Wire, #24 tinned copper,
coiled 1/8 in. diam,
4-6 turns 176-055

Parts Added:

F730 Wire, #33 heavy EZ-SOL
Magnet, coiled 1/8 in. dia 176-016

**VERTICAL OUTPUT AMPLIFIER
DC SHIFT DIVIDER RESISTORS
CHANGED TO INCREASE RANGE**

INFORMATION ONLY

M1227

Effective Prod s/n 2298

DESCRIPTION:

Range of the Output Amp DC shift control was increased by lowering the value of Divider resistors R595 and R597. The increased range allowed use of larger tolerance resistors.

Parts Removed:

R595, R597 39k 1/2w 5% 301-393

Parts Added:

R595, R597 27k 1/2w 10% 302-273

**SINGLE SWEEP RESET
CIRCUITRY IMPROVED BY
INCREASING SIZE OF C235**

See SQB

M1243

Effective Prod s/n 2420

Usable in field instruments s/n 101-2419

DESCRIPTION:

Single Sweep Reset operation was improved by increasing the pulse amplitude to the Main Sweep Delayed Trigger Amp. This was done by almost doubling the size of C234 in the Delay Pick-off Reset circuitry.

Parts Removed:

C235 12 pF 500 V 281-506

Parts Added:

C235 22 pF 500 V 281-510

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Replace C235 (12 pF 500V capacitor) with a 22 pF 500V capacitor. C235 is located on the 'B' Sweep chassis just to the left of R114, the EXT SWP AMP DC BAL control.

**AIR DEFLECTION PLATE CHANGED
TO IMPROVE AIR CIRCULATION**

INFORMATION ONLY

M1308

Effective Prod s/n 2705 w/exceptions 2691, 2702

DESCRIPTION:

The air deflection plate was replaced by one that was 1/2 in. longer. This improved the air circulation for the smaller design (shorter Vertical height) power transformers. It is recommended that the plate be added with the replacement transformer (120-037) below s/n 2705.

Parts Removed:

Plate, air deflection 386-360

Parts Added:

Plate, air deflection 386-496

**DELAY LINE DRIVER SCREEN
BYPASS CAPACITOR ADDED
TO INCREASE RANGE**

See SQB

M1272

Effective Prod s/n 2770

Usable in field instruments s/n 101-2769

DESCRIPTION:

A screen bypass capacitor C510 was added to the screens of V508 and V509 to equalize the overall response of the instrument, irrespective of the plug-in used. In addition, it permits plug-in interchange without extensive retuning of the main unit.

Parts Removed:

Parts Added:

C510 0.01 μ f 500v 283-002

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Install C510, a 0.01 μ f 500v capacitor located on the Driver chassis, between pin 8 of V508 and ground lug on its socket.

**DELAY LINE ABERRATIONS
REDUCED BY LOWERING VALUE
OF TERMINATING CAPACITORS**

INFORMATION ONLY

M1284

Effective Prod s/n 3199

DESCRIPTION:

To reduce the aberrations present in the delay line network, C938 and C940 were lowered from 1.5pf to 1.0pf capacitors. The capacitors, to correct the phase angle of the terminating impedance, were frequently out of tolerance on the high side.

Since the change from Campbell to Welwyn resistors, for use in the R938 and R940 circuit positions, there has been an increase in the inherent distributed capacity of the resistors. This, in part, contributed to the problem.

Parts Removed:

Parts Added:

C938, C940 1.5pf 500v 281-526

C938, C940 1pf 500v \pm 0.2pf 281-538

**'VERT SIG OUT' COUPLING CAPACITOR
REPLACED TO REDUCE SHOCK HAZARD**

See SQB

M1286

Effective Prod s/n 3210

Usable in field instruments s/n 101-3209

DESCRIPTION:

Coupling capacitor C540 is changed from a 400v to a 600v PTM to prevent premature failure. A possible short would place approximately +350v DC at the front panel 'Vert Sig Out' post.

Parts Removed:

C540 0.022 μ f 400v 285-515

Parts Added:


C540 0.022 μ f 600v 285-517

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Replace C540, a 0.022 μ f 400v capacitor on the Driver chassis, with a 0.022 μ f 600v capacitors.



**SWEEP GENERATOR REDUNDANT
RESISTOR REMOVED WITHOUT
LOSS OF PERFORMANCE**

INFORMATION ONLY

M1313

Effective Prod s/n 3510

DESCRIPTION:

To eliminate a redundant part, R97, a 100 Ω parasitic suppressor was removed from the grid of V90. An insulated wire replaced the resistor with no noticeable effect in operation.

Parts Removed:

R97 100 Ω 1/2W 10% 302-101

Parts Added:

**SWEEP DRIVER DIVIDER
RESISTORS RELOCATED TO
ELIMINATE POSSIBLE SHORTS**

INFORMATION ONLY

M1317

Effective Prod s/n 3547

DESCRIPTION:

Divider resistors R259 and R260 are relocated to eliminate the possibility of shorting together due to their close proximity on the ceramic strip.

**SWEEP GENERATOR FILAMENT
GROUND RELOCATED TO
IMPROVE 30MHz TRIGGERING**

See SQB

M1321

Effective Prod s/n 3547

Usable in field instruments s/n 101-3546

DESCRIPTION:

Relocating the ground of the Miller tube V90 to the tube socket of V73 eliminated jitter occurring in some instruments when a 30MHz sine wave is applied.

INSTALLATION INSTRUCTIONS:

Remove bare wire between pin 4 and ground lug of V90 on the Sweep chassis.

Install a bare wire between pins 4 and 7 of V90, and ground lug of V73 nearest pin 4.

**POWER SUPPLY PRECISION
RESISTOR WATTAGE RATING
INCREASED TO IMPROVE STABILITY**

See SQB

M1297

Effective Prod s/n 3698

Usable in field instruments s/n 101-3697

DESCRIPTION:

Applying a DC voltage to a 1% tolerance precision resistor produces a 'stress effect' that is caused by migration of the carbon particle film. Amplitude of voltage, temperature, and time duration of applied voltage influence the 'stress effect'. The carbon film is deteriorated, causing resistor instability -- either as an increase in resistor value or, in some cases, an open resistor.

Increasing the wattage ratings of the resistors from 1/2w to 1w reduces the high failure rate due to deterioration, and improves their stability.

The replacement of R715 and R718 took place at s/n 3325.

Parts Removed:

R715	50k 1/2w 1%	309-090
R718	68k 1/2w 1%	309-042
R750, R772	333k 1/2w 1%	309-053
R751	490k 1/2w 1%	309-002
R771, R797	220k 1/2w 1%	309-052
R787	1.84 M 1/2w 1%	309-021
R788	780k 1/2w 1%	309-011
R798	720k 1/2w 1%	309-009

Parts Added:

R715	50k 1w 1%	310-086
R718	68k 1w 1%	310-054
R750, R772	333k 1w 1%	310-056
R751	490k 1w 1%	310-057
R771, R797	220k 1w 1%	310-055
R787	236k 1w 1%	308-083
R788	100k 1/2w 1%	308-084
R798	720k 1w 1%	310-059

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- Replace R715, a 50k 1/2w precision resistor located on the ceramic strips above V757 on the Power chassis, with a 50k 1w precision resistor.
- Replace R718, a 68k 1/2w precision resistor located on the ceramic strips above V757, with a 68k 1w 1% precision resistor.
- Replace R750 and R772, 333k 1/2w precision resistors on the ceramic strips above V765, with 33k 1w precision resistors.
- Replace R751, a 490k 1/2w precision resistor, on the ceramic strips above V742, with a 490k 1w precision resistor.
- Replace R771 and R797, 220k 1/2w precision resistors located on the ceramic strips above V742 and V794, with 220k 1w precision resistors.
- Replace R787, a 1.84 Meg 1/2w precision resistor located on the ceramic strips above V784, with a 236k 1w wirewound resistor.
- Replace R788, a 780k 1/2w precision resistor located on the ceramic strips above V784 and adjacent to R787, with a 100k 1/2w wirewound resistor.
- Replace R798, a 720k 1/2w precision resistor located on the ceramic strips above V794, with a 720k 1w precision resistor.

**SWEEP MULTIPLIER VARIABLE CONTROL
AND DIVIDER CHANGED TO ENABLE USE
OF STANDARDIZED MULTIPLIER SWITCH**

INFORMATION ONLY

M1354

Effective Prod s/n 3936

DESCRIPTION:

A modification required in the 535 and 545 delaying sweep circuitry is also incorporated in the 531 and 541 because the change effects Multiplier switch SW90, which is common to all four instruments.

R99k and R99L were reduced by approximately 1/3 of their former value.

Parts Removed:

R99K	10k 1/2w 10%	302-103
R99L	20k 2w	311-018

Parts Added:

R99K	6.8k 1w 10%	304-682
R99L	15k 2w	311-045

**'CAL TEST PT' JACK ADDED
TO POWER CHASSIS TO EASE
CALIBRATOR VOLTAGE CHECK**

INFORMATION ONLY

M1359

Effective Prod s/n 3957

DESCRIPTION:

To bring the calibrator voltage to a more accessible point for checking, a black pin jack labeled "Cal Test Pt" was added in the right outside edge of the Power chassis, 2-1/2 in. in from the rear of the subpanel. The jack is connected to the cathode (pin 3) of V246A, the Calibrator Cathode Follower.

Parts Removed:

Parts Added:

Jack, tip, black	136-037
Washer, brass	210-840
Nut, hex, brass	210-413
Wire, no. 22 sol, w-y (4-1/2")	175-522

CABINET REDESIGNED TO USE NEW 3-SECTION TYPE TO IMPROVE ACCESS

INFORMATION ONLY

M1326

Effective Prod s/n 5001

DESCRIPTION:

The cabinet style was changed to the new 3-section, round corner cabinet used on the 530 and 540 series instruments to improve appearance and access to fuses and CRT controls.

Parts Removed:

Cabinet	437-018
Panel, front	333-137
Plate, rectifier mtg	386-311
Bracket, relay and fan mtg	406-164
Chassis, F and I	441-065
Clamp, CRT socket	343-027
Housing, air filter	380-006
Plate, subpanel	386-348
Bracket, CRT shield support	406-112
Plate, frame, bottom	387-527
Plate, frame, top	387-528
Frame, left	426-023
Frame, right	426-024
Ring, fan	354-034
Bracket, Time/CM switch	406-160
Shield, F and I - HV	337-104
Plate, switch support	386-408
Bracket, fan ring	406-119
Tube, transformer support	166-061
Tube, insulating (2)	166-057
Tube, spacer (2)	166-030
Rod, spacing, fan mt (2)	385-081
Rod, CRT support post	385-080
Rod, nylon, 5/16 x 1-1/8	385-075
Connector, coax, modified	131-038
Filer, air, 10x10x1	378-005

Parts Added:

Plate, cabinet, left side	386-564
Plate, cabinet, right side	386-565
Plate, cabinet, bottom	386-563
Panel, front	333-237
Plate, rectifier mtg	386-546
Bracket, relay mtg	406-144
Mount, fan motor	426-047
Chassis, F and I	441-142
Clamp, CRT	343-008
Housing, air filter	380-008
Plate, subpanel front	386-556
Plate, subpanel rear	386-557
Plate, rear overlay	386-558
Angle, frame bottom (2)	122-021
Angle, frame top	122-019
Bar, ext ch top supt, w/handles	381-067
Ring, fan w/mtg ears	354-053
Bracket, Time/CM switch	406-240
Shield, F and I	337-148
Shield, HV	337-150
Plate, switch support	386-525
Tube, spacing, trans support	166-105
Tube, spacing, 3/8 OD x 1/4	166-110
Tube, spacing, SPA 8-20	166-037
Tube, spacing, SPA 8-14	166-034
Rod, CRT support post	385-088
Rod, HVO support post	384-135
Rod, nylon, 5/16 x 1-1/8	385-087
Connector, coax, modified	131-064
Tube, spacing, 1/4 OD x 7/32 (2)	166-107
Filter, air, modified, 10x10x1	378-011
Plate, access panel, plexi	386-560
Clamp, access panel	343-033
Lockwasher, int no.8 (2)	210-008
Lug, solder, no.10 non-lkg(2)	210-224
Nut, hex, 8-32 x 5/16 (2)	210-409
Nut, cap, hex, 8-32x5/16 (2)	210-402
Screw, 8-32 x 1-1/4 RHS (2)	212-031
Bracket, CRT support	406-238

**CALIBRATOR 'CAL OUT' CONNECTOR
ELEVATED $1/4\Omega$ ABOVE GROUND
TO REDUCE 60Hz MODULATION**

INFORMATION ONLY

MT412

Effective Prod s/n 5001

60 Hz hum was eliminated in high gain plug-in (i.e., B and D), by elevating the Calibrator $1/4\Omega$ above ground. The hum was attributable to ground current effects between the plug-in and Calibrator while the Calibrator was operated in the multivolt range. This was reduced to a point where a clean 'Cal' output was obtained in the 0.2 millivolt range.

The mechanical changes necessary to the cabinet were included in the cabinet change, M1324, and involved the following:

The D 'Cal Out' coax clearance hole in the subpanel was enlarged to $11/16$ in. dia.

The D 'Cal Out' coax connect access hole in the front panel was enlarged to $3/4$ in. dia.

The coax connector mounting holes were enlarged to $7/16$ in. dia to accept the 4 fiber washers, and/or nylon molded insulator, and two fiber washers to insulate the connector.


Circuit changes involved adding R698, a $1/4\Omega$ $1/2$ w resistor, between the connector and ground, and relocating the RC combination of R695 and C695 to the connector ground lug.


Parts Removed:


Parts Added:

R698	$1/4\Omega$ $1/2$ w WW	308-090
Connector, modified		131-064
Lockwasher, int no.4		210-004
Lug, solder, no.10		210-224
Nut, hex, $4 \times 3/16$		210-406
Washer, plain, 5S		210-801
Washer, fiber, extruded no.4		210-849
Screw, $4-40 \times 3/8$ FHS		211-025
Insulator, nylon		406-244

See schematics and drawings on following pages.








Hardware List

1)	Connector, modified 83-IRTY	131-064
2)	Washer, fiber, extruded no.4	210-849
3)	Lug, solder, no.10	210-224
4)	Washer, plain, 5S	210-801
5)	Lockwasher, int, no.4	210-004
6)	Nut, hex, 4 x 3/16	210-406
7)	Screw, 4-40 x 3/8 FHS	211-025



CALIBRATOR OUTPUT CONNECTOR

Viewed from bottom

Production Method

Hardware List

1)	Screw, 4-40 x 3/8 FHS	211-025
2)	Insulator, nylon	406-244
3)	Connector, modified 83-IRTY	131-064
4)	Lug, solder, no.10	210-224
5)	Washer, fiber, no.10	210-812
6)	Lockwasher, int, no.4	210-004
7)	Nut, hex, 4 x 3/16	210-406

**DELAYED TRIGGER RINGING
ELIMINATED BY ADDING
+100 V DECOUPLING NETWORK**

See SQB

M1381

Effective Prod s/n 5084

Usable in field instruments s/n 101-5083

DESCRIPTION:

Decoupling was added to the +100 V supply, at the plate of V228B (Delayed Trigger Cathode Follower), to eliminate ringing in the Vertical Amplifier.

Parts Removed:

Parts Added:


R232	47 Ω 1/2W 10%	302-470
C232	0.005 μ F discap	283-001

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- Relocate one end of R201, above V228 on the Delay chassis, from CSD-24 to CSD-23. Remove bare wire strap between CSD-23 and CSD-24.
- Relocate the two white-brown-black-brown wires from pin 1 of V228 to CSD-24.
- Install C232, a 0.005 μ F discap, between pin 1 of V228 and its socket ground lug.
- Install R232, a 47 Ω 1/2W resistor, between pin 1 of V228 and CSD-24.



**DELAY PICKOFF JITTER ELIMINATED
BY ADDING CAPACITOR TO
DELAY TIME SWITCH**

See SQB

M1386

Effective Prod s/n 5105

Usable in field instruments s/n 101-5104

DESCRIPTION:

C148D, a 22pF 500V capacitor, was added to the DELAYING SWEEP TIMING switch to eliminate jitter to the Delay Pickoff. This had the effect of increasing the holdoff time to the 2, 5 and 10 μ s position of SW190A. In instruments prior to s/n 1546, a 47pF 500V capacitor was designated C148D and occupied this same circuit position. See M1123.

Parts Removed:

Parts Added:

C148D 22pF 500V 281-510

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- a) Install C148D, 22pF 500V capacitor, between the rear potentiometer mounting plate and W3-2R on the DELAY TIME/CM switch.
- b) Below s/n 1546 only --
Replace C148D, 47pf capacitor, on the DELAY TIME/CM switch with a 22pF 500V capacitor.

NOTE: The following method is used to identify the DELAY TIME/CM switch terminals:


The wafers are numbered from the front to rear.

The contact mounting holes are numbered 1 through 12 relative to the index key as shown in the drawing.

The contacts have an 'F' or 'R' suffix which denotes that they are on the front or rear of the wafer.

Example: W2-7R (denoted by * on drawing) is contact #7 on the rear of wafer 2.

(TYPICAL SWITCH CONFIGURATION)



SWEEP GENERATOR +225 V DECOUPLING
ADDED TO +GATE OUT CF TO
REDUCE 'SWEEP WRINKLE'

See SQB

M1378

Effective Prod s/n 5118

Usable in field instruments s/n 101-5117

DESCRIPTION:

Adding resistor R72 and capacitor C72 to the plate circuit of V73B reduced the 'Sweep wrinkle' which entered the Vertical Amplifier through the +225 v regulated supply.

The additional decoupling afforded by this mod is especially useful when using a 53/548 plug-in in the 0.05 volts/cm position.

Parts Removed:

Parts Added:

R72	47 Ω 1/2w 10%	302-470
C72	0.005 μ f discap	283-001

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- Move the ground end of R77, a 4.7k 1w resistor, to the nearest ground lug on V73.
- Unsolder the +225 v lead from pin 6 of V73B and connect at the slot vacated in step a.

NOTE: On some instruments it may be necessary to install a ceramic post as there isn't a vacant slot.

- Install R72, a 47 Ω resistor, between pin 6 of V73B and the slot mentioned in step b.
- Install C72, a 0.005 μ f capacitor between pin 6 of V73B and ground.

PLUG-IN SIDE PANELS REPLACED
BY ONE INTERCHANGEABLE PANEL
FOR IMPROVED ACCESS

INFORMATION ONLY

M1394

Effective Prod s/n 5393

DESCRIPTION:

Plug-in housing side panels were replaced with ones having larger access holes to allow internal adjustments with a plug-in in the instrument. Mechanical changes were made to allow using the panel for either the left or right side.

Parts Removed:

Plate, plug-in housing, right	386-357
Plate, plug-in housing, left	386-356
Shield, plug-in housing, Vert	337-067

Parts Added:

Plate, plug-in housing, side (2)	386-566
Shield, plug-in housing, Vert	337-091

**DELAYED TRIGGERING AMPLIFIER
SUPPLY DECOUPLING CHANGED TO
ELIMINATE FAST PULSE RINGING**

See SQB

M1419

Usable in field instruments s/n 101-5402


Effective Prod s/n 5403 -- s/n 3995 for 535 Rackmounts **

**Note: A new style cabinet appears on all standard instruments above s/n 5000 -- see M1326. The serial numbers between the last old style standard instrument and the first new style instruments were reserved for the 535 Rackmounts. These have an old style cabinet with an enlarged front panel for rackmounting, and should not be confused with RM35 instruments.

DESCRIPTION:

Capacitor C40 was relocated to the +100 V screen supply of the Delayed Trigger Amplifier to improve its high frequency decoupling. A wrinkle in the trace was attributed to ringing in the -150 V and the +100 V supplies, when a fast pulse was placed on the grid of V37A, the Delayed Trigger Amplifier.

Adjustment of the Delayed Time Multiplier control would position the wrinkle on the horizontal axis at the point of delay pickoff. The Main Sweep Generator schematic will show C40 connected between pin 7 (cathode) and pin 3 (screen) of V37A. Pins 1 and 3 of V37A are jumpered to +100 V.



**(PARTIAL)
MAIN SWEEP GENERATOR**

INSTALLATION INSTRUCTIONS:

- Left R40 (220k) and C40 (0.005 μF) from the second notch in the ceramic strip, directly behind the TRIGGER MODE/TRIGGER SLOPE switch.
- Dress the lead of C40 down to pin 3 of V37A and solder.
- Resolder R40 (220k 1/2 W) to the second ceramic strip notch, from which it was removed in step a.

**-150V SUPPLY RINGING AND RIPPLE
REDUCED BY ADDED DECOUPLING**

See SQB

M1422

Effective Prod s/n 5403

Usable in field instruments s/n 101-5402

s/n 3995 on 535 Rackmounts (see M1419 Note)

DESCRIPTION:

To reduce ringing and ripple in the -150V supply, a decoupling network was added between the -150V buss and ground. Although physically located on the Sweep chassis, the C720-R720 combination will be shown in shunt with C715 on the LV Power Supply schematic.

Parts Removed:

Parts Added:


C720	0.01 μ f 500v	283-002
R720	10 Ω 1/2w 10%	302-100

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- Relocate one end of R76, a 47 Ω 1/2w resistor, and the +225v lead from CSD-12 to CSD-13.
- Unsolder and discard the wire strap between CSD-12 and CSD-13.
- Install R720, a 10 Ω 1/2w resistor, between CSD-12 and the ground lug directly below it on the tube socket of V58.
- Install C720, a 0.01 μ f discap capacitor, between CSD-11 (-150v) and CSD-12.



**DELAYED SWEEP HUM REDUCED
WITH ADDED TUBE SHIELD**

INFORMATION ONLY

M1384

Effective Prod s/n 5430 -- 535-S2 only w/exceptions 5087-8, 5119, 5121-2, 5124-6, 5129, 5271
s/n 3996 for 535 Rackmounts (see M1419 Note)

DESCRIPTION:

The following changes reduced the incidence of hum interference in the 'Main Sweep Delayed' Mode at 1000:1 or greater ratios in sweep speed settings:

- 1) A socket type shield (337-004) was added to the V180 tube socket, and a tube shield (337-006) was placed over the 12AL5 used in that position. Two #4 ext lockwashers (210-003) were placed by two #4 int lockwashers (210-004) in the mounting of the socket shield.
- 2) The filament wire connecting pin 4 of V180 with pin 3 of V190 was dressed away from the shielded cable wire that is tied to the grid, pin 1, of the Miller Delaying Sweep Generator, V190.
- 3) In S2 instruments, the wires from the delaying sweep Mylar timing capacitors, C190A, B, C, E (291-011) were dressed close the DELAYING SWEEP TIMING switch, SW190.

Parts Removed:

Lockwasher, ext #4

210-003

Parts Added:

Lockwasher, int #4
Shield, socket
Shield, tube

210-004
337-004
337-006

**THERMAL CUTOUT 'OFF' TIME REDUCED
BY HIGHER DEGREE 'ON' SWITCH**

INFORMATION ONLY

M1331

Effective Prod s/n 5450

DESCRIPTION:

A new 'Therm-O-Disc' having a smaller differential between the 'OFF' and 'ON' temperature will replace the present one. This will shorten the 'OFF' time after the switch is actuated.

Parts Removed:

TK701

Thermal Cutout
128°±5°F - 'Off'
98°±5°F - 'On'

260-070

Parts Added:

TK701

Thermal Cutout
128°±5°F - 'Off'
113°±5°F - 'On'

260-070

+500V DECOUPLING CAPACITOR ADDED TO REDUCE RINGING

See SQB

M1457

Effective Prod s/n 5513

w/exceptions 5226

5434

5466-7

Usable in field instruments s/n 101-5512

5488

5496

5504-11

5263

5446

5478-9

5490-1

5498

5397-8

5454-5

5481-3

5494

5501-2

Effective Prod s/n 3596 on 535 Rackmounts
(see M1419 Note)

Usable in field instruments s/n 3596-5000

DESCRIPTION:

A decoupling discap capacitor C538 was added to reduce ringing resulting occasionally with a 53/54B plug-in. Fast risetime pulses would feedback into the filament circuit of the plug-in Input CF through the +500v wiring, causing input wrinkle approaching 4-5% at times. C538 was added between the plate (pin 6) of V535 and its ground lug.

Parts Removed:

Parts Added:

C538

0.005 μ f 500v


283-001

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Install C538, a 0.005 μ f discap capacitor, between pin 6 and the tube socket ground lug of V535 on the Driver Chassis. Some earlier instruments did not have a ground lug type socket for V535, and C538 was installed between pin 1 of V535 and the ground lug of V527.



**TRIGGER OR EXT SWEEP INPUT SUPPRESSOR
RESISTOR ADDED TO ELIMINATE
OSCILLATION IN EXT SWEEP AMP**

See SQB

M1460

Effective Prod s/n 5564 w/exceptions 5483, 5490 Usable in field instruments s/n 101-5563
s/n 3996 for 535 Rackmount (see M1419 Note)

DESCRIPTION:

To eliminate parasitic oscillation in the Ext Sweep Amplifier, a resistor was added between the TRIGGER or EXT SWEEP IN coax connector and the X1, X10 ATTEN toggle switch.

Parts Removed:

Parts Added:

R109 47 Ω 1/2 W 10% 302-470

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Replace the wire located between the TRIGGER or EXT SWEEP IN coax and the X1, X10 ATTEN switch with R108, a 47 Ω 1/2 W resistor.

**SCALE ILLUM CIRCUITRY
REWIRED TO PERMIT COMPLETE
EXTINCTION FOR PHOTOGRAPHS**

See SQB

M1444

Effective Prod s/n 5600

Usable in field instruments s/n 101-5599

DESCRIPTION:

Provides complete graticule lamp extinction by grounding the open end of the scale illumination potentiometer R600, thereby permitting complete control of the lamps. This was accomplished by adding a grounding pot solder lug and lockwasher under the scale illum pot, R600.

Parts Removed:

Parts Added:

Lockwasher, pot, int 210-012
Lug, solder, plain 210-207


Parts Required for Field Installation:

See 'Parts Added'.

continued

INSTALLATION INSTRUCTIONS:

- Remove R736 (Scale Illum pot) and install lockwasher and solder lug between pot and subpanel.
- Solder unused terminal of R736 to the solder lug just installed.
- Interchange the two existing wires connected to the pot (the white-red-blue wire should now be connected to the outside terminal -- this places the pot between 6.3 v and ground.)



AUXILIARY TRANSFORMER SECONDARY VOLTAGE LOWERED FOR SAFER OPERATION OF TIME DELAY RELAY

INFORMATION ONLY

M1467

Effective date 1-7-57 -- 535-S4 only

DESCRIPTION:

The auxiliary transformer voltage is too high for safe operation of the time delay relay. Reduces the secondary voltage from 27 v AC to 25 v AC and adds a series resistor.

Parts Removed:

T701 DC 1 120-075

Parts Added:

T701 DC 1 120-084
R708 100 Ω 1w 10% 304-101

**AUXILIARY TRANSFORMER SECONDARY
VOLTAGE LOWERED FOR SAFER
OPERATION OF TIME DELAY RELAY**

INFORMATION ONLY

M1475

Effective date 1-7-57 -- 535-S3 only

DESCRIPTION:

The auxiliary transformer voltage is too high for safe operation of the time delay relay. Reduces the secondary voltage from 27v AC to 25v AC and adds a series resistor.

Parts Removed:

T700 DC 2 120-072

Parts Added:

T700 DC 2 120-085
R708 100Ω 1w 10% 304-101

**DELAY LINE SHIELD ADDED TO ELIMINATE
PICKUP OF UNBLANKING PULSE**

INFORMATION ONLY

M1418

Effective Prod s/n 5830

DESCRIPTION:

To eliminate a ringing at high sweep speeds resulting from the Unblanking pulse feeding into the Delay Line, an 'L-shaped' shield was added between the HV chassis and Delay Line. The shield extends below the CRT control grid lead to achieve some measure of shielding for the Delay Line. Two 1/8 in. mounting holes were added in the outside lip of the HV chassis.

Earlier instruments will require some revision of the mounting hole location.

Parts Removed:

Parts Added:

Shield, Delay Line	337-156
Screw, 4-40 x 1/48HS	211-008
Lockwasher, int no.4	210-004
Nut, hex, 4-40 x 3/16	210-406

**RECTIFIER PLATE AND CRT BRACKET
IMPROVED BY REDESIGN**

INFORMATION ONLY

M1451

Effective Prod s/n 5985

DESCRIPTION:

To improve the rigidity of the instrument and to simplify the final assembly squaring and aligning operation, a rectifier mounting plate of new design was used. The new plate has no rear flange, and the top and bottom were extended to the rear making the overall width 11-5/8 in. Additional fastening points were provided at the top rear through a newly added hole in the Sweep chassis and at the bottom rear through the existing Clare relay bracket mounting holes in the Power chassis. In addition, two new holes were provided in the Rectifier mounting plate for fastening a new CRT support bracket which was installed as a part of this modification. The former CRT support bracket was fastened to the rear flange of the old rectifier mounting plate.

Parts Removed:

Plate, rectifier mounting	386-546
Bracket, CRT support	406-238

Parts Added:

Plate, rectifier mounting	386-574
Bracket, CRT support	406-251

**DELAYING SWEEP TRIGGER SHAPER
SIGNAL INCREASED 20% TO INSURE
PROPER TRIGGERING OPERATION**

See SQB

M1454

Effective Prod s/n 6031

Usable in field instruments s/n 101-6030

s/n 4010 for 535 Rackmounts (see M1419 Note)

DESCRIPTION:

The Trigger Shaper Pulse Output was increased 20% to insure a level consistent with established spec (5 volts). This allowed proper triggering of the multivibrator.

Prior to this change, if the trigger signal was marginal, the potential existed for tube aging in service to further deteriorate the amplitude to the point where erratic multi operation would be experienced.

Parts Removed:

R224	4.7k 1/2W 10%	302-472
------	---------------	---------

Parts Added:

R224	5.6k 1/2W 10%	302-562
------	---------------	---------

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Replace R224, a 4.7k 1/2W resistor, with a 5.6k 1/2W resistor. R224 is located on the ceramic strips above V216 on the Delay Sweep chassis, connected between pin 1 of V216 and +350 V.

TRIGGERING 'AC AUTO' MODE CHANGED TO 'AUTOMATIC'

INFORMATION ONLY

M1405

Effective Prod s/n 6045 (see list in Description)

DESCRIPTION:

An 'Automatic' mode of triggering replaces the present 'AC Auto' mode. In the New Mode of operation, the front panel 'Stability' control is replaced by an internal control which is preset for optimum triggering. The new 'Preset Stability' R49, a 100k 2w potentiometer, was mounted at the front outside corner on the Sweep chassis.

Included with the new circuitry requirements was a switch circuit SW5G, added to the front side of section 5 of the Triggering Mode switch. The switch will remain a direct replacement.

The front panel was changed to the extent that the 'AC Auto' position of the Triggering Mode control was redesignated 'Automatic'.

The following changes were effected in the Sweep Cable:

- 1) The white-violet wire which formerly tied to the 'Stability' pot center contact (variable arm) was rerouted to tie to the lower wiper arm of the newly added 'Triggering Mode' switch section.
- 2) A white-orange wire was added from the SW5G 'Automatic' contact to the Preset Stability pot center contact (arm).
- 3) A white-blue wire was added to the upper arm of the newly added 'Triggering Mode' switch section to the center arm of the 'Stability' pot.
- 4) A black-brown-green-brown wire was added from one end of the 'Preset Stability' pot to -150v available at the outboard ceramic strip adjacent to V40. The other end contact of the 'Preset Stability' pot is grounded by means of a pot ground lug.

	<u>Standard</u>	<u>Rackmount</u>
New switch section added but not wired	s/n 5470	s/n 3996
Pot mounting hole added to sweep chassis	s/n 5553	s/n 3996
Pot added, switch wired, new panel	s/n 6045	Standard Rackmount instruments with 'Automatic' never produced

The following new cabinet design, special instrument front panels are available with the automatic feature:

535-S1	333-298	535-S4	333-251	<u>Old Style</u>	
535-S2	333-299	535-S6	333-253	535-S4 Rackmount	333-314
535-S3	333-250	535-IBM	333-320		

The following panels will be available for Customer Service usage:

535-S1	333-248	535-S2	333-249
--------	---------	--------	---------

The following instruments were modified out-of-sequence:

5718 --	535-S6	4010 --	535-S4 RM	4020 --	535RM	Special Painted Panel
5876 --	535-S2	4016 --	535-S6 RM	4021 --	535RM	" " "
5878 --	535-S2	4017 --	535-S6 RM	4022 --	535RM	" " "
5881 --	535-S4	4018 --	535-S6 RM	4023 --	535RM	" " "
5882 --	535-S4	4019 --	535-S6 RM	4024 --	535RM	" " "
5831 --	535			4025 --	535RM	" " "
5856 --	535			4031-41 --	535RM	" " "

continued

M1405
(con'd)

This mod is incorporated in Modification Kits 040-149 (s/n 101-1074) and 040-152 (1075-6044).

Parts Removed:

Panel, front, "AC Auto" 333-238

Parts Added:

Panel, front, "Automatic" 333-297
R49 100k 2W 3/8x3/8 311-026

**DELAYING SWEEP SHOCK
HAZARD ELIMINATED WITH
ADDED GROUND WIRE**

See SQB

M1485

Effective Prod s/n 6126

Usable in field instruments s/n 101-6125

s/n 4010 for 535 Rackmounts (see M1419 Note)

DESCRIPTION:

A shock hazard in testing and servicing the delaying sweep chassis exists when the chassis is swung out from the main unit. In this position there is no positive ground return to the scope frame. A #6 ground lug was added to the delaying sweep chassis and a #20 stranded wire added to the power cable between the lug and the ground lug of V791 on the power deck.

Parts Removed:

Parts Added:

Lug, solder, SE6 210-202
Wire, #20 str, white 6in. (175-512)

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

- a) Install a #6 ground lug under the head of the lower screw which mounts the delaying sweep chassis to the swivel support post.
- b) Connect a #20 white stranded wire between the installed ground lug and the ground lug of V791 on the Power chassis. The wire will pass through the plastic cable clamp and the grommet in front of V791.

**KNOBS REPLACED FOR BETTER SPACING
AND IMPROVED APPEARANCE**

INFORMATION ONLY

M1489

Effective Prod s/n 6151
s/n 4010 for 535 Rackmount (see M1419 Note)

DESCRIPTION:

An improved appearance and better spacing is gained with the use of smaller knobs in the limited space below the CRT. The knobs replaced by this change are the Focus, Intensity, Astigmatism and Scale Illumination controls.

Parts Removed:

Knob, 0.780D x 0.591 hi (4) 366-044

Parts Added:

Knob, 0.007D x 0.525 hi (4) 366-033

**VERTICAL AMPLIFIER BYPASS CAPACITOR
ADDED TO ELIMINATE OSCILLATION**

See SQB

M1494

Effective Prod s/n 6321
s/n 4010 for 535 Rackmounts (see M1419 Note)

Usable in field instruments s/n 101-6320

DESCRIPTION:

A bypass capacitor was added to the plate circuit of V558A, preventing parasitic oscillations in the Vertical Amplifier circuits.

Parts Removed:

Parts Added:

C560 0.01 μ f 500v 283-002

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Install C560, a 0.01 μ f discap, between pin 1 of V558A and ground.

**DEFLECTION PLATE CONNECTOR
ACCESS PANEL REMOVED**

INFORMATION ONLY

M1546

Effective Prod s/n 6801

DESCRIPTION:

Because of low usage, the access plate has been removed and will be supplied as an accessory (013-008), on special order only.

Parts Removed:

Parts Added:

Clamp, access panel 343-033
Panel, plexi plate, access 386-560

**DELAY PICKOFF CIRCUITRY
IMPROVED BY REPLACING V195,
A SINGLE 6U8, WITH TWO 6AU6's**

INFORMATION ONLY

M1505

Effective Prod s/n 7010

DESCRIPTION:

This modification was to correct several problems which existed in the delay pickoff circuit of the delaying sweep:

- 1) The high rejection rate of 6U8's because of unbalance.
- 2) Heater hum.
- 3) A general improvement in circuitry with the introduction of the more stable 6AU6's.

Changes in the chassis were made to accommodate the two 7-pin tube sockets replacing the single 9-pin tube socket used previously. No changes in circuitry were necessary. The accompanying schematics show the change in tube socket wiring. See Before and After schematics on following page.

As additional information, pin 4 of each 6AU6 heater is grounded. Also, V195A,B became V195 and V196 respectively.

Parts Removed:

V195A,B	6U8	154-033
Chassis		441-064
Socket, tube, 9-pin		136-015

Parts Added:

V195, V196	6AU6	154-022
Chassis		441-095
Socket, tube, 7-pin	(2)	135-008
Screw, 4-40 x 5/16	(2)	211-033
Nut, hex, 4-40 x 3/16	(2)	210-406
Lockwasher, #4 ext	(2)	210-003

continued



**POWER SUPPLY TRANSFORMER CHANGED
TO EXPORT TYPE FOR ECONOMY**

INFORMATION ONLY

M1551

Effective Prod s/n 7060

DESCRIPTION:

A high percentage of instruments require an export transformer (Mod 161A). To save the cost of handling and rework, the export transformer (with multi-tap primary) replaces the domestic type on standard instruments also.

Parts Removed:

T700 LV, 117/234 V 120-037

Parts Added:

T700 LV, Export 120-086
Tag, Voltage 334-634

**X10 DELAYING SWEEP ATTENUATOR
TRIMMER RANGE CHANGED WITH
INCREASED CAPACITOR VALUE**

INFORMATION ONLY

M1561

Effective Prod s/n 7495

DESCRIPTION:

Proper adjustment of C100, a X10 attenuator network trimmer capacitor, requires the use of a capacitor having a greater range on the high end. To accomplish this end, C100 was changed from a 5-25 pF 500 V ceramic capacitor to a 8-50 pF 500 V ceramic capacitor.

Parts Removed:

C100 5-25 pF 500 V 281-011

Parts Added:

C100 8-50 pF 500 V 281-013

Parts Required for Field Installation:

See 'Parts Added'.

INSTALLATION INSTRUCTIONS:

Replace C100, a 5-25 pF variable capacitor located between C110 and C101 on the bracket directly behind the X1-X10 attenuator toggle switch, with a 8-50 pF 500 V capacitor.

**GRATICULE STUDS CHANGED
TO REMOVABLE TYPE**

INFORMATION ONLY

M1570

Effective Prod s/n not given

DESCRIPTION:

To facilitate replacement of damaged or corroded graticule studs, without removing the instrument front and subpanel, a new graticule stud has been made available through Customer Service. The internally threaded stud can be fastened in place from the back of the subpanel with a 10-32 x 3/8 BHS screw and a #10 internal lockwasher. Removal of the old stud is possible by drilling through with a 9/32 in. drill, then breaking off with pliers.

Parts Removed:

Parts Added:

Stud, graticule, 10-32 int thread 355-043

TRIGGERING 'PRESET' POSITION ADDED TO STABILITY CONTROL

See SQB

M1512

Effective Prod s/n 7553

Usable in field instruments s/n 101-7552

DESCRIPTION:

A 'Preset' position was added to the front panel stability control. This was to make use of the internal Preset stability adjustment, added by M1404 for the automatic mode, for all modes of triggering. In preset position, the front panel stability control is replaced by the internal preset stability control and only the triggering level control needs adjustment for proper triggering.

Parts Removed:

R14, R43 2-100k 311-030

Parts Added:


R14, R43 2-100k w/SPDT sw 311-096

Parts Required for Field Installation:

Field Modification Kits	040-149	(s/n 101-1074)
	040-152	(s/n 1075-6044)
	040-154	(s/n 6045-7552)

INSTALLATION INSTRUCTIONS:

Refer to kit instructions.



DELAYING SWEEP REWIRED TO ELIMINATE NEED FOR CHECKED NEON DIODES

INFORMATION ONLY

M1590

Effective Prod s/n 7611

DESCRIPTION:

To eliminate the need for checked neon diodes in the Delaying Sweep Generator circuit, neon diode B180 was relocated from the junction of R186, the plate of V190 (pin 5) and the cathode of V150B (pin 8), to the junction of R185 and R187, and the cathode of V150B. With the change in circuitry for B180, it is not necessary that B187 be a checked neon.

Parts Removed:

B180	Neon, checked	150-011
B187	Neon, checked	150-009

Parts Added:

B180, B187	Neon, raw	150-002
------------	-----------	---------

SWEEP CHANGED TO ELIMINATE NEED FOR CHECKED NEON DIODES

INFORMATION ONLY

M1594

Effective Prod s/n 7627

DESCRIPTION:


To eliminate the need for checked neon diodes in the Sweep Generator circuit, neon diode B96 was relocated from the junction of R93, C95 and the cathode of V85 to the junction of R95, R90 and the cathode of V85. With the change in circuitry for B96, it is not necessary that B95 be a checked neon. It was established that B287 of the Sweep Amplifier also required only a raw neon.

Parts Removed:


B95, B287	NE-2 55 v ckd	150-009
B287	NE-2 65 v ckd	150-011

Parts Added:

B95, B287, *B96	NE-2, raw	150-002
--------------------	-----------	---------



BEFORE



AFTER

CRT ROTATING RING INSTALLED**INFORMATION ONLY****M1611**

Effective Prod s/n 7688

s/n 4072 for 535 Rackmounts (see M1419 Note)

w/exceptions 4057-66

DESCRIPTION:

To provide an easier method of rotating the CRT, a molded nylon rotating ring (with handle) has been fitted to the CRT socket.

Parts Removed:**Parts Added:**

Ring, rotating

354-062

**DELAYING SWEEP TIMING
SWITCH VARIABLE CAPACITORS
REPLACED TO ELIMINATE DRIFT****INFORMATION ONLY****M1526**

Effective Prod s/n 7861

s/n 4072 for 535 Rackmounts (see M1419 Note)

w/exceptions 4063-6, 4068-71

DESCRIPTION:

Because of a tendency to drift after setting C190D and C190F in the Delaying Sweep Timing switch, an inherent fault of this type fiber mounted trimmer, ceramic trimmers (TS2A NPO Erie) are now being used. The larger dimensions of the all-ceramic trimmer has necessitated a new bracket. The bracket includes an indexing tab to allow clockwise rotation of the Delay Time switch 90° because of space limitations. There was also lead length changes to C190A, C190B and C190C. The replacement for C190D required a value difference from 8-50pF to 7-45pF.

Parts Removed:

C190D	8-50pF fiber	281-013
C190F	3-12pF fiber	281-009
Screw, thrd-cut, 4-40x1/4 (4)		213-035
Bracket, aluminum		406-115

Parts Added:

C190D	7-45 pF cer	281-012
C190F	3-12 pF cer	281-007
Screw, thrd-cut, 4-40x5/16(4)		213-034
Bracket, aluminum		406-273

**CALIBRATOR SWITCH REDESIGNED
FOR EASIER INSTALLATION**

See SQB

M1498

Effective Prod s/n 7894

Usable in field instruments s/n 101-7893

DESCRIPTION:

The Square-wave Calibrator switch was replaced to use a separate shield for ease of installation and to simplify wiring.

Parts Replacement Kit 050-034 is available to facilitate the replacment of Square-wave Calibrator switch 260-013 in pre-effective serial number instruments.

Parts Removed:

SW670	Calibrator Shield	260-013 337-064
-------	----------------------	--------------------

Parts Added:

SW670	Calibrator Shield	260-177 337-093
-------	----------------------	--------------------

**EXT SWEEP AMPLIFIER DC BAL
DIVIDER RESISTOR CHANGED
TO INCREASE CONTROL RANGE**

INFORMATION ONLY

M1607

Effective Prod s/n 7913

s/n 4074 on 535 Rackmounts (see M1419 Note)

DESCRIPTION:

The External Sweep DC Bal divider resistor R113 was changed from 47k to 33k to provide an increased adjustment range.

Parts Removed:

R113	47k 1W 10%	304-473
------	------------	---------

Parts Added:

R113	33k 1W 10%	304-333
------	------------	---------

SWEEP CABLES REPLACED WITH ONE MAIN CABLE

INFORMATION ONLY

M1672

Effective Prod s/n 8147 w/exceptions 8144, 8398
s/n 4082 for 535 Rackmounts (see M1419 Note)

DESCRIPTION:

To replace twenty-two separate insulated wires, and two separate cable harnesses with one main cable harness. This simplified production of the chassis and cured some problems existing in the older cables.

Parts Removed:

Cable, Main Sweep, no. 1	179-071
Cable, Main Sweep, no. 3	179-072

Parts Added:

Cable, Main Sweep	179-188
-------------------	---------

+500V TERMINAL POINT PROVIDED FOR USE WITH NEW RM VERT AMPS

INFORMATION ONLY

M1676

Effective Prod s/n 8147
s/n 4082 for 535 Rackmounts (see M1419 Note)

DESCRIPTION:

The objective of this mod is to make 500 series sweeps, in present production, usable with new vertical amplifiers which will be incorporated in the RM series instruments.

To provide access to a 500V supply which will be the 'striking' voltage for the neon vertical indicators through dividers, a loop breakout was made in the main sweep cable and brought up to CSB-12. R627, a 1k 1/2W 10% resistor, was repositioned to connect from CSA-12 to CSB-12. This change establishes CSB-12 as a 500V terminal point compatible with the needs of the new vertical amplifier circuitry. No additional changes in components or circuitry were made.

