

# FACTORY CALIBRATION PROCEDURE

## CONTENTS:

This is the guide for calibrating new instruments in Product Manufacturing. The procedure consists of 4 sections:

### Equipment Required

Factory Test Limits - Factory Test Limits are limits an instrument must meet before leaving Manufacturing. These limits are often more stringent than advertised performance requirements. This is to insure that the instrument will meet advertised requirements after shipment, allows for individual differences in test equipment used, and (or) allows for changes in environmental conditions.

Short Form Procedure - The Short Form Procedure has the same sequence of steps and the same limits on checks or adjustments as the Main Procedure.

Main Procedure - The Main Procedure gives more detailed instructions for the calibration of the instrument. This procedure may require that some checks and adjustments be made so that performance is better than that required by the Factory Test Limits. This insures the Factory Test Limits will be met when side panels are added, permits some normal variation in test equipment and plug-in scopes, etc.

Abbreviations in this procedure will be found listed in TEKTRONIX STANDARD A-100. Definitions of terms used in this procedure may be found in TEKTRONIX STANDARD A-101.

In this procedure, all front panel control labels and Tektronix instrument names are in capital letters (VOLT/DIV, etc). Internal adjustment labels are capitalized only (Gain Adj, etc).

## CHANGE INFORMATION:

This procedure has been prepared by Product Manufacturing Staff Engineering. For information on changes made to this procedure, to make suggestions for changing this procedure, or to order additional copies: please contact PMSE, 39-307. (HD)

*This procedure is  
company confidential*

SWEPT  
FREQUENCY  
CONVERTER  
(015-0107-00)

June 1968

For all serial  
numbers.



©, 1968 TEKTRONIX, INC., PO Box 500  
BEAVERTON, OREGON. All rights reserved.



PMSE

COMPANY CONFIDENTIAL

Page 1 of 11

EQUIPMENT REQUIRED:

The following equipment is necessary to complete this procedure:

a. *TEKTRONIX Instruments*

- 1 TYPE 540B SERIES OSCILLOSCOPE with
- \* 1 TYPE 1A1 PLUG-IN UNIT and
- 1 TYPE 6028 X1 PASSIVE PROBE and
- 1 TYPE 6006 X10 PASSIVE PROBE (test scope)
- 1 TYPE 1L5 SPECTRUM ANALYZER (test scope)
- \* 1 TYPE 184 TIME MARK GENERATOR
- 1 TYPE 191 SINE WAVE GENERATOR
- 1 TYPE 76TU LINE-VOLTAGE CONTROL UNIT<sup>1</sup>
- 1 TYPE 540 B SERIES OSCILLOSCOPE with
- 1 TYPE 1L5 SPECTRUM ANALYZER (calibration scope)

b. *Test Fixtures and Accessories*

- 1 Filter (067-0575-00)
- 1 600 $\Omega$  Termination (011-0092-00)
- 2 BNC 93% Cable (012-0075-00)
- 1 BNC 50 $\Omega$  Cable (012-0057-01)
- 1 BNC to dual binding post Adapter (013-0094-00)
- 1 50 $\Omega$  BNC Termination (011-0049-00)

c. *Other Equipment*

- 1 2:1 Step-up Transformer (067-0052-00)

\* This equipment must be traceable to NBS for certification of measurement characteristics.

<sup>1</sup> Check Accuracy at 45VAC and 136VAC

Substitute test equipment may be used. The Plant Staff Engineer must approve any substitutions. All equipment listed must perform within its manufacturer's specifications, unless otherwise stated.

## FACTORY TEST LIMITS

### QUALIFICATION

Factory Test Limits are qualified by the conditions specified in the main body of the Factory Calibration Procedure. The numbers and letters to the left of the limits correspond to the procedure steps where the check or adjustment is made. Steps without Factory Test Limits (set-ups, presets, etc.) are not listed. Instruments may not meet Factory Test Limits if calibration or checkout methods and test equipment differ substantially from those in this procedure.

- |  |                                   |
|--|-----------------------------------|
| 4. POWER SUPPLY                                  | * 9. AMPLITUDE FLATNESS           |
| a. -10V; $\pm 10\%$ ; ripple $\leq 100\text{mV}$ | $\pm 2.5\%$ , 50Hz to 1MHz        |
| 90VAC to 272VAC                                  |                                   |
| b. +10V: $\pm 10\%$ ; ripple $\leq 100\text{mV}$ | 10. 1MHz HARMONIC DISTORTION      |
| 90VAC to 272VAC                                  | 3rd harmonic: $\leq 2.5\%$        |
| * 5. 3MHz OSCILLATOR                             |                                   |
| b. FREQUENCY range: 3MHz, + & -                  | 11. INPUT VOLTAGE RANGE           |
| 238Hz  | Amplitude: $\pm 1\%$ , 0.8V to 2V |
| 6. OUTPUT AMPLITUDE                              |                                   |
| a. Max output: 4V to 8V P-P                      | 12. HARMONIC DISTORTION           |
| b. OUTPUT AMPLITUDE range: 17.7                  | 3rd harmonic: $\leq 2\%$          |
| to 1   |                                   |
| 7. FAST-SLOW                                     |                                   |
| a. Recovery time: 10 seconds                     |                                   |
| b. SLOW amplitude $\pm 1\%$                      |                                   |
| 8. OUTPUT RESISTANCE                             |                                   |
| 600 $\Omega$ $\pm 15\%$                          |                                   |

THE END

\* Indicates measurement characteristics; test equipment must be traceable to NBS for instrument certification.

## SHORT FORM PROCEDURE

Factory TEST LIMITS are limits an instrument must meet before it leaves Manufacturing; therefore, it must be possible to inspect to these limits. Because of normal variations in test equipment and plug-in scopes, addition of side panels, etc, it is necessary to set up some circuits so their performance is better than required by Factory Test Limits. Therefore, the instructions given in the Factory Calibration Procedure may call for checks or adjustments which result in less error than that allowed by the Factory Test Limits.

### 1. FUSES

- a. Check fuses F80 and F82:  
1/16 A SLO BLO

### 2. RESISTANCE CHECK

- a. Check Supplies

<u>Pin No</u>	<u>Supply</u>	<u>Meter Scale</u>	<u>Approx Resistance</u>
P	-10V	x1k	2k $\Omega$
R	+10V	x10	70 $\Omega$

- b. Check transformer primary

	<u>To</u>	<u>Approx Resistance</u>
Gnd pin	chassis	0 $\Omega$
Power pin	chassis	inf
Power pin	power pin	180 $\Omega$

### 3. PRESETS

### 4. POWER SUPPLY

- a. Check Voltages: 10V  $\pm$ 1V
- b. Check ripple:  $\leq$ 100mV, 90 to 272VAC

### 5. 3MHz OSCILLATOR

- a. Setup
- b. Adjust L41 for zero beat
- c. Check FREQUENCY range: + and - 250Hz

### 6. OUTPUT AMPLITUDE

- a. Maximum output: 4 to 8V P-P
- b. Range: 17.7 to 1

### 7. FAST-SLOW

- a. Recovery Time: 10 seconds
- b. Check SLOW Amplitude:  $\pm$ 0.5mm

### +8. OUTPUT RESISTANCE

- a. Check output resistance: 600 $\Omega$   $\pm$ 15%  
(2cm  $\pm$ 1.5mm)

### 9. AMPLITUDE FLATNESS

- a. Setup: 5cm at 50Hz
- b. 10kHz amplitude:  $\pm$ 1.0mm
- + c. 100kHz amplitude:  $\pm$ 1.0mm
- + d. 300kHz amplitude:  $\pm$ 1.0mm
- e. 1MHz amplitude:  $\pm$ 1.0mm

### 10. 1MHz HARMONIC DISTORTION

- a. Setup
- b. Check distortion: 1cm

### 11. INPUT VOLTAGE

- a. Setup : 5cm with 1.5V input
- b. Check .65V input:  $\pm$ 0.5mm
- + c. Check 2V input:  $\pm$ 0.5mm

### 12. HARMONIC DISTORTION

- a. Setup
- b. 10kHz distortion:  $\leq$ 1.6cm
- + c. 100kHz distortion:  $\leq$ 1.6cm
- + d. 300kHz distortion:  $\leq$ 1.6cm
- e. 50Hz distortion:  $\leq$ 1.6cm

+ These checks are not made on 100% of the instruments but are done on a sampling basis.

THE END

1. FUSES

Check fuses, F80 and F82.  
1/16 A, SLO BLO

2. RESISTANCE CHECK*a. Check supplies*

Measure resistance to ground  
at:

<u>Pin No</u>	<u>Supply</u>	<u>Meter Scale</u>	<u>Approx Resistance</u>
P	-10V	x1k	2k $\Omega$
R	+10V	x10	70 $\Omega$

*b. Check transformer primary*

Turn POWER switch to ON.

Measure from power plug:

	<u>To</u>	<u>Approx Resistance</u>
Gnd pin	chassis	0 $\Omega$
Power pin	chassis	inf
Power pin	power pin	180 $\Omega$

b. Instrument not connected to  
TYPE 76TU.

3. PRESETS*a. Test Scope with 1A1 installed*

TIME/CM	5mSEC
TRIGGER MODE	AUTO
TRIGGER SLOPE	+
TRIGGER SOURCE	LINE
CH 1 VOLTS/CM	.05
CH 2 VOLTS/CM	1

*b. SWEPT FREQUENCY CONVERTER*

FAST-SLOW	FAST
FREQUENCY	set 180° cw from fully ccw
OUTPUT AMPLITUDE	fully cw
POWER	OFF

## 3. (cont'd)

## c. TYPE 1L5

CENTER FREQUENCY-Hz	500k
DISPERSION Hz/CM	100k
SWEEP MODE	MANUAL
MANUAL	midrange

---

4. POWER SUPPLYa. Check voltages: 10V  $\pm$ 1V

Connect the SFC (SWEPT FREQUENCY CONVERTER) to the TYPE 76TU via a 2:1 step-up transformer. Set the TYPE 76TU for 57.5VAC. (The step-up transformer will convert this to 115VAC.) Switch POWER to ON.

Measure the voltage at pin P of the circuit board for -9 to -11V.

Measure the voltage at pin R for +9 to +11V.

## b. Check ripple:

$\leq 100\text{mV}$ , 90 to 272VAC

Connect a X1 probe from CH 1 of the TYPE 1A1 to pin P. Vary the TYPE 76TU from 45 to 136VAC and check ripple for 100mV, max.

Connect the X1 probe to pin R. Vary the TYPE 76TU between 45 and 136VAC and check ripple for 100mV, max.

Return the TYPE 76TU to 57.5VAC.

---

5. 3MHz OSCILLATOR

## a. Setup

Connect a 93 $\Omega$  BNC cable with adapter between CH 2 and the SFC OUTPUT. Connect a 50 $\Omega$  BNC cable from the TYPE 184 MARKER OUT to the SFC OSC IN. Set the TYPE 184 for 1 $\mu$ s markers.

## 5a. (cont'd)

Switch the TYPE 1A1 to CH 2. Set Test Scope TIME/CM to  $1\mu\text{s}$  and TRIGGER SOURCE to NORM.


## b. Adjust L41: zero beat

Adjust L41 until the Test Scope displays 1MHz sine waves. The sine wave amplitude will vary slowly as "zero beat" is approached. Adjust L41 for minimum variation at "zero beat".

c. Check FREQUENCY range:  
+ and - 250Hz

Set the TYPE 184 for  $5\mu\text{s}$  markers. Switch Test Scope TIME/CM to 2mSEC, TRIGGER MODE to TRIG, and LEVEL for a stable display. Check for at least 5 peaks in 8cm with FREQUENCY fully cw. Rotate FREQUENCY fully ccw and check for at least 5 peaks in 8cm. Readjust L41 if necessary.

Remove the cable from TYPE 184 MARKER OUTPUT.



5 peaks in 8cm

## 6. OUTPUT AMPLITUDE

## a. Maximum output: 4 to 8V P-P

Connect the TYPE 1L5 OSC OUT to the SFC OSC IN with 93 $\Omega$  cable. Set TYPE 1A1 CH 2 VOLTS/CM to 2. Check for 2 to 4cm display.

## b. Range: 17.7 to 1

Switch CH 2 VOLTS/CM to 1. Adjust VARIABLE for 3.55cm of display. Change CH 2 VOLTS/CM to .1. Turn SFC OUTPUT AMPLITUDE fully ccw. Check for no more than 2cm of display.

## 7. FAST-SLOW

a. *Recovery time: 10 seconds*

Return OUTPUT AMPLITUDE fully cw.  
Adjust TYPE 1A1 CH 2 VOLTS/CM and  
VARIABLE for 5cm display. Set 1L5  
CENTER FREQUENCY-Hz to 0000 and  
DISPERSION Hz/CM to 1k. Set MANUAL  
SCAN fully clockwise.

Switch FAST-SLOW from FAST to SLOW.  
Display must return to former ampli-  
tude within 10 seconds.

b. *Amplitude:  $\pm 0.5mm$*

Check SLOW amplitude for 4.95 to  
5.05cm.

## +8. OUTPUT RESISTANCE      $600\Omega \pm 15\%$

Set CH 2 VARIABLE for 4cm of display.  
Place  $600\Omega$  Terminator on CH 2 end of  
 $93\Omega$  cable.

Check for 1.85 to 2.15cm display.

## 9. AMPLITUDE FLATNESS

a. *Setup: 5cm at 50Hz*

Set TYPE 1L5 CENTER FREQUENCY-Hz to  
000 and DISPERSION Hz/CM to 100. Set  
Test Scope TIME/CM to 20mSEC. Adjust  
TYPE 1L5 MANUAL SCAN for 1 cycle/cm.  
Set CH 2 VARIABLE for 5cm display.

b. *10kHz amplitude:  $\pm 1.0mm$*

Set TYPE 1L5 CENTER FREQUENCY-Hz to  
9900 and DISPERSION Hz/CM to 1K. Check  
for 4.9 to 5.1cm display.

+c. *100kHz amplitude:  $\pm 1.0mm$*

Set TYPE 1L5 CENTER FREQUENCY-Hz to  
100k. Check for 4.9 to 5.1cm display.

a. Be sure output is terminated in  
 $600\Omega$ .

+These checks are not made on 100% of  
the instruments but are done on a sampling  
basis.



## 9. (cont'd)

d. 300kHz amplitude:  $\pm 1.0mm$

Set TYPE 1L5 CENTER FREQUENCY-Hz to 300k. Check for 4.9 to 5.1cm display.

e. 1MHz amplitude:  $\pm 1.0mm$

Set Test Scope TIME/CM to 1 $\mu$ SEC. Set TYPE 1L5 CENTER FREQUENCY-Hz to 990k. Adjust MANUAL SCAN for 1 cycle per cm.

Check for sine wave amplitude of 4.9 to 5.1cm.

e. Measure from trace center to trace center.

---

10. 1MHz HARMONIC DISTORTION

a. Setup

Connect Filter to the SFC OUTPUT. Connect a 93 $\Omega$  BNC cable to the Filter OUTPUT. Connect a X10 probe from TYPE 1A1 CH 2 INPUT to Filter INPUT.

b. Check distortion: 1cm

Adjust CH 2 VOLTS/CM to .05 and VARIABLE for 5cm of display. Disconnect the X10 probe and connect the 93 $\Omega$  cable to CH 2 INPUT. Check for 1cm maximum display of 3MHz.

---

11. INPUT VOLTAGE

a. Setup

Replace the Filter with adapter and connect the 93 $\Omega$  cable to the SFC OUTPUT. Place the 600 $\Omega$  Terminator at the 1A1 end of the cable. Switch CH 2 VOLTS/CM .5.

Connect TYPE 191 OUTPUT through a 50 $\Omega$  Terminator to the TYPE 1A1 CH 1. Set CH 1 VOLTS/CM to .5. Adjust TYPE 191 AMPLITUDE for 3cm at 2.5MHz.

## 11a. (cont'd)

Connect TYPE 191 to SFC OSC IN.  
Set TYPE 1A1 to CH 2. Adjust CH 2  
VARIABLE for 5cm. Switch FAST-SLOW  
to FAST.

*b. Check 0.65V input:  $\pm 0.5\text{mm}$*

Connect TYPE 191 to TYPE 1A1 CH 1.  
Adjust TYPE 191 AMPLITUDE for  
1.3cm of display.

Connect TYPE 191 to SFC OSC IN.  
Switch 1A1 to CH 2. Check for 4.95  
to 5.05cm of display.

*c. Check 2V input:  $\pm 0.5\text{mm}$*

Connect TYPE 191 to TYPE 1A1 CH 1.  
Adjust TYPE 191 AMPLITUDE for 4cm  
of display.

Connect TYPE 191 to SFC OSC IN.  
Switch TYPE 1A1 to CH 2. Check for  
4.95 to 5.05cm of display.

---

12. HARMONIC DISTORTION*a. Setup*

Set calibration Scope 1L5 CENTER  
FREQUENCY-Hz to 9900 and DISPERSION  
Hz/CM to 1k. Connect OSC OUT to SFC  
OSC IN with 93 $\Omega$  cable.

Set Test Scope TIME/CM to .2SEC. Re-  
place the TYPE 1A1 with the second 1L5.  
Connect SWEEP A to SWEEP INPUT and set  
SWEEP MODE to EXT. Set Test Scope 1L5  
CENTER FREQUENCY-Hz to 50k, VERTICAL  
DISPLAY to LOG and DISPERSION Hz/CM to  
10k. Connect the SFC OUTPUT through the  
600 $\Omega$  Terminator to the Test Scope 1L5  
INPUT. Adjust the Test Scope 1L5  
INPUT. Adjust the Test Scope 1L5 VOLTS/  
CM and VARIABLE for 5cm display at 10kHz.

## 12. (cont'd)

b. 10kHz distortion:  $\leq 1.6\text{cm}$

Check for 1.6cm or less display  
at 30kHz.

†c. 100kHz distortion:  $\leq 1.6\text{cm}$

Change Calibration Scope 1L5 CENTER  
FREQUENCY-Hz to 100k. Change Test  
Scope 1L5 CENTER FREQUENCY-Hz to 500k  
and DISPERSION-Hz/CM to 100k. Check  
for 1.6cm or less display at 300kHz.

†d. 300kHz distortion:  $\leq 1.6\text{cm}$

Change Calibration Scope 1L5 CENTER  
FREQUENCY-Hz to 300k. Check for 1.6cm  
or less display at 900kHz.

e. 50Hz distortion:  $\leq 1.6\text{cm}$

Change Calibration Scope 1L5 CENTER  
FREQUENCY-Hz to 000 and DISPERSION  
Hz/CM to 100. Change Test Scope CEN-  
TER FREQUENCY-Hz to 100, DISPERSION  
Hz/CM to 20.

Switch SFC FAST-SLOW to SLOW.

Adjust Calibration Scope MANUAL sweep  
for a 5cm display of 50Hz. (Test Scope  
VARIABLE VOLTS/CM may need readjustment.)

Check for 1.6cm or less at 150Hz.

THE END