

Tektronix
COMMITTED TO EXCELLENCE



COMBINATION EDITION
*Wizards
Workshop*

* ALL SERVICE QUESTIONS FROM EUROPE, MIDDLE EAST,
* AND AFRICA SHOULD BE ADDRESSED TO THE EUROPEAN
* MARKETING CENTER SERVICE GROUP IN THE NETHERLANDS.

TEKTRONIX INTERNAL USE ONLY

PUBLISHED BY SERVICE ADMIN SUPPORT
56-037 EXT. 8939 MERLO

SEPTEMBER 1981

WIZARDS WORKSHOP MASTER INDEX

92-515

MICHAEL A MIHALIK

COMBINATION WIZARD

JANUARY 1981 - JULY 1981

NOTE: THIS INDEX IS TO SUPPLEMENT THE JANUARY 1977 -
DECEMBER 1980 EDITION. A COMPLETE REPLACEMENT WILL BE
DISTRIBUTED IN JANUARY 1982.



WIZARDS WORKSHOP INDEX

ADMINISTRATIVE SUPPORT

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| INFORMATION SYSTEMS | 11-11 | JUN 19, 1981 | 4 |
| INFORMATION SYSTEMS | 11-13 | JUL 17, 1981 | 5 |
| REPORT DISTRIBUTION | 11-10 | JUN 05, 1981 | 12 |
| SERVICE INFORMATION SYSTEMS | 11-01 | JAN 16, 1981 | 6 |
| SERVICE INFORMATION SYSTEMS PROGRAM | 11-05 | MAR 27, 1981 | 10 |
| SERVICE PROCESSING RECORD | 11-12 | JUL 03, 1981 | 9 |
| SERVICE RECORD PROCESSING; DOA PRODUCTS | 11-04 | MAR 6, 1981 | 7 |
| SERVICE RECORD PROCESSING - MODULE EXCHANGE COPY | 11-06 | APR 10, 1981 | 10 |
| SERVICE RECORD PROCESSING- TRANSFERRED PRODUCTS | 11-07 | APR 24, 1981 | 3 |
| SERVICE RECORD PROCESSING | 11-09 | MAY 22, 1981 | 2 |
| SERVICE SUPPORT PRODUCT RESPONSIBILITY LIST | 11-11 | JUN 19, 1981 | A-1 |
| WIZARD WORKSHOP BY MICROFICHE | 11-11 | JUN 19, 1981 | 4 |

1 SEPTEMBER 1981

PAGE 1

WIZARDS WORKSHOP INDEX

GENERAL

| TITLE | ISSUE | DATE | PAGE |
|---|-------|--------------|------|
| 131-2407-00- MIXED STOCK - "PURGE" | 11-04 | MAR 6, 1981 | 6 |
| 156-0072-00 DEFECTIVE DATE CODES | 11-07 | APR 24, 1981 | 2 |
| 231-0312-00 - MIXED STOCK - "PURGE" | 11-04 | MAR 6, 1981 | 6 |
| 311-0053-00 DEFECTIVE DATE CODE - "PURGE" | 11-07 | APR 24, 1981 | 2 |
| ANTI-STATIC MATERIALS REMINDER | 11-02 | JAN 30, 1981 | 2 |
| AUDIO TAPES AVAILABLE | 11-08 | MAY 8, 1981 | 5 |
| BASIC TRANSISTOR TROUBLESHOOTING REVISITED | 11-11 | JUN 19, 1981 | 2 |
| BASIC TRANSISTOR TROUBLESHOOTING REVISITED - ARTICLE #2 | 11-12 | JUL 03, 1981 | 4 |
| BASIC TRANSISTOR TROUBLESHOOTING REVISITED - ARTICLE #3 | 11-13 | JUL 17, 1981 | 1 |
| BEAVERTON SERVICE SUPPORT GROUP- NEW PHONE EXTENSIONS | 11-05 | MAR 27, 1981 | 2 |
| BEAVERTON SERVICE SUPPORT GROUP - NEW PHONE EXTENSIONS REF. PULL-OUT | 11-06 | APR 10, 1981 | A-1 |
| CLEANING AND MAINTENANCE OF TEK-MADE ROTARY SWITCHES | 11-13 | JUL 17, 1981 | A-1 |
| CRT FAILURES AND REJECTS | 11-04 | MAR 6, 1981 | 3 |
| DESIGNATED SERVICE CENTERS | 11-01 | JAN 16, 1981 | 4 |
| DIGITAL CONCEPTS VIDEOTAPE (CORRECTION) | 11-11 | JUN 19, 1981 | 1 |
| EXTENSION SHAFTS (W-KNOBS) | 11-02 | JAN 30, 1981 | 5 |
| FAILURE CODES - ALPHABETICAL LISTING | 11-06 | APR 10, 1981 | 6 |
| IC RELIABILITY | 11-13 | JUL 17, 1981 | 2 |
| INTERNATIONAL MANUFACTURED PRODUCTS SOLD IN THE U.S. | 11-05 | MAR 27, 1981 | 3 |
| LOGIC PROBE, 010-6401-01 | 11-02 | JAN 30, 1981 | 5 |
| M.R.I.S. CHANGES ITS NAME | 11-05 | MAR 27, 1981 | 4 |
| MANUAL CORRECTION REQUESTS | 11-10 | JUN 05, 1981 | 5 |
| MASS STORAGE CONCEPTS FLEXIBLE DISK-PART I | 11-04 | MAR 6, 1981 | 4 |
| MASS STORAGE CONCEPTS FLEXIBLE DISK - PART 2 | 11-06 | APR 10, 1981 | 7 |
| MICROFICHE AND MANUAL CORRECTION FORMS | 11-07 | APR 24, 1981 | 1 |
| MICROFICHE MAINTENANCE INFORMATION | 11-08 | MAY 8, 1981 | 5 |
| NEW DISTRIBUTORS IN KOREA | 11-08 | MAY 8, 1981 | 6 |
| NEW HONG KONG DISTRIBUTOR | 11-03 | FEB 20, 1981 | 3 |
| NEW SERVICE ACTION REQUEST FORMS | 11-11 | JUN 19, 1981 | 3 |
| NEW VIDEO TAPES/SERVICE TECHNICIANS | 11-03 | FEB 20, 1981 | 4 |

1 SEPTEMBER 1981

PAGE 2

WIZARDS WORKSHOP INDEX

GENERAL

| TITLE | ISSUE | DATE | PAGE |
|---|-------|--------------|------|
| ORGANIZATIONAL CHART - CHICAGO AREA | 11-02 | JAN 30, 1981 | 6 |
| PROBE SUPPORT | 11-11 | JUN 19, 1981 | 3 |
| PRODUCT SAFETY PERSONNEL | 11-02 | JAN 30, 1981 | 7 |
| REORGANIZATION WITHIN SERVICE ORGANIZATION | 11-12 | JUL 03, 1981 | 7 |
| SAMPLING TRAINING PACKAGE | 11-09 | MAY 22, 1981 | 1 |
| SERVICE ACTION REQUEST (GAR) FORM ORDERING INSTRUCTIONS | 11-13 | JUL 17, 1981 | 4 |
| SERVICE SUPPORT RELOCATION | 11-10 | JUN 05, 1981 | 5 |
| SERVICE UPDATE PROGRAMS STATUS | 11-02 | JAN 30, 1981 | 9 |
| SERVICE UPDATE PROGRAMS STATUS | 11-05 | MAR 27, 1981 | 4 |
| SERVICE UPDATE PROGRAMS STATUS | 11-10 | JUN 05, 1981 | 6 |
| SHOP JACKETS NOW AVAILABLE | 11-13 | JUL 17, 1981 | 4 |
| SOLDERING ITEMS | 11-01 | JAN 16, 1981 | 5 |
| STOLEN INSTRUMENTS (INTERNATIONAL) | 11-06 | APR 10, 1981 | 9 |
| STOLEN INSTRUMENTS (INTERNATIONAL) | 11-08 | MAY 8, 1981 | 6 |
| TEKTRONIX MANUFACTURED INTEGRATED CIRCUITS | 11-07 | APR 24, 1981 | 1 |
| TEST EQUIPMENT MAINTENANCE | 11-12 | JUL 03, 1981 | 8 |
| TROUBLESHOOTING SYMPTOMS HANDBOOKS | 11-03 | FEB 20, 1981 | 5 |
| TROUBLESHOOTING SYMPTOM GUIDES AVAILABLE FOR EUROPE | 11-06 | APR 10, 1981 | 9 |
| TROUBLESHOOTING SYMPTOMS HANDBOOK - CORRECTION | 11-12 | JUL 03, 1981 | 8 |

1 SEPTEMBER 1981

PAGE 3

WIZARDS WORKSHOP INDEX

INFORMATION DISPLAY DIVISION

MEASUREMENT DISPLAY

| TITLE | ISSUE | DATE | PAGE |
|---|-------|--------------|------|
| 618 MOD DM, GMA125 MOD KA POWER SUPPLY CABLE | 11-04 | MAR 6, 1981 | 8 |
| 618 OPT 30 CABLE (012-0924-00) | 11-06 | APR 10, 1981 | 20 |
| 634 : YOKE DRIVER BOARD MODIFICATION #39769 | 11-11 | JUN 19, 1981 | 8 |
| 634 : YOKE DRIVER BOARD MODIFICATION #36631 | 11-11 | JUN 19, 1981 | 5 |
| 634 GEOMETRY SPECIFICATIONS | 11-04 | MAR 6, 1981 | 8 |
| IDD MAINTENANCE AGREEMENT PROMOTION SERVICE PLAN 12/14/79 CORRECTION | 11-01 | JAN 16, 1981 | 18 |
| IDD PRODUCTS POWER LINE REQUIREMENTS AND ENVIRONMENTAL IMPACT- REF. PULL-OUT | 11-09 | MAY 22, 1981 | B-1 |
| MEASUREMENT DISPLAY MODIFIED PRODUCTS | 11-02 | JAN 30, 1981 | 16 |

LABORATORY INSTRUMENTS DIVISION

SAMPLING PRODUCTS

| | | | |
|---|-------|--------------|----|
| 1502 U1575 SOLDERED TO CIRCUIT BOARD | 11-06 | APR 10, 1981 | 11 |
| 1502 WARRANTY EXCEPTION FOR THE SAMPLING BRIDGE AND TUNNEL DIODE | 11-12 | JUL 03, 1981 | 10 |
| 1502/1503 CHART RECORDER WITH A TIGHT FIT | 11-07 | APR 24, 1981 | 4 |
| SERVICE UPDATE PROGRAM #3001 | 11-01 | JAN 16, 1981 | 7 |

TM 500

| | | | |
|--|-------|--------------|----|
| AA501 CIRCUIT DESCRIPTION AUDIO TAPE AVAILABLE | 11-04 | MAR 6, 1981 | 3 |
| AM503 SWITCH CONTACTS | 11-11 | JUN 19, 1981 | 16 |
| BNC WRENCH AVAILABLE | 11-02 | JAN 30, 1981 | 17 |
| CG511AP CALIBRATION VOLTMETER AND TERMINATION RECOMMENDATIONS | 11-11 | JUN 19, 1981 | 9 |
| CG551AP OPTION 01 FIELD INSTALLATION | 11-10 | JUN 05, 1981 | 13 |
| CG551AP RESPONSE TO % VARIABLE QUERIES | 11-13 | JUL 17, 1981 | 6 |
| CG551AP RESPONSE TO "DSP ON/OFF" COMMAND | 11-13 | JUL 17, 1981 | 6 |
| DC503A TIME A TO B DESIGN ERROR | 11-07 | APR 24, 1981 | 4 |
| DC509 MAINTENANCE INFORMATION UPDATE | 11-11 | JUN 19, 1981 | 9 |
| DC509 UNIVERSAL COUNTER/TIMER INTER-CHANNEL CROSSTALK | 11-11 | JUN 19, 1981 | 12 |

1 SEPTEMBER 1981

WIZARDS WORKSHOP INDEX

TM 500

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| DM501A 200 ZERO MODIFICATION | 11-05 | MAR 27, 1981 | 11 |
| DM501A 200 ZERO MODIFICATION UPDATE | 11-07 | APR 24, 1981 | 5 |
| DM501A AC VOLTS ZERO | 11-03 | MAY 8, 1981 | 8 |
| DM501A INTERMITTENTS | 11-05 | MAR 27, 1981 | 11 |
| DM502 AC HOOK | 11-03 | FEB 20, 1981 | 6 |
| DM502A, CLARIFICATION OF CAL/CERT | 11-03 | MAY 8, 1981 | 7 |
| FG501/FG507 SINE DISTORTION STABILIZATION | 11-01 | JAN 16, 1981 | 11 |
| FG501A/FG507 DISTORTION MEASUREMENT CORRECTION | 11-07 | APR 24, 1981 | 5 |
| FG501A/FG507 DISTORTION MEASUREMENT | 11-05 | MAR 27, 1981 | 12 |
| FG504 FUSE MODIFICATION KIT | 11-03 | FEB 20, 1981 | 6 |
| FG507/FG501A DISTORTION MEASUREMENT | 11-05 | MAR 27, 1981 | 12 |
| PG501 OSCILLATION WHEN SWITCHING RANGES | 11-06 | APR 10, 1981 | 11 |
| PG505 PULSE GENERATOR | 11-11 | JUN 19, 1981 | 13 |
| REPORT OF CALIBRATION AND CERTIFICATION | 11-11 | JUN 19, 1981 | 10 |
| 32503 - REPAIRING INTERMITTENT S240 | 11-13 | JUL 17, 1981 | 7 |
| TROUBLESHOOTING FLOWCHART FOR CG551AP DRIFT | 11-09 | MAY 22, 1981 | 3 |

5000 SERIES

| | | | |
|---|-------|--------------|----|
| 5000/7000 SERIES SPOT-OF-GOLD RIBBON CONNECTOR CODE 13 TERMINATION | 11-01 | JAN 16, 1981 | 12 |
| 5110/R, 5111/R, 5115/R OPTION 7 HORIZONTAL BANDWIDTH | 11-02 | JAN 30, 1981 | 17 |
| 5223 +86 VOLT POWER SUPPLY | 11-03 | FEB 20, 1981 | 6 |
| 5223 CAPACITOR RATING CHANGE (C613) | 11-02 | JAN 30, 1981 | 18 |
| 5223 GPIB CONVERSION KIT | 11-04 | MAR 6, 1981 | 9 |
| 5223 GPIB CONVERSION KIT AND RETROFIT MAINTENANCE NOTES | 11-10 | JUN 05, 1981 | 13 |
| 5223, DISPLACED DOTS | 11-12 | JUL 03, 1981 | 10 |
| 5223, NEW MEMORY BOARD SHIELD | 11-11 | JUN 19, 1981 | 14 |
| 5223, OPTION 10, G.P.I.B., RETROFIT INSTALLATION MAINTENANCE NOTES | 11-07 | APR 24, 1981 | 6 |
| 5223, POSSIBLE VERTICAL AND HORIZONTAL OSCILLATIONS | 11-13 | JUL 17, 1981 | 8 |
| 5223, TROUBLESHOOTING W/MEMORY BOARD ON EXTENDER | 11-07 | APR 24, 1981 | 6 |

1 SEPTEMBER 1981

WIZARDS WORKSHOP INDEX

7000 SERIES

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| 7603 AND 7613 VERT. SIG. OUT CENTERING SPEC. CORRECTION | 11-04 | MAR 6, 1981 | 9 |
| 7613 AND 7603 VERT. SIG. OUT CENTERING SPEC. CORRECTION | 11-04 | MAR 6, 1981 | 9 |
| 7704A MAIN INTERFACE POWER CABLE FALLS OFF | 11-04 | MAR 6, 1981 | 10 |
| 7704A, 7854, R7903 AND 7904 FIELD REPLACEMENT CRT'S | 11-10 | JUN 05, 1981 | 14 |
| 7854 POSSIBLE CONTINUOUS ACQUIRE | 11-10 | JUN 05, 1981 | 15 |
| 7854 ROM BOARD ERROR, S/N B010400 & BELOW | 11-04 | MAR 6, 1981 | 10 |
| 7854, DIAGNOSTIC MANUALS | 11-08 | MAY 8, 1981 | 8 |
| 7854, PREVENTION OF POSSIBLE CRT BURNS | 11-07 | APR 24, 1981 | 7 |
| 7854, ROM BOARD | 11-11 | JUN 19, 1981 | 14 |
| 7904/R7903 HIGH SPEED TIMING | 11-02 | JAN 30, 1981 | 18 |
| 7885 DIGITAL VOLTMETER BOARD CHANGE DOCUMENTATION | 11-01 | JAN 16, 1981 | A-1 |
| 7885 DIGITAL VOLTMETER BRD CHNG DOCUMENTATION REF. PULL-OUT CORRECTION | 11-02 | JAN 30, 1981 | A-1 |
| 7D15 IC SOCKETS CODE 18 TERMINATION | 11-01 | JAN 16, 1981 | 12 |

WIZARDS WORKSHOP INDEX
COMMUNICATIONS DIVISION

MEDICAL PRODUCTS

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| 400/401 INSTALLATION KITS FOR MEDICAL INSTRUMENTS | 11-13 | JUL 17, 1981 | 10 |
| 403/412 LEAD FAULT MALFUNCTION | 11-13 | JUL 17, 1981 | 11 |
| 413-A RESPIRATION COMPLAINTS | 11-05 | MAR 27, 1981 | 13 |
| 413A -- CHANGE IN MOUNTING HARDWARE FOR Q4158 & Q4159 | 11-13 | JUL 17, 1981 | 12 |
| 413A/REPLACEMENT OF RATE LIMITS POTS | 11-13 | JUL 17, 1981 | 13 |
| MEDICAL (U.S. ONLY) | 11-12 | JUL 03, 1981 | 5 |
| MEDICAL BUSINESS UNIT PHASE-OUT PLAN | 11-03 | FEB 20, 1981 | 7 |
| MEDICAL MONITORS | 11-09 | MAY 22, 1981 | 1 |
| MEDICAL PRODUCTS, ROLE OF SERV SUPPORT | 11-03 | FEB 20, 1981 | 7 |
| USE OF ACTIVITY COSES/TDS REPORTING (U.S. ONLY) | 11-08 | MAY 8, 1981 | 9 |
| VITATEK SUPPORT | 11-11 | JUN 19, 1981 | 15 |

SPECTRUM ANALYZERS

| | | | |
|--|-------|--------------|-----|
| 492 2ND CONVERTER (P/N 119-1096-00) REPL | 11-03 | FEB 20, 1981 | 8 |
| 492 FRONT PANEL LOCK UP | 11-01 | JAN 16, 1981 | 13 |
| 492 OPERATOR'S MANUAL CORRECTION (C8/880) | 11-02 | JAN 30, 1981 | 19 |
| 492/492P RUNNING TIME | 11-05 | MAR 27, 1981 | 14 |
| 492/492P SER. MAN. V.2 - MAN. CHG. INFO. TO OFFSET MIXER AREA (REPRINT) | 11-11 | JUN 19, 1981 | 15 |
| 492/492P SERV. MAN. V.2 - MAN. CHG. INFO. OFFSET MIXER AREA | 11-10 | JUN 05, 1981 | 18 |
| 492/P 100HZ SIDEBANDS CAUSED BY FAN | 11-03 | FEB 20, 1981 | 11 |
| 492/P 100HZ SIDEBANDS CAUSED BY FAN - "UPDATE" | 11-05 | MAR 27, 1981 | 16 |
| 492/P 2ND L.O. REPLACEMENT | 11-03 | FEB 20, 1981 | 9 |
| 492/P 33 & 66HZ SYNTHESIZER SIDEBANDS ON FIRST L.O. | 11-08 | MAY 8, 1981 | 10 |
| 492/P 3MM CONNECTORS | 11-04 | MAR 6, 1981 | 11 |
| 492/P B03 & UP SERVICE VOLUME #2 CORRECTIONS | 11-08 | MAY 8, 1981 | 12 |
| 492/P B03 AND UP MANUAL CHANGE TO CALIBRATION PROCEDURE | 11-12 | JUL 03, 1981 | A-1 |

1 SEPTEMBER 1981

PAGE 7

WIZARDS WORKSHOP INDEX

SPECTRUM ANALYZERS

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| 492/P FIELD MOD KITS TO RETROFIT OPTIONS 1,2, & 3 - "NOT AVAILABLE" | 11-05 | MAR 27, 1981 | 14 |
| 492/P INCORRECT POWER SUPPLY CAPACITORS INSTALLED | 11-09 | MAY 22, 1981 | 5 |
| 492/P MANUAL CORRECTION (VOLUME), C8/880 | 11-02 | JAN 30, 1981 | 21 |
| 492/P MICROPROCESSOR SELF TEST LOOP ERROR (A58CR2025) | 11-06 | APR 10, 1981 | 13 |
| 492/P MICROPROCESSOR LOCK-UP DURING TURN ON | 11-09 | MAY 22, 1981 | 5 |
| 492/P OSCILLATIONS OF 320 MHZ ON THE 110 MHZ IF AMP BOARD | 11-09 | MAY 22, 1981 | 6 |
| 492/P POWER SUPPLY TROUBLESHOOTING HINTS | 11-08 | MAY 8, 1981 | 10 |
| 492/P REPLACEMENT OF A30A1 F3038 | 11-09 | MAY 22, 1981 | 6 |
| 492/P S/N B03 AND UP MANUALS | 11-08 | MAY 8, 1981 | 12 |
| 492/P SERVICE MANUAL #2 MANUAL CHANGE INFORMATION TO CENTER FREQUENCY CONTROL | 11-05 | MAR 27, 1981 | 15 |
| 492/P SERVICE VOLUME #1 MANUAL CORRECTION (C11/1280) | 11-02 | JAN 30, 1981 | 23 |
| 492/P TUNABLE 2ND L.O. P/N 119-1022-01 MARKED INCORRECTLY | 11-04 | MAR 6, 1981 | 11 |
| 492P CIRCUIT BOARD MOUNTING HARDWARE MISSING | 11-13 | JUL 17, 1981 | 17 |
| 492P/492 RUNNING TIME | 11-05 | MAR 27, 1981 | 14 |
| 7L12 SWEEP GATE OUTPUT VOLTAGE TOO LOW | 11-12 | JUL 03, 1981 | 11 |
| 7L14 MANUAL CORRECTIONS TO DIAGRAM 15 | 11-04 | MAR 6, 1981 | 12 |
| 7L18 SPOT-OF-GOLD REPAIR PROGRAM (U.S. ONLY) | 11-03 | FEB 20, 1981 | 13 |
| 7L18 SPOT-OF-GOLD REPAIR PROGRAM (INTERNATIONAL) | 11-03 | FEB 20, 1981 | 12 |
| HIGH PERFORMANCE WAVEGUIDE MIXERS - SUPPORT | 11-10 | JUN 05, 1981 | 16 |
| RETURNING R & R ASSEMBLIES FOR SPECTRUM ANALYZERS | 11-08 | MAY 8, 1981 | 14 |

1 SEPTEMBER 1981

WIZARDS WORKSHOP INDEX

TELEVISION PRODUCTS

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| 1480 SERIES POOR FOCUS IN LINE SELECT MODE | 11-06 | APR 10, 1981 | 18 |
| 1480 SERIES VARIABLE LINE SELECTOR | 11-01 | JAN 16, 1981 | 16 |
| 149A LINEARITY RAMP PRESENTATION | 11-01 | JAN 16, 1981 | 14 |
| 1900 FCC COLOR BAR VIT CHROMINANCE | 11-06 | APR 10, 1981 | 18 |
| 1900 RACK LATCH COLORS | 11-06 | APR 10, 1981 | 18 |
| 520 TRACE ABERRATIONS | 11-06 | APR 10, 1981 | 15 |
| 528 OPTION 3 MAIN CIRCUIT BOARD ASSEMBLY | 11-10 | JUN 05, 1981 | 21 |
| 528A CRT IMPLOSION SHIELD | 11-07 | APR 24, 1981 | 12 |
| 528A FUSES | 11-07 | APR 24, 1981 | 12 |
| 528A TRANSFORMER SCREWS | 11-10 | JUN 05, 1981 | 21 |
| 529 FIELD CASE | 11-06 | APR 10, 1981 | 15 |
| 650 SERIES CRT VENDOR I.D. NUMBERS | 11-06 | APR 10, 1981 | 16 |
| 650 SERIES RASTER/VIDEO CENTERING | 11-07 | APR 24, 1981 | 12 |
| 650 SERIES RED CLAMP OSCILLATIONS | 11-06 | APR 10, 1981 | 16 |
| 650 SERIES/SOCKETS, 136-0220-00 | 11-09 | MAY 22, 1981 | 7 |
| 650HR, ADJUSTMENT C1270 | 11-04 | MAR 6, 1981 | 13 |
| 670A SECONDARY EMISSION | 11-01 | JAN 16, 1981 | 15 |
| SPG 1/2 CALIBRATION TECHNIQUE | 11-08 | MAY 8, 1981 | 15 |
| SPG1 MANUAL ERROR CORRECTION | 11-07 | APR 24, 1981 | 9 |
| SPG1/SPG2 CAL PROCEDURE CORRECTION | 11-04 | MAR 6, 1981 | 13 |
| TDC 1/2 FIRST LO ADJUSTMENT | 11-09 | MAY 22, 1981 | 7 |
| TDC PLL CIRCUIT FAILURE MODE | 11-10 | JUN 05, 1981 | 21 |
| TDC REPAIR AND RETURN PARTS | 11-01 | JAN 16, 1981 | 13 |
| TDC VOLTAGE CONTROLLED OSCILLATOR, ASU (UHF) | 11-07 | APR 24, 1981 | 10 |
| TSP 1/11 CALIBRATION PROCEDURE | 11-03 | FEB 20, 1981 | 14 |
| TV APP NOTE #22, 140 SERIES BLANKING INTERVALS | 11-13 | JUL 17, 1981 | 18 |
| TV GENERAL/PARTS ORDER PROBLEMS | 11-02 | JAN 30, 1981 | 24 |

1 SEPTEMBER 1981

PAGE 9

WIZARDS WORKSHOP INDEX

COMMUNICATIONS DIVISION (1980)

| TITLE | ISSUE | DATE | PAGE |
|--------------------------------------|-------|--------------|------|
| 1330 PART PROBLEM, 156-1309-00 | 11-07 | APR 24, 1981 | 13 |
| KEY PART NUMBERS (ANG. BULLETIN #11) | 11-04 | MAR 6, 1981 | 29 |

WIZARDS WORKSHOP INDEX

SERVICE INSTRUMENT DIVISION

ACCESSORIES

| TITLE | ISSUE | DATE | PAGE |
|---|-------|--------------|------|
| 40 PIN LOW PROFILE DIP CLIPS | 11-12 | JUL 03, 1981 | 13 |
| ALLIGATOR CLIPS P/N 344-0046-00 | 11-13 | JUL 17, 1981 | 20 |
| C-30B & 31B REAR FRAME ASSEMBLY | 11-11 | JUN 19, 1981 | 16 |
| C-51 & C-53 CURRENT SURGE MODIFICATION | 11-11 | JUN 19, 1981 | 17 |
| P6042 - P/N 156-0014-00 (M-18) REPLACEMENTS | 11-11 | JUN 19, 1981 | 17 |
| P6042 DEFECTIVE PROBE CABLES | 11-03 | FEB 20, 1981 | 15 |
| P6105 & P6106 BNC REPLACEMENT | 11-13 | JUL 17, 1981 | 20 |
| P6120 SERVICE MAINTENANCE INFORMATION | 11-11 | JUN 19, 1981 | 18 |
| P6201 PERFORMANCE IMPROVEMENT | 11-11 | JUN 19, 1981 | 19 |
| P6451 CUSHIONING PADS | 11-12 | JUL 03, 1981 | 13 |
| TEMPERATURE BATHS AND PROBES | 11-07 | APR 24, 1981 | 14 |

DATA COMMUNICATION ANALYZERS

| | | | |
|--|-------|--------------|----|
| 834 - IMPROVED REFERENCE CLOCK STABILITY | 11-12 | JUL 03, 1981 | 14 |
| 834 CHIP SELECT GLITCHES | 11-03 | FEB 20, 1981 | 16 |
| 834 FIRMWARE UPDATE | 11-02 | JAN 30, 1981 | 25 |
| 834 RO2 FIRMWARE UPDATE | 11-08 | MAY 8, 1981 | 16 |
| 834 RO1 "TRANSFER 30" CAUSING KEYBOARD LOCKUP | 11-12 | JUL 03, 1981 | 16 |
| 834 USED TO SERVICE OTHER DATA COMMUNICATION TESTERS | 11-11 | JUN 19, 1981 | 21 |
| 851 - THRESHOLD SWITCHES HAVING REVERSED CONTACTS | 11-11 | JUN 19, 1981 | 22 |
| 851 DC VOLTS OFFSET | 11-02 | JAN 30, 1981 | 26 |
| 851 NEW COUNTER BOARD REPLACEMENT | 11-03 | FEB 20, 1981 | 18 |

WIZARDS WORKSHOP INDEX

LOGIC ANALYZERS

| TITLE | ISSUE | DATE | PAGE |
|---|-------|--------------|------|
| 303 PART NUMBER CORRECTION | 11-02 | JAN 30, 1981 | 27 |
| 303 PART NUMBER CORRECTION | 11-06 | APR 10, 1981 | 19 |
| 303 TIME BASE STABILIZATION | 11-02 | JAN 30, 1981 | 27 |
| 7D02 OPTION 1 INTERMITTENT DIAGNOSTIC FAILURES | 11-11 | JUN 19, 1981 | 23 |
| 7D02 INTERMITTENT DIAGNOSTIC FAILURES WITH FLEXIBLE EXTENDERS | 11-05 | MAR 27, 1981 | 19 |
| DF1 - STEP ADDED TO 050-0999-01 | 11-13 | JUL 17, 1981 | 21 |
| PM108 UPDATE | 11-13 | JUL 17, 1981 | 22 |

PORTABLES

| | | | |
|---|-------|--------------|-----|
| 2213, 2215 FAILURE OR PROBLEM INFORMATION | 11-11 | JUN 19, 1981 | 24 |
| 2213, 2215 MAINTENANCE INFORMATION II | 11-13 | JUL 17, 1981 | 27 |
| 2335, 2336 DS900 PART NUMBER CHANGE | 11-12 | JUL 03, 1981 | 17 |
| 2335, 2336 MAINTENANCE INFORMATION | 11-10 | JUN 05, 1981 | 23 |
| 2335, 2336 MANUAL CALIBRATION CORRECTIONS | 11-12 | JUL 03, 1981 | B-1 |
| 2335, 2336 VERTICAL ABERRATIONS CHANGING 1 TO 2 MINOR DIVISIONS | 11-12 | JUL 03, 1981 | 17 |
| 2335, 2336, 2337 MAINTENANCE INFORMATION | 11-08 | MAY 8, 1981 | 18 |
| 305 NEW SERVICE MANUAL PART NUMBER | 11-03 | FEB 20, 1981 | 19 |
| 314/335 IMPROVED RELIABILITY OF VARIED CAPACITORS | 11-03 | FEB 20, 1981 | 19 |
| 335 P/N CHANGE FOR Q100 & Q200 | 11-03 | FEB 20, 1981 | 20 |
| 335 VERTICAL POSITION RANGE INCREASED | 11-03 | FEB 20, 1981 | 20 |
| 400 SERIES LOOSE HANDLES | 11-03 | FEB 20, 1981 | 21 |
| 400 SERIES FOR SCOPES/COMP HANDLE ASSEMBLY PART NUMBERS | 11-04 | MAR 6, 1981 | 14 |
| 442 BNC RELIABILITY | 11-03 | FEB 20, 1981 | 21 |
| 464, 465/B, 466, 475/A TRIGGER I.C. REPLACEMENT | 11-07 | APR 24, 1981 | 15 |
| 464/466 TIMING ERROR IN 10X MAGNIFICATION | 11-03 | FEB 20, 1981 | 22 |
| 468 BREAKING CABLES | 11-12 | JUL 03, 1981 | 16 |
| 468 MICROPROCESSOR LOCKUP OR INTERMITTENT OPERATION | 11-01 | JAN 16, 1981 | 17 |
| 468 MICROPROCESSOR LOCKUP | 11-08 | MAY 8, 1981 | 17 |

1 SEPTEMBER 1981

WIZARDS WORKSHOP INDEX

PORTABLES

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| 468 REMOVAL AND REPLACEMENT OF U456 (A/D CONVERTER CHIP) | 11-07 | APR 24, 1981 | 16 |
| 468 REPLACEMENT OF 74LS377'S THAT DRIVE L.E.D.'S | 11-07 | APR 24, 1981 | 18 |
| 468 SERVICE UPDATE PLAN #3002 | 11-06 | APR 10, 1981 | 19 |
| 468, MICROPROCESSOR LOCK-UP | 11-07 | APR 24, 1981 | 15 |
| 485 HF ADJUSTMENTS | 11-09 | MAY 22, 1981 | 8 |
| 03-261 MAINTENANCE INFORMATION | 11-13 | JUL 17, 1981 | 25 |
| PORTABLES, T900 SERIES RESPONSIBILITY LIST | 11-13 | JUL 17, 1981 | 26 |
| T912 F702 VALUE CHANGE | 11-07 | APR 24, 1981 | 15 |
| T912 STORAGE CIRCUIT, Q942 FAILURE UPDATE | 11-03 | FEB 20, 1981 | 23 |

TELEQUIPMENT

| | | | |
|--------------------------------|-------|--------------|----|
| TELEQUIPMENT SUPPORT QUESTIONS | 11-07 | APR 24, 1981 | 18 |
|--------------------------------|-------|--------------|----|

WIZARDS WORKSHOP INDEX

INFORMATION DISPLAY DIVISION

INFORMATION DISPLAY DIVISION

| TITLE | ISSUE | DATE | PAGE |
|---|-------|--------------|------|
| 4014/15/16 CUSTOM MOD INTERACTIVE BUFFER MODIFICATION | 11-02 | JAN 30, 1981 | 28 |
| 4014/4015 NEW SHIPPING CARTONS | 11-02 | JAN 30, 1981 | 28 |
| 4015/14 NEW SHIPPING CARTONS | 11-02 | JAN 30, 1981 | 28 |
| 4016-1, 4024/25/27 KEYBOARD CABINET ASSEMBLY | 11-05 | MAR 27, 1981 | 20 |
| 4016/GMA125 CRT RETURNS | 11-10 | JUN 05, 1981 | 24 |
| 4024/25 MOTOROLA MONITOR CHANGES | 11-09 | MAY 22, 1981 | 9 |
| 4024/25/27, 4016-1 KEYBOARD CABINET ASSEMBLY | 11-05 | MAR 27, 1981 | 20 |
| 4027 INTERFACING WITH HARDCOPIERS | 11-08 | MAY 8, 1981 | 21 |
| 4050 SERIES MAG TAPE DRIVE CABLE | 11-13 | JUL 17, 1981 | 28 |
| 4051 CPU BOARD TO EXTENDED MEMORY BOARD CABLE INSTALLATION | 11-09 | MAY 22, 1981 | 12 |
| 4052/4054 MAS/ALU CIRCUIT BOARD MODIFICATION #M40036 | 11-04 | MAR 6, 1981 | 15 |
| 4052/4054 VERSION 4.3 FIRMWARE | 11-09 | MAY 22, 1981 | 13 |
| 4052/4054 VERSION 4.3 FIRMWARE | 11-12 | JUL 03, 1981 | 18 |
| 4052/54. VERIFICATION OF COM CLOCK MOD #M40828 | 11-05 | MAR 27, 1981 | 20 |
| 4054 LINE FILTER MODIFICATION #41521 | 11-07 | APR 24, 1981 | 19 |
| 4054 POWER SWITCH MODIFICATION #M41675 | 11-01 | JAN 16, 1981 | 18 |
| 4054/52 MAS/ALU CIRCUIT BOARD MODIFICATION #M40036 O | 11-04 | MAR 6, 1981 | 15 |
| 4054/52 VERIFICATION OF COM CLOCK MOD #M40828 | 11-05 | MAR 27, 1981 | 20 |
| 4081 MANUAL PART NUMBERS - REF. PULL-OUT | 11-06 | APR 10, 1981 | B-1 |
| 4611/12 NIB BOUNCE CORRECTION | 11-10 | JUN 05, 1981 | 25 |
| 4611/12 NIB BOUNCE | 11-08 | MAY 8, 1981 | 21 |
| 4611/12 SHORT BETWEEN THE BACKING ELECTRODES | 11-08 | MAY 8, 1981 | 22 |
| 4611/4612 COPY BELT RELIABILITY | 11-10 | JUN 05, 1981 | 24 |
| 4611/4612 LINES IN COPY | 11-04 | MAR 6, 1981 | 15 |
| 4611/4612 PAPER ROLL PRECAUTION | 11-07 | APR 24, 1981 | 19 |
| 4611/4612 PRE-SHIPMENT PREPARATION | 11-04 | MAR 6, 1981 | 16 |
| 4611/4612: HUMIDITY EFFECT ON COPY QUALITY | 11-13 | JUL 17, 1981 | 28 |
| 4612 AGC PILOT CHANGE | 11-08 | MAY 8, 1981 | 23 |
| 4612/11 LINES IN COPY | 11-04 | MAR 6, 1981 | 15 |
| 4612/11 PRE-SHIPMENT PREPARATION | 11-04 | MAR 6, 1981 | 16 |

1 SEPTEMBER 1981

WIZARDS WORKSHOP INDEX

INFORMATION DISPLAY DIVISION

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| 4632 INTERMITTENT TIMING BOARD | 11-05 | MAR 27, 1981 | 21 |
| 4633A PARTIAL IMPLEMENTATION OF MODIFICATION 40750 | 11-07 | APR 24, 1981 | 20 |
| 4633A/4634 CONVEYOR TENSION CHANGED | 11-04 | MAR 6, 1981 | 17 |
| 4634/4633A CONVEYOR TENSION CHANGED | 11-04 | MAR 6, 1981 | 17 |
| 463X ADHESIVE FOR LIGHT SEALS | 11-10 | JUN 05, 1981 | 25 |
| 463X BELT LOT IDENTIFICATION | 11-08 | MAY 8, 1981 | 24 |
| 463X CUTTER CLUTCH CHATTER | 11-06 | APR 10, 1981 | 21 |
| 463X MOTOR AND TACH BRUSH CHANGE #41203 | 11-04 | MAR 6, 1981 | 17 |
| 463X PROCESSOR BAFFLE REMOVED | 11-09 | MAY 22, 1981 | 15 |
| 4642 APPLICATION COMPATIBILITY | 11-09 | MAY 22, 1981 | 16 |
| 4642 CONTROL CHARACTER HANDLER | 11-09 | MAY 22, 1981 | 20 |
| 4642 DCI DETECTION | 11-04 | MAR 6, 1981 | 18 |
| 4642 JUMPER CONFIGURATIONS | 11-06 | APR 10, 1981 | 22 |
| 4642 JUMPER CONFIGURATIONS (ARTICLE REPEAT) | 11-07 | APR 24, 1981 | 21 |
| 4662 FRONT PANEL EXTENDER CABLE | 11-12 | JUL 03, 1981 | 21 |
| 4662 PLATEN SHIMS | 11-04 | MAR 6, 1981 | 18 |
| 4663 GPIB HANGS WHEN LOADED DOWN | 11-03 | FEB 20, 1981 | 24 |
| 4663 MOTOR/PEN DRIVE BOARD UPDATE | 11-02 | JAN 30, 1981 | 29 |
| 4663 PEN CARRIAGE HEIGHT GAUGE | 11-06 | APR 10, 1981 | 26 |
| 4663 PEN HOLDER BATCH PROBLEM | 11-08 | MAY 8, 1981 | 24 |
| 4663 PLATEN CLEANING PROCEDURE, REV | 11-06 | APR 10, 1981 | 27 |
| 4663 ROM OVERLAY, EXCHANGE PROCEDURES | 11-06 | APR 10, 1981 | 28 |
| 4663 SOFT START POWER SUPPLY | 11-01 | JAN 16, 1981 | 19 |
| 4663 VISCOUS OIL DAMPER | 11-03 | FEB 20, 1981 | 25 |
| 4905 WANG30 HARD DISK DRIVE PRTS CROSS REF. PULL-OUT | 11-04 | MAR 6, 1981 | A-1 |
| 4905/4907 SHUGART DISK DRIVE NEW CIRCUIT BOARD NEW WIRE SET | 11-05 | MAR 27, 1981 | 21 |
| 4907 IMPROPERLY STRAPPED DISK DRIVES MAY DAMAGE FILES | 11-07 | APR 24, 1981 | 25 |
| 4907/4905 SHUGART DISK DRIVE NEW CIRCUIT BOARD NEW WIRE SET | 11-05 | MAR 27, 1981 | 21 |

1 SEPTEMBER 1981

PAGE 15

WIZARDS WORKSHOP INDEX

MEASUREMENT DISPLAY

| TITLE | ISSUE | DATE | PAGE |
|---|-------|--------------|------|
| 618 MOD DM, GMA125 MOD KA POWER SUPPLY CABLE | 11-04 | MAR 6, 1981 | 8 |
| 618 OPT 30 CABLE (012-0924-00) | 11-06 | APR 10, 1981 | 20 |
| 634 : YOKE DRIVER BOARD MODIFICATION #39769 | 11-11 | JUN 19, 1981 | 8 |
| 634 : YOKE DRIVER BOARD MODIFICATION #36631 | 11-11 | JUN 19, 1981 | 5 |
| 634 GEOMETRY SPECIFICATIONS | 11-04 | MAR 6, 1981 | 8 |
| IDD MAINTENANCE AGREEMENT PROMOTION SERVICE PLAN 12/14/79 CORRECTION | 11-01 | JAN 16, 1981 | 18 |
| IDD PRODUCTS POWER LINE REQUIREMENTS AND ENVIRONMENTAL IMPACT- REF. PULL-OUT | 11-09 | MAY 22, 1981 | B-1 |
| MEASUREMENT DISPLAY MODIFIED PRODUCTS | 11-02 | JAN 30, 1981 | 16 |

WIZARDS WORKSHOP INDEX

DATA COMMUNICATIONS

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| 401X TELETYPE PORT INTERFACE-REF. PULL-OUT | 11-02 | JAN 30, 1981 | |
| RS232 CABLES | 11-03 | FEB 20, 1981 | 26 |

LABORATORY INSTRUMENT DIVISION

MICROCOMPUTER DEVELOPMENT PRODUCTS

| | | | |
|--|-------|--------------|----|
| 8001/8002A 8048 EMULATOR DUMP & RESTORE PROM MODIFICATION | 11-02 | JAN 30, 1981 | 31 |
| 8001/8002A DOS ERROR 66 WITH THE Z80 EMULATOR | 11-02 | JAN 30, 1981 | 31 |
| 8002 MEMORY BOARDS | 11-07 | APR 24, 1981 | 26 |
| 8002A/8001 DOS ERROR 66 WITH THE Z80 EMULATOR | 11-02 | JAN 30, 1981 | 31 |
| 8022 PROTOTYPE CONTROL PROBE CALIBRATION PROCEDURE ERROR | 11-04 | MAR 6, 1981 | 19 |
| 8550 EMULATOR COMPATIBILITY HARDWARE MODIFICATIONS | 11-02 | JAN 30, 1981 | 32 |
| 8550 PROGRAMMABLE FEATURES OF AUXILIARY AND LINE PRINTER PORTS | 11-02 | JAN 30, 1981 | 36 |
| 8550 QUME DRIVE INSTALLATION | 11-03 | FEB 20, 1981 | 32 |
| B-PHASE MICROLAB AND PERSONALITY CARD COMPATIBILITY | 11-10 | JUN 05, 1981 | 26 |
| EMULATORS ARE PRODUCTS | 11-03 | FEB 20, 1981 | 29 |
| F8 EMULATOR MEMORY MAPPING CAPABILITIES | 11-06 | APR 10, 1981 | 29 |

SEMICONDUCTOR TEST SYSTEMS

| | | | |
|---|-------|--------------|----|
| 1800 SERIES TEST STATION WIRE LIST CORRECTION | 11-13 | JUL 17, 1981 | 31 |
| BUS, CONDUCTOR PN INCORRECT | 11-13 | JUL 17, 1981 | 29 |
| PRAM CLOCK PULSE/ERROR CONTROL IMPROVEMENT | 11-13 | JUL 17, 1981 | 29 |
| S-3200 "R MASK" SIGNAL TIMING, 2942/SIGNAL BUFFER MASK UNIT | 11-08 | MAY 8, 1981 | 28 |
| S-3200 1804 MANUAL | 11-08 | MAY 8, 1981 | 25 |

1 SEPTEMBER 1981

WIZARDS WORKSHOP INDEX

SEMICONDUCTOR TEST SYSTEMS

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| S-3200 1835 DUAL STATION MULTIPLEXER MANUAL | 11-03 | MAY 8, 1981 | 25 |
| S-3200 CF1, POWER-UP, DIODE CHANGE | 11-04 | MAR 6, 1981 | 20 |
| S-3200 CYCLE.EDT (FO80) | 11-03 | MAY 8, 1981 | 25 |
| S-3200 DIODE CHANGES, 1140A, 1140A651F, DUAL STATIONS, REMOTES | 11-04 | MAR 6, 1981 | 23 |
| S-3200 ELECTROGLAS PROBER INTERFACES (MANUALS) | 11-09 | MAY 22, 1981 | 21 |
| S-3200 FANS | 11-08 | MAY 8, 1981 | 26 |
| S-3200 FICM4.EDT: VDT | 11-08 | MAY 8, 1981 | 26 |
| S-3200 IMPEDANCE MISMATCH, 1140A651F (CORRECTION) | 11-05 | MAR 27, 1981 | 29 |
| S-3200 IS2 (1140A651F) PROGRAMMABLE CURRENT SUPPLY CABLES | 11-07 | APR 24, 1981 | 27 |
| S-3200 MANUALS | 11-06 | APR 10, 1981 | 30 |
| S-3200 MATRIX. EDT (FO60) | 11-08 | MAY 8, 1981 | 27 |
| S-3200 NEW MC-3 TEST FIXTURE CIRCUIT BOARD ASSY | 11-04 | MAR 6, 1981 | 24 |
| S-3200 PMC SWITCHING POWER SUPPLIES OUTPUT RIPPLE | 11-03 | FEB 20, 1981 | 34 |
| S-3200 R1330651L, CONNECTOR: 131-0294-00 | 11-07 | APR 24, 1981 | 27 |
| S-3200 R2942 CROSS TALK | 11-04 | MAR 6, 1981 | 27 |
| S-3200 REED CHANGE, DC SUBSYSTEM AMPLIFIER CIRCUIT BOARDS | 11-04 | MAR 6, 1981 | 26 |
| S-3200 SM-1 OPTION TEST (CABLES) | 11-07 | APR 24, 1981 | 28 |
| S-3200 SYNCHRONIZED 2942/PRAM OPERATION | 11-05 | MAR 27, 1981 | 29 |
| S-3200 TYPE D SOCKET CARD PART NUMBER | 11-12 | JUL 03, 1981 | 22 |
| S-3200: 1140 TYPE PROGRAMMABLE POWER SUPPLY, INTERMITTENTS | 11-12 | JUL 03, 1981 | 23 |
| S-3200: POGO RING CLEANER | 11-12 | JUL 03, 1981 | 22 |
| S-3455 ERROR CONTROL CARD STRAPPING | 11-09 | MAY 22, 1981 | 23 |
| S3200: R1340 EXTENDER BOARD IMPROVED | 11-13 | JUL 17, 1981 | 30 |
| SECTOR CARD CHAINING MOD | 11-12 | JUL 03, 1981 | 22 |
| TEKTEST III VERSION 4.00 | 11-13 | JUL 17, 1981 | 30 |

WIZARDS WORKSHOP INDEX

SIGNAL PROCESSING SYSTEMS

| TITLE | ISSUE | DATE | PAGE |
|--|-------|--------------|------|
| 7912AD UNDERRATED CAPACITORS | 11-05 | MAR 27, 1981 | 30 |
| 7912AD: 040-0959-00 CHANGES REVISION LEVEL OF TWO BOARDS | 11-07 | APR 24, 1981 | 28 |
| 7912AD: ADD. INFO. ON W2 ARTICLE ISSUE 11-05 " 7912AD UNDERRATED CAP." | 11-13 | JUL 17, 1981 | 31 |
| 7912AD: CONN. TO/FROM PWR SUP CAN BE REVERSED CAUSING CIR. DAMAGE | 11-13 | JUL 17, 1981 | 32 |
| 7912AD: IMPROVED RELIABILITY OF THE POWER SUPPLY | 11-13 | JUL 17, 1981 | 33 |
| 7912AD: IMPROVED RELIABILITY OF THE FAN CIRCUIT | 11-13 | JUL 17, 1981 | 32 |
| 7912AD: IMPROVED RELIABILITY OF THE +365 VOLT POWER SUPPLY | 11-13 | JUL 17, 1981 | 36 |
| 7912AD: INCREASE AIR CIRCULATION IN THE POWER AND THE INSTRUMENT | 11-13 | JUL 17, 1981 | 37 |
| 7912AD: PREVENT DAMAGE TO TRANSISTORS WHEN CHANGING PARTS | 11-13 | JUL 17, 1981 | 37 |
| 7912AD: TO MAKE ALL POWER SUPPLIES INTERCHANGABLE | 11-13 | JUL 17, 1981 | 38 |
| 7912AD: UPDATING THE POWER SUPPLY TO THE MOST RECENT VERSION | 11-13 | JUL 17, 1981 | 42 |
| WPXXX PACKAGES HAVE A NEW IMPROVED EXTENDER BRACKET | 11-02 | JAN 30, 1981 | 39 |

WIZARDS WORKSHOP INDEX

COMMUNICATIONS DIVISION (1980)

| TITLE | ISSUE | DATE | PAGE |
|--------------------------------------|-------|--------------|------|
| 1330 PART PROBLEM, 156-1309-00 | 11-07 | APR 24, 1981 | 13 |
| KEY PART NUMBERS (ANG. BULLETIN #11) | 11-04 | MAR 6, 1981 | 29 |