

Tektronix[®]
COMMITTED TO EXCELLENCE



COMBINATION EDITION

Wizards Workshop

* ALL SERVICE QUESTIONS FROM EUROPE, MIDDLE EAST, *
* AND AFRICA SHOULD BE ADDRESSED TO THE EUROPEAN *
* MARKETING CENTER SERVICE GROUP IN THE NETHERLANDS. *

TEKTRONIX INTERNAL USE ONLY

PUBLISHED BY SERVICE ADMIN SUPPORT
56-037 EXT, 8939 MERLO

JUNE 1981

WIZARDS WORKSHOP MASTER INDEX

JANUARY 1977 - DECEMBER 1980

NOTE: THIS INDEX REPLACES MAY 1980 EDITION.

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
ADMINISTRATIVE SUPPORT.	1
GENERAL	2
INFORMATION DISPLAY DIVISION	
MEASUREMENT DISPLAY PRODUCTS	11
TEST AND MEASUREMENT PRODUCTS GENERAL	12
LABORATORY INSTRUMENT DIVISION	
BENCHTOP SEMICONDUCTOR TEST SYSTEMS.	14
SAMPLING PRODUCTS	14
TM500	16
5000 SERIES	19
7000 SERIES	20
COMMUNICATIONS DIVISION	
MEDICAL PRODUCTS	23
SPECTRUM ANALYZERS	27
TELEVISION PRODUCTS	29
1980	37
SERVICE INSTRUMENT DIVISION	
ACCESSORIES	38
DIGITAL SERVICE INSTRUMENTS	40
DATA COMMUNICATION ANALYZERS	40
LOGIC ANALYZERS	41
PORTABLES	43
TELEQUIPMENT	51

TABLE OF CONTENTS (CONTINUED)

<u>SECTION</u>	<u>PAGE</u>
INFORMATION DISPLAY DIVISION	52
DATA COMMUNICATIONS	71
LABORATORY INSTRUMENT DIVISION	
MICROCOMPUTER DEVELOPMENT PRODUCTS	71
SEMICONDUCTOR TEST SYSTEMS	74
SIGNAL PROCESSING SYSTEMS	79
COMMUNICATIONS DIVISION	
1980	81



WIZARDS WORKSHOP INDEX

ADMINISTRATIVE SUPPORT

TITLE	ISSUE	DATE	PAGE
"DOA", DEFINITION	10-11	MAY 30,1980	9
4014, 4014-1, 4015, 4015-1 MAINTENANCE AGREEMENT	10-17	AUG 22,1980	4
ACTIVITY CODE CHANGE	10-18	SEPT 5,1980	4
BLANKET REPAIR PURCHASE ORDERS	10-19	SEPT 19,1980	5
COMPONENT FAILURE REPORTING	10-10	MAY 16,1980	3
IN-HOUSE SERVICE RECORDS (ACTIVITY CODE 01)	10-07	APR 4,1980	4
MAINTENANCE AGREEMENT PRICING	10-07	APR 4,1980	4
MAINTENANCE AGREEMENT ADMINISTRATION	10-21	OCT 17,1980	10
MAINTENANCE AGREEMENT ADMINISTRATION	10-23	NOV 21,1980	4
MORE ON THE NEW SERVICE RECORDS	10-03	FEB 8,1980	12
NEW SERVICE RECORDS	10-01	JAN 11,1980	9
NEW SERVICE RECORDS - U.S. DOMESTIC SERVICE ONLY	10-04	FEB 22,1980	5
NEW SERVICE RECORDS	10-05	MAR 7,1980	8
NEW SERVICE RECORDS	10-06	MAR 21,1980	7
NEW SERVICE RECORDS(CHANGES MADE)	10-11	MAY 30,1980	10
NON-PART RELATED FAILURE CODES	10-10	MAY 16,1980	3
REPORT DISTRIBUTION	10-16	AUG 8,1980	4
REPORT DISTRIBUTION	10-22	OCT 31,1980	4
SERVICE RECORD PROCEDURES (REFERENCE PULL-OUT)	10-07	APR 4,1980	A-1
SERVICE RECORD REPORTING - MODULE EXCHANGE COPY	10-08	APR 18,1980	4
SERVICE RECORD PROCEDURES	10-12	JUNE 13,1980	5
SERVICE RECORD PROCESSING	10-13	JUNE 27,1980	8
SERVICE RECORD/TIME DISTRIBUTION SHEETS	10-20	OCT 3,1980	3
SERVICE RECORD PROCEDURES - FAILURES CODES (REF. PULL-OUT)	10-24	DEC 12,1980	A-1

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
067-0878-00 "RS-232 SELF TEST ADAPTER" - CROSSTALK	10-18	SEPT 5,1980	5
118-0588-00 INCORRECT VALUE	9-22	NOV 16,1979	6
118-0802-00 MIXED STOCK--PURGE	10-25	DEC 19,1980	4
131-0679-02, BNC CONNECTORS	9-13	JUL 13,1979	5
131-0847-00 REDESIGNED	8-23	JUL 21,1978	9
136-0220-00 INFORMATION ONLY (TRANSISTOR'S SOCKETS)	9-17	SEP 7,1979	7
148-0034-XX RELAYS	7-18	AUG 12,1977	9
151-0150-00 TRANSISTOR, MOTOROLA MANUFACTURED DEFECTIVE CODE DATES	7-11	MAY 27,1977	7
151-0188-00, DEFECTIVE	7-24	OCT 7,1977	4
151-0190-00 DEFECTIVE STOCK	10-10	MAY 16,1980	1
151-0220-00 INFORMATION ONLY	9-19	OCT 5,1979	4
151-0225-00 DEFECTIVE DATE CODE -- "TELEDYNE"	7-30	DEC 9,1977	8
151-0239-00 OUT OF SPECS "FAIRCHILD BRAND ONLY"	7-30	DEC 9,1977	8
151-0254-00 LEAD CONFIGURATION CHANGE	7-19	AUG 19,1977	6
151-0373-00 (PNP), 151-0349-00 (NPN) MARKED WRONG--MOTOROLA BRAND ONLY	7-18	AUG 12,1977	6
151-0402-00 LEAD CONFIGURATION	9-17	SEP 7,1979	7
151-1036-00 MIXED STOCK	10-03	FEB 8,1980	3
151-1042-00 DEFECTIVE DATE CODE - "TELEDYNE"	9-06	APR 6,1979	8
152-0141-02 MIXED STOCK	10-18	SEPT 5,1980	5
152-0141-02 MIXED STOCK	9-09	MAY 18,1979	3
152-0153-00 SILICON DIODE, FAIRCHILD MANUFACTURED, DISCONTINUED	7-11	MAY 27,1977	7
152-0153-00/-02 DEFECTIVE DATE CODE	9-08	MAR 4,1979	13
152-0293-00 - DEFECTIVE PLATING	9-12	JUN 29,1979	3
152-0429-00 WRONG PARTS	9-09	MAY 18,1979	4
152-0574-00 MIXED STOCK - "PURGE"	10-18	SEPT 5,1980	6
152-0585-00 POOR RELIABILITY	9-15	AUG 10,1979	9
153-0610-02 - RAW PART CHANGE (INFORMATION ONLY)	9-14	JUL 27,1979	7
155-0006-01 DEFECTIVE DATE CODES	9-22	NOV 16,1979	6
155-0049-01 DEFECTIVE DATE CODE	7-18	AUG 12,1977	6
155-0067-02 DEFECTIVE LOT DATE	9-20	OCT 19,1979	3
155-0067-02 MIXED STOCK	9-14	JUL 27,1979	7
155-0123-00 DEFECTIVE DATE CODE	7-18	AUG 12,1977	6
155-0195-00 - IMPROPERLY MARKED	9-12	JUN 29,1979	3
156-0021-00 -- DEFECTIVE DATE CODE -- "PURGE"	10-18	SEPT 5,1980	6
156-0047-00 MIXED STOCK - SIGNETICS	9-05	MAR 16,1979	7
156-0058-00 MIXED STOCK	9-05	MAR 16,1979	7
156-0067-00 COMPONENT FAILURE	8-15	MAY 12,1978	6
156-0087-00 MIXED STOCK	9-08	MAR 4,1979	13
156-0118-00 - DISQUALIFIED VENDOR	9-12	JUN 29,1979	3
156-0118-01 - DISQUALIFIED VENDOR	9-14	JUL 27,1979	8
156-0141-00 - INCORRECT OUTPUTS	9-14	JUL 27,1979	8

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
156-0177-00/01 DEFECTIVE DATE CODE-MOTOROLA	7-22	SEPT 23,1977	4
156-0182-00 DEFECTIVE DATE CODE "PURGE"	10-18	SEPT 5,1980	6
156-0182-00 DEFECTIVE DATE CODE "MOTOROLA"	8-15	MAY 12,1978	6
156-0182-00 WRONG PART NUMBER, MOTOROLA	7-14	JULY 8,1977	19
156-0218-00/01 DEFECTIVE DATE CODE (FAIRCHILD)	9-05	MAR 16,1979	7
156-0326-00 MIXED STOCK	9-04	MAR 2,1979	7
156-0328-00 DEFECTIVE DATE CODE	9-08	MAR 4,1979	13
156-0349-03 CHANGE OF MARKING (INFORMATION)	9-05	MAR 16,1979	7
156-0385-00/01 MIXED STOCK	9-09	MAY 18,1979	4
156-0410-00 DEFECTIVE DATE CODES	9-20	OCT 19,1979	3
156-0412-00 DEFECTIVE DATE CODE	9-22	NOV 16,1979	6
156-0530-00 MIXED STOCK	10-01	JAN 11,1980	8
156-0733-00 DEFECTIVE DATE CODE	9-21	NOV 2,1979	6
156-0788-00 OUTPUT IS OPEN	9-19	OCT 5,1979	4
156-0801-00 MIXED STOCK	9-06	APR 6,1979	8
156-0874-00 DEFECTIVE DATE CODE "T.I. BRAND"	8-15	MAY 12,1978	6
156-0916-00 INCORRECT PART	9-17	SEP 7,1979	8
156-0945-00 DEFECTIVE PARTS	9-16	AUG 24,1979	5
156-0956-00 & 01 DEFECTIVE DATE CODE - TEXAS INSTRUMENT'S BRAND	9-03	FEB 16,1979	7
156-0972-00 DEFECTIVE DATE CODE "INTEL BRAND"	8-15	MAY 12,1978	7
156-0982-00 - MIXED STOCK "PURGE"	10-18	SEPT 5,1980	6
156-0987-00 DEFECTIVE DATE CODE	9-09	MAY 18,1979	4
156-0998-00 DEFECTIVE DATE CODES - "SIGNETICS"	9-06	APR 6,1979	8
156-1059-00 MIXED STOCK	9-14	JUL 27,1979	8
156-1068-00 DEFECTIVE DATE CODE - MOTOROLA	9-04	MAR 2,1979	7
156-1097-00 MIXED STOCK	9-14	JUL 27,1979	8
156-1243-00 - MARKING ERRORS	9-14	JUL 27,1979	8
156-1254-00 DEFECTIVE DATE CODE	9-15	AUG 10,1979	9
156-1336-01 DEFECTIVE DATA CODE--PURGE	10-25	DEC 19,1980	4
158-0151-00 MIXED STOCK "PURGE"	10-22	OCT 31,1980	3
160-0117-00 INCORRECT MARKINGS AND PARTS	9-09	MAY 18,1979	4
211-0256-00 MIXED STOCK	9-09	MAY 18,1979	5
212-0517-00 DAMAGED THREADS	9-09	MAY 18,1979	5
260-0742-00 MIXED STOCK	9-09	MAY 18,1979	5
281-0093-00 MIXED STOCK	9-05	MAR 16,1979	7
281-0178-00/281-0182-00 MIXED STOCK	9-05	MAR 16,1979	8
281-0593-00 INCORRECT PARTS	9-17	SEP 7,1979	8
283-0299-00 MIXED STOCK	9-05	MAR 16,1979	8
283-XXXX-XX DEFECTIVE DATE CODES - "SPRAGUE"	9-09	MAY 18,1979	5
285-0938-00:DEFECTIVE DATE CODES	10-08	APR 18,1980	2
285-0938-00 DEFECTIVE DATE CODES "PURGE"	10-13	JUNE 27,1980	6
307-0387-00 MIXED STOCK	9-12	JUN 29,1979	3

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
308-0213-00 MARKINGS INCORRECT	10-03	FEB 8,1980	4
311-0601-00 INCORRECT VALUE	9-24	DEC 14,1979	8
311-1162-00 DEFECTIVE DATE CODE	9-05	MAR 16,1979	8
311-1224-00 DEFECTIVE DATE CODE	9-19	OCT 5,1979	4
311-1817-00 DEFECTIVE DATE CODE	9-05	MAR 16,1979	8
311-1915-00 DEFECTIVE DATE CODE	10-09	MAY 2,1980	3
321-0086-00 INCORRECT VALUE AND COLOR CODE	9-05	MAR 16,1979	8
321-0126-03 MIXED STOCK	10-12	JUNE 13,1980	4
321-0236-00 RESISTOR MARKED WRONG	7-16	JULY 29,1977	4
321-0338-00 AND 321-0242-00/08 MIXED STOCK "PURGE"	10-13	JUNE 27,1980	7
321-0983-00 INCORRECT MARKINGS	9-21	NOV 2,1979	6
322-0510-00 TEMPERATURE SENSITIVE	9-22	NOV 16,1979	6
366-1433-00 - INCORRECT ALIGNMENT	9-12	JUN 29,1979	3
382-0299-00 MIXED STOCK	9-05	MAR 16,1979	8
4016/GMA125 CRT PACKAGING	10-15	JULY 25,1980	8
832/833 - RE-EMPHASIS OF VIDEO TAPES	9-23	NOV 30,1979	3
ACTIVITY CODE 18 "PRODUCT FIELD INSTALLED"	8-26	SEPT 1,1978	8
ADM	10-16	AUG 8,1980	4
AEROSOL CLEANERS	7-09	APR 29,1977	5
ANNOUNCEMENT OF CALIBRATION FIXTURES CATALOG	10-08	APR 18,1980	2
ANNOUNCEMENT OF TRAINING PACKAGES (CORRECTION)	8-11	APR 14,1978	3
ANNOUNCEMENT OF TRAINING PACKAGES (CORRECTION TO THIS ARTICLE IN ISSUE 8-11)	8-09	MAR 31,1978	4
ANTI-STATIC BENCH TOP COVER - BLACK CONDUCTIVE FOAM	7-03	FEB 4,1977	4
ANTI-STATIC SHIPPING MATERIAL AVAILABLE	8-03	FEB 3,1978	4
AUDIOTAPES, VIDEOTAPES, AND TRAINING PACKAGES AVAILABLE	8-13	APR 28,1978	6
AVOID JAMMED AND RUINED AUDIO CASSETTES	7-14	JULY 8,1977	4
AVX BRAND CERAMIC GLASS ENCAPSULATED CAPACITORS	8-03	FEB 3,1978	4
BATTERY CARE AND MAINTENANCE	10-14	JULY 11,1980	2
BEAVERTON PRODUCT UPDATE STATUS	10-22	OCT 31,1980	2
BERG CONNECTOR CRIMP TOOLS	10-23	NOV 21,1980	2
CAL COMP FLOPPY DISC VIDEO TAPE AVAILABLE	7-10	MAY 13,1977	5
CAM SWITCH REPAIR MANUAL (REFERENCE PULL-OUT)	10-23	NOV 21,1980	E-1
CARE AND CLEANING OF SOLDERING IRONS AND IRON-CLAD TIPS	9-22	NOV 16,1979	1
CERAMIC THICK FILM ENCAPSULATION MATERIAL CHANGE	7-10	MAY 13,1977	5
CHARGING NICD BATTERIES	7-01	JAN 14,1977	5
CLEANING NOISY POTENTIOMETERS	10-17	AUG 22,1980	2
CLEANING SWITCHES	8-28	SEPT 29,1978	4
COLOR CONCENTRATION REDUCED IN HARMONICS	7-18	AUG 12,1977	4
CRT FAILURE INFORMATION	10-13	JUNE 27,1980	3
CRT NECK PINS	7-05	MAR 4,1977	9
CRT PART NUMBERS IN GENERAL	7-06	MAR 18,1977	4

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
CRT REMOVAL PRECAUTIONS	7-28	NOV 18,1977	3
CRTS, REPORTING DOA	7-28	NOV 18,1977	3
DATA SHEETS & CAL FIXTURES FOR MICROFICHE	10-02	JAN 25,1980	4
DEC EQUIPMENT RACKS	8-22	JUL 7,1978	5
DIGITAL STORAGE CONCEPTS	9-22	NOV 16,1979	2
EMC SERVICE GROUP (REFERENCE PULL-OUT)	9-24	DEC 14,1979	A-1
EUROPEAN MANUFACTURING	10-04	FEB 22,1980	1
EXCHANGE/REPAIR & RETURN	7-01	JAN 14,1977	5
FAILURE CODES - ALPHABETICAL LISTING	10-13	JUNE 27,1980	4
FAILURE MODE OF FIELD REJECTS ANALYZED	7-07	APR 1,1977	8
FAILURE REPORTING	9-17	SEPT 7,1979	9
FAILURE REPORTING	7-10	MAY 13,1977	6
FAILURE REPORTING (PULLOUT REFERENCE)	7-19	AUG 19,1977	16
FAIRCHILD 152-0061-00 "WRONG PART"	7-26	OCT 28,1977	4
FIELD FAILURE REPORTING	8-05	MAR 3,1978	5
FIELD FAILURE REPORTS ON TEKTRONIX INTEGRATED CIRCUITS	8-13	APR 28,1978	8
FIELD PRODUCT UPDATES	10-15	JULY 25,1980	2
FLUKE 5101B TAPES	10-21	OCT 17,1980	3
FLUOROCARBON SPRAY PAINT	7-26	OCT 28,1977	4
GMA125/4016 CRT PACKAGING	10-15	JULY 25,1980	8
GPIB CABLES, NEW PART NUMBERS	8-33	DEC 8,1978	6
GUERNSEY MODIFICATIONS, JANUARY & FEBRUARY 1980	10-09	MAY 2,1980	2
HARMONICA TERMINAL CONNECTOR HOLDERS	7-26	OCT 28,1977	5
HIGH RESISTANCE MEASUREMENT TECHNIQUE	10-21	OCT 17,1980	4
HISTORY STATUS MICROFICHE REPORT BY PRODUCT	7-15	JULY 22,1977	5
IC PULLER	8-27	SEPT 15,1978	4
IC SOCKET RELIABILITY PROBLEM	8-13	APR 28,1978	8
INFORMATION SYSTEMS-TEKNETTING SERVICE RECORDS	8-21	JUN 30,1978	5
INFORMATION SYSTEMS-CODE 18	8-20	JUN 23,1978	5
INFORMATION SYSTEMS-MORE ON SERVICE RECORDS	8-19	JUN 9,1978	5
INFORMATION SYSTEMS-FILLING OUT SERVICE RECORDS	8-18	JUN 2,1978	4
INFORMATION SYSTEMS-WIZARD'S WORKSHOP SPLIT	8-17	MAY 26,1978	3
INFORMATION SYSTEMS-COMPONENT FAILURE ANALYSIS	8-25	AUG 18,1978	3
INFORMATION SYSTEMS-INTERIM MIS	8-24	AUG 4,1978	5
INFORMATION SYSTEMS-MAINTENANCE AGREEMENTS	8-27	SEPT 15,1978	4
INFORMATION SYSTEMS-SQI	8-34	DEC 22,1978	4
INFORMATION SYSTEMS-EXCHANGE PROGRAMS	8-22	JUL 7,1978	5
INFORMATION SYSTEMS-MAINTENANCE AGREEMENT TRANSMITTAL FORMS	8-32	NOV 24,1978	5
INFORMATION SYSTEMS-TDS & SERVICE RECORDS	8-16	MAY 19,1978	5
INFORMATION SYSTEMS CORRECTION	8-20	JUN 23,1978	6
INITIAL MANUAL DISTRIBUTION	8-30	OCT 27,1978	7
INSTALLATION REPORT	10-24	DEC 12,1980	1

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
INSTALLATION AND REPAIR OF NON-CORPORATE DOCUMENTED MODIFICATIONS	8-25	AUG 18,1978	4
INSTRUCTION MANUAL CORRECTION REQUEST FORMS CHANGES	8-34	DEC 22,1978	4
INTERMITTENT I.C. SOCKETS (ALL TYPES)	10-03	FEB 8,1980	3
INTERNATIONAL POWER CORD & PLUG OPTIONS - GCS PRODUCTS	10-13	JUNE 27,1980	5
INTERNATIONAL SYSTEM DOWN ORDERING PROCEDURE	9-12	JUN 29,1979	8
INVENTORY CONTROL TAG	10-13	JUNE 27,1980	6
INVOICING PROCEDURES	8-28	SEPT 29,1978	7
JET TRAINING PACKAGE	8-23	JUL 21,1978	6
LOCATING MOD KIT INSTRUCTIONS IN THE M.R.I.S.	10-21	OCT 17,1980	5
LOGIC ANAL CANNON PLUGS P/N 131-1345-00 - DEFECTIVE "PURGE"	10-18	SEPT 5,1980	5
LONG TERM PRODUCT SUPPORT	9-02	FEB 2,1979	5
MAINTENANCE AGREEMENT LABEL AVAILABLE	7-28	NOV 18,1977	3
MANUAL CORRECTION FORM CHANGES DELIVERY STATION	8-09	MAR 31,1978	5
MANUAL SECTION OF THE MICROFICHE	9-25	DEC 21,1979	2
MICROFICHE CORRECTION FORM	9-10	JUN 1,1979	5
MICROFICHE STORAGE	7-31	DEC 16,1977	5
MICROFICHE USER INFORMATION	9-22	NOV 16,1979	2
MICROFICHE, NEW INDEXES AVAILABLE	9-09	MAY 18,1979	3
MYSTERIOUS DISAPPEARANCE REPORT	7-26	OCT 28,1977	5
NBS TIME AND FREQUENCY BULLETIN	10-03	FEB 8,1980	3
NBS TRACEABLE TRANSITION TIME MEASUREMENTS AT TEK	9-08	MAR 4,1979	5
NEW 156-0067, 156-0158 OP AMPS AVAILABLE	7-27	NOV 11,1977	9
NEW ANTI-STATIC WRIST STRAP AVAILABLE	8-26	SEPT 1,1978	11
NEW PARTS ORDERABLE FROM CSG	10-12	JUNE 13,1980	2
NEW POWER CORDS - SAFETY HAZARD	7-15	JULY 22,1977	7
NEW SERVICE RECORDS	9-24	DEC 14,1979	9
NEW SHIPPING MEMO FORM	7-32	DEC 23,1977	6
NEW SMALL KNOB DESIGNED	7-31	DEC 16,1977	5
NOTE ON MAINTENANCE AGREEMENTS	8-29	OCT 13,1978	4
ON-SITE SERVICE RECORD AND TDS WHEN PARTS AND LABOR ARE WARRANTED	8-30	OCT 27,1978	8
ON-SITE SERVICE RECORDS	9-06	APR 6,1979	6
OPTO COUPLER/ISOLATORS - DEFECTIVE DATE CODES	10-08	APR 18,1980	2
PART NUMBERS FOR 10 WIRE RIBBON CABLES WITH HARMONIC CONNECTORS	8-03	FEB 3,1978	5
PAYROLL CODES ON TIME DISTRIBUTION SHEETS	8-25	AUG 18,1978	4
PELTOLA CONNECTOR SYSTEM PART NUMBERS	10-14	JULY 11,1980	6
PHONE EXTENSION CHANGES FOR BEAVERTON T&M SERVICE SUPPORT	10-12	JUNE 13,1980	3
PINK POLYETHYLENE ANTI-STATIC BAGS	9-08	MAR 4,1979	11
PROCEDURE CONCERNING SERVICE CENTER REQS IN ERROR	9-24	DEC 14,1979	3
PRODUCT HISTORY STATUS LISTING - HEERENVEEN	10-09	MAY 2,1980	3
PRODUCT RESPONSIBILITY LIST FR T&M SERV SUPP (REF PULL-OUT)	10-15	JULY 25,1980	C-1

1 JANUARY 1981

PAGE 6

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
PRODUCT RESPONSIBILITY LIST FOR WALKER RD SERV SUPP (R.P.O.)	10-15	JULY 25,1980	B-1
PRODUCT RESPONSIBILITY LIST FOR IDD SER SUPPORT (REF PULL-OUT)	10-15	JULY 25,1980	A-1
PRODUCT SAFETY	10-15	JULY 25,1980	5
PRODUCTS SENT DIRECTLY TO BEAVERTON BY CUSTOMER FOR REPAIRS	7-04	FEB 18,1977	5
QUALITY ASSURANCE	9-15	AUG 10,1979	8
QUALITY CHECK PROGRAM FOR ASSEMBLIES	10-14	JULY 11,1980	6
QUALITY CHECK PROGRAM FOR ASSEMBLIES	10-17	AUG 22,1980	2
QUERIES FROM INTERNATIONAL	9-17	SEP 7,1979	3
QUESTIONABLE SUPPLY COMPANY	8-18	JUN 2,1978	4
R.F. CABLES	9-22	NOV 16,1979	4
RE-EMPHASIS OF 832/833 VIDEO TAPES	9-23	NOV 30,1979	3
RE-FORMING CAPACITORS EXTENDS SHELF LIFE	9-14	JUL 27,1979	3
RELAYS (TEK MADE, DEFECTIVE CODE DATES)	7-22	SEPT 23,1977	3
REPAIR OF SAFETY DEFECTS	7-11	MAY 27,1977	6
REPORT OF CALIBRATION & CERTIFICATION	9-18	SEP 21,1979	3
RETURNING DEFECTIVE CRT'S TO BEAVERTON	10-05	MAR 7,1980	2
RETURNING CRT'S TO BEAVERTON FOR SALVAGE	7-10	MAY 13,1977	7
RETURNING PARTS AND ACCESSORIES FROM SERVICE CENTERS	7-04	FEB 18,1977	5
REVENUE SPLITTING	8-20	JUN 23,1978	7
REVISED "FIELD MODIFICATIONS SUGGESTION/CORRECTION REPORT"	7-30	DEC 9,1977	6
REVISION TO IDD TROUBLESHOOTING SYMPTOMS HANDBOOK	9-22	NOV 16,1979	3
SAFETY HAZARDS	7-18	AUG 12,1977	5
SALES TRAINING MOVES	10-11	MAY 30,1980	8
SALES/SERVICE AND MOD SUMMARY SECTION OF MICROFICHE	9-25	DEC 21,1979	3
SAW FILTERS	9-13	JUL 13,1979	3
SERVICE CENTER TIME DISTRIBUTION SHEET	9-03	FEB 16,1979	8
SERVICE GROUPS MOVE	10-15	JULY 25,1980	6
SERVICE LABOR RATE CHANGE	9-07	APR 20,1979	8
SERVICE RECORD REPORTING--TIMES	9-08	MAR 4,1979	5
SERVICE RECORD PROCESSING--CLARIFICATION OF BLOCKS	9-15	AUG 10,1979	4
SERVICE RECORD PROCEDURES--TRAVEL INFORMATION	9-15	AUG 10,1979	3
SERVICE RECORD REPORTING--WORKMANSHIP PROBLEMS	8-31	NOV 10,1978	5
SERVICE RECORD PROCESSING--REPORTING INSTRUMENT	9-23	NOV 30,1979	3
SERVICE RECORD PROCEDURES - (COPIES)	9-17	SEPT 7,1979	11
SERVICE TEKNOTES - PURPOSE AND PROCEDURES	10-07	APR 4,1980	3
SERVICE TEKNOTES	9-25	DEC 21,1979	4
SHAFT CAM SWITCH INTERCONCENTRIC DRIVER BREAKAGE	7-17	AUG 5,1977	6
SHIPPING INFORMATION	8-32	NOV 24,1978	6
SIGNATURE/DATA ANALYSIS	9-13	JUL 13,1979	5
SIGNETICS 156-0172-00 "DEFECTIVE DATE CODE"	7-30	DEC 9,1977	8
SOFTWARE AND FIRMWARE ARE VALUABLE PROPERTY	7-28	NOV 18,1977	4

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
SOLDERING WITH EUTECTIC SOLDER	10-06	MAR 21,1980	2
SPANNER WRENCH AVAILABLE	9-02	FEB 2,1979	6
STATIC AWARENESS	8-26	SEPT 1,1978	8
STATIC PRECAUTIONS	9-06	APR 6,1979	7
STATIC SENSITIVE PARTS HANDLING - WRIST STRAP AND SOLDAPULLT	8-21	JUN 30,1978	5
STOLEN INSTRUMENTSS (INTERNATIONAL)	10-01	JAN 11,1980	1
STOLEN INSTRUMENTS (INTERNATIONAL)	10-03	FEB 8,1980	4
STOLEN INSTRUMENTS (INTERNATIONAL)	10-16	AUG 8,1980	3
STOLEN INSTRUMENTS (INTERNATIONAL)	10-19	SEPT 19,1980	4
STOLEN INSTRUMENTS (INTERNATIONAL)	10-21	OCT 17,1980	6
STOLEN INSTRUMENTS (INTERNATIONAL)	10-23	NOV 21,1980	3
STOLEN INSTRUMENTS (INTERNATIONAL)	10-24	DEC 12,1980	4
SURVEY-31 WARRANTY	9-15	AUG 10,1979	6
SWITCH MAINTENANCE	7-02	JAN 21,1977	6
SWITCHES VIDEO CASSETTE	7-05	MAR 4,1977	10
SYSTEM DOWN ORDERING PROCEDURES VERSUS 021- PART NUMBERS	9-13	JUL 13,1979	5
T.I. 151-0423-00 CODE DATE FAILURES	7-16	JULY 29,1977	5
TDS MAIL SCHEDULE	10-06	MAR 21,1980	3
TDS REPORTING/LABOR EXCEPTIONING	9-01	JAN 12,1979	5
TEKTRONIX FIRMWARE SUPPORT POLICY	9-05	MAR 16,1979	6
TEKTRONIX LONG TERM PRODUCT SUPPORT INFORMATION	8-02	JAN 27,1978	3
TEKTRONIX LONG TERM PRODUCT SUPPORT INFORMATION (CORRECTION)	8-03	FEB 3,1978	5
TEKTRONIX PART NUMBER 290-0308-00 VENDOR CHANGE WITHOUT PART NUMBER CHANGE	7-09	APR 29,1977	5
TEKTRONIX PRODUCTS BOUND FOR OVERSEAS CORRECTION	8-06	MAR 10,1978	7
TEKTRONIX PRODUCTS BOUND FOR OVERSEAS USE	8-01	JAN 20,1978	7
TEKTRONIX PRODUCTS BOUND FOR OVERSEAS USE - UPDATE	8-04	FEB 17,1978	6
TELEQUIPMENT	10-09	MAY 2,1980	3
TEN ELECTRO COMMANDMENTS	9-07	APR 20,1979	9
TIME DISTRIBUTION SHEET (TDS) REPORTING	10-17	AUG 22,1980	3
TIME DISTRIBUTION SHEETS	9-25	DEC 21,1979	5
TO-202 TRANSISTOR PIN-OUTS	8-14	MAY 5,1978	4
TOPICS FROM MARKETING TRAINING	9-07	APR 20,1979	10
TRANSPORTING HAZARDOUS MATERIALS	7-30	DEC 9,1977	7
TREATMENT OF LEDS	8-27	SEPT 15,1978	6
TROUBLESHOOTING YOUR OSCILLOSCOPE - ARTICLE 4	10-01	JAN 11,1980	2
TROUBLESHOOTING YOUR OSCILLOSCOPE- ARTICLE 6	10-03	FEB 8,1980	5
TROUBLESHOOTING YOUR OSCILLOSCOPE	10-05	MAR 7,1980	3
TROUBLESHOOTING YOUR OSCILLOSCOPE -ARTICLE 5	10-02	JAN 25,1980	5
TROUBLESHOOTING YOUR OSCILLOSCOPE - ARTICLE 8	10-06	MAR 21,1980	4
TROUBLESHOOTING YOUR OSCILLOSCOPE - REVISION	10-08	APR 18,1980	3
TROUBLESHOOTING YOUR OSCILLOSCOPE (ARTICLE 3)	9-25	DEC 21,1979	7

1 JANUARY 1981

WIZARDS WORKSHOP INDEX

GENERAL

TITLE	ISSUE	DATE	PAGE
TROUBLESHOOTING YOUR OSCILLOSCOPE (ARTICLE 1)	9-23	NOV 30,1979	5
TROUBLESHOOTING YOUR OSCILLOSCOPE (FORWARD)	9-22	NOV 16,1979	5
TROUBLESHOOTING MICROPROCESSOR BASED SYSTEMS VIDEO CASSETTE	7-05	MAR 4,1977	9
TROUBLESHOOTING YOUR OSCILLOSCOPE (ARTICLE 2)	9-24	DEC 14,1979	4
TURN-AROUND-TIME REPORT	9-13	JUL 13,1979	3
U.S. FIELD FAILURE REPORTING TREND	7-05	MAR 4,1977	10
UNAUTHORIZED PRODUCT MODIFICATIONS	10-04	FEB 22,1980	4
UNIT OF MEASURE - BY THE FOOT	7-15	JULY 22,1977	7
UNIVERSAL LOAD UNIT - DESIGN ERROR	10-21	OCT 17,1980	7
UNIVERSAL LOAD UNIT - PRODUCTION ERROR	10-23	NOV 21,1980	3A
UPDATING SCHEDULE FOR MICROFICHE (MRIS)	9-23	NOV 30,1979	9
VACUUM SOLDER EXTRACTION	9-11	JUN 15,1979	4
VIDEO AND AUDIO TAPES AVAILABLE	8-04	FEB 17,1978	6
VIDEO AND AUDIOTAPES AVAILABLE	9-12	JUN 29,1979	2
VIDEO AND AUDIO TAPES AVAILABLE	8-20	JUN 23,1978	8
VIDEO AND AUDIO TAPES AVAILABLE	8-34	DEC 22,1978	5
VIDEO AND TRAINING PACKAGE ANNOUNCEMENTS	8-23	JUL 21,1978	7
VIDEO CASSETTE ON CREDIT	7-06	MAR 18,1977	4
VIDEO CASSETTES ON MEASUREMENTS IN THE SERVICE DOMAIN THE 851 DIGITAL TESTER	7-08	APR 15,1977	3
VIDEO TAPE AND AUDIOTAPES AVAILABLE	9-07	APR 20,1979	12
VIDEO TAPE ANNOUNCEMENTS	8-31	NOV 10,1978	6
VIDEO TAPE ANNOUNCEMENTS	9-18	SEP 21,1979	9
VIDEO TAPE ANNOUNCEMENTS	7-26	OCT 28,1977	6
VIDEO TAPE ANNOUNCEMENTS	7-31	DEC 16,1977	7
VIDEO TAPE AVAILABLE	7-23	SEPT 30,1977	3
VIDEO TAPES AVAILABLE	7-14	JULY 8,1977	5
VIDEO TAPES AVAILABLE	8-29	OCT 13,1978	5
VIDEO TAPES AVAILABLE	7-12	JUNE 10,1977	4
VIDEO TAPES AVAILABLE	7-20	AUG 26,1977	5
VIDEO TAPES AVAILABLE	7-27	NOV 11,1977	9
VIDEO TAPES FOR THE TEST & MEASUREMENT SERVICE TECHNICIAN	9-08	MAR 4,1979	12
VIDEOTAPE ANNOUNCEMENTS	10-02	JAN 25,1980	10
VIDEOTAPE DISTRIBUTION MOVES	10-11	MAY 30,1980	7
VIDEOTAPES AVAILABLE	10-11	MAY 30,1980	5
VIDEOTAPES AVAILABLE	10-20	OCT 3,1980	1
WALKER ROAD PRODUCT UPDATE STATUS	10-19	SEPT 19,1980	4
WARRANTY FAILURE RETURNS	7-12	JUNE 10,1977	5
WARRANTY POLICIES	10-01	JAN 11,1980	6
WARRANTY POLICIES MANUAL UPDATE	10-03	FEB 8,1980	11
WARRANTY POLICY	10-04	FEB 22,1980	4
WARRANTY POLICIES	9-17	SEPT 7,1979	16

WIZARDS WORKSHOP INDEX


GENERAL

TITLE	ISSUE	DATE	PAGE
WATTS TO BTU/HOUR CONVERSION	8-12	APR 21,1978	4
WD40 LUBRICANT	7-08	APR 15,1977	3
WIRE FOR CIRCUIT BOARD MODIFICATION	8-09	MAR 31,1978	6
WIRE PREP GENERAL INFORMATION	10-01	JAN 11,1980	8
WIZARDS WORKSHOP MASTER INDEX	10-23	NOV 21,1980	4
WIZARDS WORKSHOP NOW ON MICROFICHE	8-17	MAY 26,1978	3
ZIP GRIP #10 NOW ORDERABLE	8-34	DEC 22,1978	6

WIZARDS WORKSHOP INDEX
INFORMATION DISPLAY DIVISION

MEASUREMENT DISPLAY PRODUCTS

TITLE	ISSUE	DATE	PAGE
600 SERIES PRODUCTS	10-17	AUG 22,1980	10
602 - H.V. TRANSISTOR Q200	8-11	APR 14,1978	6
602 HIGH VOLTAGE POWER SUPPLY IMPROVEMENT	10-07	APR 4,1980	8
602 MOD 705B PACKAGING	7-18	AUG 12,1977	8
602 NOISY FOCUS POT PROBLEM	10-05	MAR 7,1980	24
602 PHASING ADJUSTMENT	10-23	NOV 21,1980	25
602 POWER SWITCH IMPROVEMENT	8-28	SEPT 29,1978	22
603,603A,604,604A,605,606,606A DEF AMPLIFIER SETTLING	10-04	FEB 22,1980	21
603/604 AND 605 TRANSISTOR RELIABILITY MOD (REPEAT)	8-11	APR 14,1978	7
603/604 DEFLECTION AMPLIFIER	8-07	MAR 17,1978	15
603/604 HIGH VOLTAGE IMPROVEMENT	7-10	MAY 13,1977	23
603/604 HIGH VOLTAGE CIRCUIT MOD	8-16	MAY 19,1978	12
603/604 MONITOR OUTPUT TRANSISTORS	7-19	AUG 19,1977	13
603/604 RELIABILITY MOD - M31277	8-11	APR 14,1978	6
603/604 TRANSISTOR CHANGES	8-11	APR 14,1978	7
605, 607 DOT OR TRACE BLINKING 5-9-77	7-11	MAY 27,1977	20
606 DISPLAY MONITOR	7-10	MAY 13,1977	24
606 MONITOR AVERAGE PLATE VOLTAGE ADJUSTMENT	7-20	AUG 26,1977	9
606A 607A 608 624 634 OP AMP CHANGE	10-20	OCT 3,1980	13
606B,607,607A,620,624, DEFLECTION AMPLIFIER SETTLING TIME PROBLEM	10-04	FEB 22,1980	21
608 CRT REPLACEMENT IN EARLY INSTRUMENTS	10-23	NOV 21,1980	25
608 GROUND CLIP	8-28	SEPT 29,1978	23
608 OPTION 25 CHANGE	8-06	MAR 10,1978	10
608 Z-AXIS EXTENDER BOARD	8-12	APR 21,1978	7
611 U450 LAYOUT MISLEADING	10-23	NOV 21,1980	25
611 Z-AXIS NOISE ELIMINATED	7-21	SEPT 9,1977	11
613 CG,/613-1 CG/613 JA; MODIFICATION 35391 APPLIES	10-23	NOV 21,1980	26
634 ARCING CRT DETECTION	10-23	NOV 21,1980	26
634 MODIFICATION #36364	10-23	NOV 21,1980	26
634 OPTIONS 23 AND 28 MECHANICAL PART NUMBERS	8-32	NOV 24,1978	13
634 RELIABILITY & NOISE MODIFICATION #3777	10-20	OCT 3,1980	14
634 TORX TOOLS AVAILABLE	10-20	OCT 3,1980	20
ALL MONITORS - CORRECT SHIPPING PROCEDURES	10-03	FEB 8,1980	20
DOT GENERATOR CIRCUIT CHANGE	8-17	MAY 26,1978	5



WIZARDS WORKSHOP INDEX

TEST & MEASUREMENT PRODUCTS GENERAL

TITLE	ISSUE	DATE	PAGE
"DIP" INSERTION TOOL	9-02	FEB 2,1979	20
067-0741-99 USING THE CRYSTAL CLOCK	7-04	FEB 18,1977	11
105-XXXX-XX - CAM DRUMS CAUSING LEAKAGE PROBLEMS	8-04	FEB 17,1978	14
1440 - 741 OP. AMP. REPLACEMENT	7-08	APR 15,1977	11
148-0034-00 FAILURES OF RELAYS	7-09	APR 29,1977	13
150-1037-00 LED DISPLAY, 7 SEGMENT PROBLEMS	7-04	FEB 18,1977	11
151-0188-00 MIXED STOCK	8-30	OCT 27,1978	24
151-0192-00 POOR RELIABILITY	8-20	JUN 23,1978	16
151-0251-00 DEFECTIVE DATE CODE "MOTOROLA"	8-05	MAR 3,1978	17
152-0227-00 MIXED PARTS	8-21	JUN 30,1978	15
152-0462-00 - MOTOROLA BRAND	8-04	FEB 17,1978	14
152-0493-00 - DEFECTIVE DATE CODES - "HIGH VOLTAGE DEVICES"	8-07	MAR 17,1978	15
152-0586-00 VENDOR'S PART NUMBER CHANGE	8-21	JUN 30,1978	15
152-0639-00 CRACKING OF DIODES' GLASS BODY -- CAUTION	8-30	OCT 27,1978	24
155-0014-01 WRONG PART INTERNALLY	7-19	AUG 19,1977	4
155-0023-00 DEFECTIVE DATE CODE	8-25	AUG 18,1978	8
155-0024-00 DEFECTIVE DATE CODE	8-25	AUG 18,1978	9
155-0108-00 DEFECTIVE RUNS	8-20	JUN 23,1978	16
156-0030-00 DEFECTIVE DATE CODE	8-24	AUG 4,1978	11
156-0053-00 DEFECTIVE DEVICES - AMD BRAND	8-32	NOV 24,1978	9
156-0058-00 - COMPONENT MIX	8-13	APR 28,1978	15
156-0058-00 - COMPONENT MIX (CORRECTION)	8-14	MAY 5,1978	9
156-0091-00 DEFECTIVE DATE CODES - "SIGNETICS"	8-06	MAR 10,1978	10
156-0120-00/01 DEFECTIVE "ITT BRAND"	8-24	AUG 4,1978	11
156-0141-00 DEFECTIVE DATE CODE	8-30	OCT 27,1978	25
156-0178-00/152-0107-03 MIXED STOCK	8-28	SEPT 29,1978	21
156-0178-00/152-0107-03 MIXED STOCK	8-28	SEPT 29,1978	21
156-0245-00 MIXED STOCK	8-30	OCT 27,1978	25
156-0325-00 MIXED STOCK	8-21	JUN 30,1978	15
156-0349-00 MIXED STOCK	8-24	AUG 4,1978	11
156-0403-00 DEFECTIVE DATE CODE	8-25	AUG 18,1978	9
156-0465-00 MIXED STOCK	8-32	NOV 24,1978	9
156-0480-00 - DISQUALIFIED VENDOR	8-13	APR 28,1978	15
156-0515-02 MIXED PARTS	8-20	JUN 23,1978	16
156-0576-02 MIXED STOCK	8-21	JUN 30,1978	15
156-0599-00 VENDOR PART NUMBER DELETED	8-08	MAR 24,1978	8
156-0666-01 INCORRECT DATA AT ALL ADDRESSES - MOTOROLA	8-32	NOV 24,1978	9
156-0914-00 INCORRECT MARKED DEVICES	8-20	JUN 23,1978	16
156-0916-00 MIXED PARTS	8-20	JUN 23,1978	17
156-0957-00 - DEFECTIVE DATE CODE	8-13	APR 28,1978	15
156-0982-00 DEFECTIVE TEXAS INSTRUMENTS BRAND ONLY	8-20	JUN 23,1978	17
156-1013-00 DEFECTIVE DATE - MOTOROLA BRAND	8-31	NOV 10,1978	18

TEST & MEASUREMENT PRODUCTS GENERAL

TITLE	ISSUE	DATE	PAGE
156-1031-00 DEFECTIVE DATE CODE - FAIRCHILD BRAND	8-30	OCT 27,1978	25
159-0049-00 OPEN FUSES--BUSS BRAND	8-02	JAN 27,1978	9
159-0116-00 FUSE--MIXED PARTS	8-02	JAN 27,1978	9
161-0071-XX - DEFECTIVE POWER CORDS	8-04	FEB 17,1978	15
290-0480-00 EXCESSIVE LEAKAGE	8-04	FEB 17,1978	15
311-1177-00 DEFECTIVE DATE CODE--BECKMAN/HELIPOT	7-30	DEC 9,1977	17
7603/7403/D40/D83 CRT PROBLEM	7-03	FEB 4,1977	4
APPROVED RTV SILICON RUBBER PRODUCTS	9-05	MAR 16,1979	15
AUDIO AND VIDEO TRAINING TAPES	8-28	SEPT 29,1978	20
AUDIO TAPES AVAILABLE	7-18	AUG 12,1977	4
AVX BRAND CERAMIC GLASS ENCAPSULATED CAPACITORS ADDENDUM	8-10	APR 7,1978	7
CORRECTION TO TERMINAL POST SOLDERING PROBLEM (WIZARD 12-10-76)	7-02	JAN 21,1977	9
CRT RELIABILITY	7-11	MAY 27,1977	6
DEFECTIVE LITTLEFUSE BRAND FUSES	8-20	JUN 23,1978	13
ELECTROLYTIC CAP FAILURES ANALYZED	9-05	MAR 16,1979	15
EQUIPMENT RACK	8-04	FEB 17,1978	13
FIXED CAPACITORS - CLARIFICATION OF MARKINGS	8-25	AUG 18,1978	8
METROLOGY - TRACEABILITY	8-28	SEPT 29,1978	20
MOSTEK 156-0410-00 "DEFECTIVE DATE CODE"	7-26	OCT 28,1977	17
MOTOROLA 2N3055 TRANSISTORS/151-0140-00	7-09	APR 29,1977	13
NEW "CAUTION" LABEL FOR TEK-MADE SWITCHES	8-20	JUN 23,1978	14
NEW FORMAT GUIDELINES FOR T&M MANUALS	9-02	FEB 2,1979	20
NEW SCHEMATIC SYMBOLS, "DRAFTING STANDARD" AVAILABLE	8-30	OCT 27,1978	24
OMISSION IN MEASURING CRT PHOTOGRAPHIC WRITING RATE ARTICLE/FEB 19, 1977	7-05	MAR 4,1977	11
POTENTIAL NUVISTOR SHORTAGE	7-10	MAY 13,1977	8
REJECT PARTS PROVIDE VALUABLE FAILURE INFORMATION	8-27	SEPT 15,1978	17
RELAYS (TEK MADE, DEFECTIVE CODE DATES)	8-04	FEB 17,1978	13
SHAFT CAM SWITCH INTERCONCENTRIC DRIVER BREAKAGE (CORRECTION)	7-19	AUG 19,1977	4
SWITCH PIN INFORMATION	7-13	JUNE 24,1977	21
TECHNICAL SUPPORT OF OLDER PRODUCTS	7-13	JUNE 24,1977	22
TM 500 LABEL PART NUMBER	9-07	APR 20,1979	28
TUTORIAL - MEASURING CRT PHOTOGRAPHIC WRITING RATE	7-04	FEB 18,1977	1
155-0006-01 DEFECTIVE DATE CODE	9-01	JAN 12,1979	14
156-0030-00 DEFECTIVE DATE CODE - FAIRCHILD	9-01	JAN 12,1979	14
156-0398-00 INCORRECT MARKINGS	9-02	FEB 2,1979	16
156-0511-00 DEFECTIVE DATE CODES - "SIGNETICS"	9-01	JAN 12,1979	14
290-0804-00 MIXED STOCK	9-03	FEB 16,1979	21
P/N 151-0301-00 - MIXED STOCK	8-26	SEPT 1,1978	26
PDP-11 DL11-E PART NUMBER	9-07	APR 20,1979	24
PDP-11/35 COMPUTER CONFIGURATION GUIDE	8-26	SEPT 1,1978	24
PDP/11 TERMINAL INTERFACE STRAPPING	8-28	SEPT 29,1978	14
SYSTEM INSTALLATION REPORTS - STS, SPS, AND MDL	9-02	FEB 2,1979	16
SYSTEMS PHONE INFORMATION	7-22	SEPT 23,1977	3

WIZARDS WORKSHOP INDEX
LABORATORY INSTRUMENT DIVISION

BENCHTOP SEMICONDUCTOR TEST SYSTEMS

TITLE	ISSUE	DATE	PAGE
576 AMPLIFIER OSCILLATIONS	10-21	OCT 17,1980	11
576 STEP GENERATOR INTERMITTENTLY SKIPS STEPS	10-17	AUG 22,1980	5
576/577 TRANSISTOR ADAPTER SOCKET CHANGES	10-24	DEC 12,1980	5

SAMPLING PRODUCTS

1500 SERIES CHART RECORDER - L8215 SHORTING TO FRAME	9-02	FEB 2,1979	36
1501 CHART PAPER INCOMPATABILITY	8-13	APR 28,1978	21
1501/1503 DISTANCE METER "O" RING PART NUMBER (354-0563-00)	9-09	MAY 18,1979	23
1502 ABERRATIONS	7-28	NOV 18,1977	16
1502 ABERRATIONS	8-03	FEB 3,1978	15
1502 CALIBRATION PROCEDURE REWRITTEN	8-29	OCT 13,1978	11
1502 CASE REMOVAL	7-29	NOV 25,1977	8
1502 CHART RECORDER - EXPLODED VIEW	7-04	FEB 18,1977	13
1502 MAINTENANCE NOTE	7-07	APR 1,1977	16
1502 MANUAL CHANGE INFORMATION (070-1792-00)	7-26	OCT 28,1977	22
1502 NON-LINEARITY ON X0.1 RAMP	8-32	NOV 24,1978	17
1502 SAMPLING BRIDGE INSTALLATION AID	10-08	APR 18,1980	29
1502 STRIPLINE MAINTENANCE NOTE	7-05	MAR 4,1977	22
1502/1503 BATTERY PACK RETURNS	7-01	JAN 14,1977	11
1502/1503 BNC REPLACEMENT	7-15	JULY 22,1977	14
1502/1503 CAMERA FUNCTION	7-32	DEC 23,1977	15
1502/1503 CAMERA FUNCTION DELETED	7-29	NOV 25,1977	9
1502/1503 CHART RECORDER	8-02	JAN 27,1978	13
1502/1503 CHART RECORDER FUSING, M30656	8-16	MAY 19,1978	12
1502/1503 CHART RECORDER FUSING	8-19	JUN 9,1978	23
1502/1503 CHART RECORDER MANUAL	8-09	MAR 31,1978	15

WIZARDS WORKSHOP INDEX

SAMPLING PRODUCTS

TITLE	ISSUE	DATE	PAGE
1502/1503 FRONT PANEL PLUG-IN SEAL REPLACEMENT	7-06	MAR 18,1977	10
1502/1503 INTENSITY PROBLEMS CORRECTION	8-25	AUG 18,1978	9
1502/1503 MANUALS REPRINTED	9-16	AUG 24,1979	6
1502/1503 DISTANCE METER "O" RING PART NUMBER (354-0563-00)	9-09	MAY 18,1979	6
1502/1503 CHART RECORDER - SECURING ROD	9-02	FEB 02,1979	37
1502/1503 - INTENSITY RANGE IMPROVEMENT	9-04	MAR 2,1979	26
1502/1503 -- CHANGE IN TORQUE FOR THE CASE SCREWS	8-30	OCT 27,1978	32
1502/1503 BATTERY PACK SIDE COVERS	8-09	MAR 31,1978	15
1502/1503 CABLE PART NUMBERS	7-03	FEB 4,1977	19
1502/1503 CHART RECORDER MANUAL	8-31	NOV 10,1978	21
1502/1503 HAND TOOLS TORQUE SCREWDRIVER	7-31	DEC 16,1977	19
1502/1503 LINE FUSE CHANGE	7-18	AUG 12,1977	9
1502/1503 POTENTIAL INTENSITY LOSS/DEGRADATION	8-31	NOV 10,1978	21
1502/1503 PROBLEM -- CRACKED CASES	8-29	OCT 13,1978	12
1502/1503 WATERPROOFING	7-31	DEC 16,1977	20
1502/1503 ZERO REFERENCE POT MOD	8-30	OCT 27,1978	32
1503 - FAST RAMP CALIBRATION PROCEDURE CORRECTION	8-29	OCT 13,1978	12
1503 - INTENSITY LIMIT ADJUSTMENT	9-02	FEB 02,1979	37
1503 INTERMITTENT 50 OHM TERM SWITCH	7-07	APR 1,1977	16
1S2 TDR/SAMPLER D435 REPLACEMENT	7-05	MAR 4,1977	21
3S5 CHANNEL 'A' TRIG CONNECTOR	7-05	MAR 4,1977	23
7S14 TRIG KICKOUT PULSE SPECIFICATION	8-15	MAY 12,1978	12
7S14/5S14 TRACE JITTER: MOD 32888	8-10	APR 7,1978	17
ADDENDUM TO 1502 STRIP LINE REPAIR	7-09	APR 29,1977	13
FUSE HOLDER WATERSEAL	8-31	NOV 10,1978	20
S-1 INPUT TERMINATOR, R4 METAL FLANGE PART NUMBER	7-22	SEPT 23,1977	11

WIZARDS WORKSHOP INDEX

TM 500

TITLE	ISSUE	DATE	PAGE
131-0274-00 DEFECTIVE BNC CONNECTORS - KING BRAND	9-03	FEB 16,1979	34
150-1038-00 MIXED STOCK	9-03	FEB 16,1979	34
151-0254-00 CHANGE OF MARKINGS	9-03	FEB 16,1979	34
151-0333-00 DEFECTIVE - SPRAGUE	9-03	FEB 16,1979	35
151-0347-00/01 DEFECTIVE DATE CODES	9-03	FEB 16,1979	35
151-0434-00/01 DEFECTIVE DATE CODE - MOTOROLA	9-03	FEB 16,1979	35
152-0634-00 ARCING OR DEAD	9-03	FEB 16,1979	35
152-0635-00 ARCING THROUGH THE CONNECTOR	9-03	FEB 16,1979	35
156-0305-00 MIXED STOCK	9-03	FEB 16,1979	35
156-0398-00 MIXED STOCK	9-03	FEB 16,1979	36
156-0426-00 DEFECTIVE DATE CODE - AMI BRAND	9-03	FEB 16,1979	36
156-0574-00 MIXED STOCK	9-03	FEB 16,1979	36
156-0785-00 DEFECTIVE DATE CODES - INTERSIL	9-03	FEB 16,1979	36
283-0111-00 MIXED STOCK	9-03	FEB 16,1979	37
290-0582-00 MIXED STOCK	9-03	FEB 16,1979	37
311-0160-00 DEFECTIVE DATE CODE	9-03	FEB 16,1979	37
311-0571-00 MIXED STOCK	9-03	FEB 16,1979	37
40 DC 505/DC 505A NEW FIELD MODIFICATION KIT	8-28	SEPT 29,1978	28
5110/5112 MOD 172F - MISSING MICA WASHER ON Q213	9-21	NOV 2,1979	8
AF 501 CIRCUIT IMPROVEMENT	10-15	JULY 25,1980	9
AF 501 ERRATIC NOISE SPIKES ON OUTPUT	8-06	MAR 10,1978	19
AF 501 MAINTENANCE NOTES	10-19	SEPT 19,1980	6
AM 501 INTERNAL OFFSET NULL ADJUST INOP	8-08	MAR 24,1978	12
AM 502 DIFFICULTY MEETING 1 MHZ BANDPASS	10-08	APR 18,1980	5
AM 502 MAINTENANCE NOTES	10-03	FEB 8,1980	13
AM 502-P/N 151-1029-00 DEFECTIVE DATE CODES	9-22	NOV 16,1979	7
CG 551AP +5 VOLT SUPPLY LOADING	10-20	OCT 3,1980	4
CG 551AP PARTS SUPPORT	10-22	OCT 31,1980	5
CG 551AP SHIPPING	10-19	SEPT 19,1980	7
DC 503 "MANUAL MODE INOP"	8-04	FEB 17,1978	20
DC 503 FIELD MOD INSTRUCTION ERRORS	9-03	FEB 16,1979	30
DC 503 MAINTENANCE NOTES	9-12	JUN 29,1979	A-1
DC 503 NO GATE LIGHT	9-15	AUG 10,1979	10
DC 503 PREVENT DISPLAY ERRORS	9-03	FEB 16,1979	31
DC 504 - "Q195 REPLACEMENT"	9-12	JUN 29,1979	4
DC 504 - 156-0410-00 - DEFECTIVE DATE CODE - "MOSTEK"	8-08	MAR 24,1978	13
DC 504 040-0901-00	9-05	MAR 16,1979	34
DC 504/OPT. 1 "PREVENT CROSSTALK"	7-10	MAY 13,1977	19
DC 505/DC505A MOD KIT CORRECTION	7-07	APR 1,1977	20
DC 505A - U925 VENDOR COMPATIBILITY	7-16	JULY 29,1977	17
DC 505A AND 153 INTERFACE PROBLEMS	7-31	DEC 16,1977	22
DC 505A ERRONEOUS COUNTING AT 10HZ	10-08	APR 18,1980	5

WIZARDS WORKSHOP INDEX

TM 500

TITLE	ISSUE	DATE	PAGE
DC 505A MANUAL ERROR	10-08	APR 18,1980	5
DC 505A MAINTENANCE NOTES	9-12	JUN 29,1979	B-1
DC 505A NEW MANUAL	9-08	MAY 4,1979	14
DC 505A NEW POWER SUPPLY IMPROVEMENT MOD KIT	8-07	MAR 17,1978	20
DC 505A PRECAUTIONS WHEN USING AN EXTENDER CABLE	9-03	FEB 16,1979	31
DC 505A U90 REPLACEMENT	10-22	OCT 31,1980	5
DC 508 MAINTENANCE NOTES (BELOW SN:B02) REFERENCE PULL-OUT	10-01	JAN 11,1980	A-1
DC 508 NEW FIELD MOD KIT: 050-1175-00	9-03	FEB 16,1979	31
DC 508 NEW FIELD MODIFICATION KITS	8-30	OCT 27,1978	36
DC 508 NEW PRESCALER BOARD	9-06	APR 6,1979	50
DC 508 PERFORMANCE CHECK CORRECTION	9-12	JUN 29,1979	5
DC 508 PRESCALER CABLE ASSEMBLIES	10-11	MAY 30,1980	11
DM 501 - 156-0041-00 - DEFECTIVE DATE CODE - "FAIRCHILD"	8-07	MAR 17,1978	20
DM 501 ARCING	9-15	AUG 10,1979	10
DM 501 INCORRECT INPUT CLAMPING PROTECTION	8-05	MAR 3,1978	21
DM 501 MAINTENANCE NOTES - REF PULL-OUT	10-01	JAN 11,1980	B-1
DM 501 MAINTENANCE NOTES - REFERENCE PULL-OUT	10-01	JAN 11,1980	D-1
DM 501 NEW MOD KITS FOR DISPLAY CIRCUIT BOARD REPLACEMENT	8-02	JAN 27,1978	15
DM 501A 500V AC RANGE 1 & LOW	10-10	MAY 16,1980	4
DM 501A SPECIAL MAINTENANCE INFORMATION (REFERENCE PULL-OUT)	10-22	OCT 31,1980	A-1
DM 501A UNSTABLE OHMS READINGS	10-18	SEPT 5,1980	7
DM 502 MAINTENANCE NOTES - REFERENCE PULL-OUT	10-01	JAN 11,1980	C-1
DM 502 S/N B029624 & BELOW INTERMITTENT ERROR COUNT... RANGE (CORRECTION)	8-04	FEB 17,1978	21
DM 502 S/N B029624 & BELOW INTERMITTENT ERROR COUNT -200VDC RANGE	8-02	JAN 27,1978	15
DM 502A MAINTENANCE NOTES	9-25	DEC 21,1979	11
DM 502A, 02 - PROTECTION FOR U1301 AND U1321	9-13	JUL 13,1979	6
FG 501 - FRONT PANEL AND SUBPANEL REPLACEMENT	9-14	JUL 27,1979	9
FG 501 BOARD POLARITY PADS WRONG	8-01	JAN 20,1978	19
FG 501 EXCESSIVE DRIFT IN HOLD MODE - "CORRECTION"	8-34	DEC 22,1978	21
FG 501 EXCESSIVE DRIFT IN HOLD MODE	8-31	NOV 10,1978	21
FG 501 MAJOR MANUAL ERRORS	9-01	JAN 12,1979	A-1
FG 501 NEW CUSTOM MODIFICATION	8-32	NOV 24,1978	18
FG 501 OUTPUT AMPLIFIER IMPROVED	8-32	NOV 24,1978	18
FG 501 U-48 VENDOR COMPATIBILITY	7-24	OCT 7,1977	11
FG 503 "DS528 REPLACEMENT"	9-13	JUL 13,1979	6
FG 503 "U121 REPLACEMENT"	9-13	JUL 13,1979	7
FG 503 POWER LAMP REPLACED	9-19	OCT 5,1979	5
FG 503 TIMING PROBLEMS WHEN A CUSTOM TIMING CAPACITOR IS INSTALLED	9-22	NOV 16,1979	8
FG 504 "B04 REWORK PROGRAM" DISCONTINUED	9-07	APR 20,1979	33
FG 504 (B042 AND ABOVE) BLOWING FUSES	10-18	SEPT 5,1980	7

1 JANUARY 1981

PAGE 17

WIZARDS WORKSHOP INDEX

TM 500

TITLE	ISSUE	DATE	PAGE
FG 504 - NEW MANUAL FOR S/N B04 -- AND ABOVE	10-04	FEB 22,1980	6
FG 504 1 AMP FUSE MODIFICATION	10-24	DEC 12,1980	6
FG 504 151-0232-00 - DEFECTIVE DATE CODES - "INTERSIL"	8-04	FEB 17,1978	22
FG 504 COMPONENTS REVERSED	9-08	MAY 4,1979	14
FG 504 FACTORY REWORK	8-04	FEB 17,1978	21
FG 504 IMPROVE 10(5) TIMING ADJUSTMENT RANGE	9-22	NOV 16,1979	9
FG 504 IMPROVE RELIABILITY OF OUTPUT AND POWER SUPPLY CIRCUIT	7-05	MAR 4,1977	28
FG 504 MAINTENANCE NOTES	9-06	APR 6,1979	A-1
FG 504 MISSING RUNS	7-10	MAY 13,1977	19
FG 504 POSSIBLE DAMAGE TO CUSTOMERS EQUIPMENT	7-10	MAY 13,1977	21
FG 504 REAR INTERFACE OUTPUT CHANGES	9-12	JUN 29,1979	6
FG 504 TROUBLE SHOOTING HINTS	7-15	JULY 22,1977	20
FG501A/FG507 SINE DISTORTION ADJUSTMENT	10-25	DEC 19,1980	6
FIELD MOD KIT FOR REAR INTERFACE WIRING	8-07	MAR 17,1978	20
INTERMITTENT RELAYS IN DM501A AND DM502A	10-15	JULY 25,1980	9
NOTICE ABOUT RMC CAPS IN DM 501A'S AND DM 502A'S	10-14	JULY 11,1980	7
PG 501 "Q170 AND Q176 REPLACEMENT	8-27	SEPT 15,1978	28
PG 501 MAINTENANCE NOTES	10-19	SEPT 19,1980	8
PG 502 MAINTENANCE NOTES	10-19	SEPT 19,1980	9
PS 503A MAINTENANCE NOTES	10-04	FEB 22,1980	6
RG 501 MAINTENANCE NOTES	10-19	SEPT 19,1980	12
RTM/TM 506 APPLICATION PRECAUTION (CORRECTION)	10-17	AUG 22,1980	6
RTM/TM 506 APPLICATION PRECAUTIONS	10-10	MAY 16,1980	5
SC 502 MAINTENANCE NOTES (REFERENCE PULL-OUT)	10-05	MAR 7,1980	A-1
SC 503 - P/N 311-2017-00 DEFECTIVE	10-04	FEB 22,1980	7
SC 503 MAINTENANCE NOTES	10-08	APR 18,1980	6
SC 504 INTERMITTENT +5V/ -5V SUPPLIERS	10-10	MAY 16,1980	6
SC 504 MODIFICATIONS	10-22	OCT 31,1980	6
SCPDA 1 SOFTWARE PERFORMANCE REPORT	10-24	DEC 12,1980	7
SG 502 MAINTENANCE NOTES	10-19	SEPT 19,1980	13
SG 503 MAINTENANCE NOTES	10-20	OCT 3,1980	5
SG 503 Q190 LEAD CONFIGURATION	9-08	MAY 4,1979	15
SG 504 HARMONIC DISTORTION & LEVELING IMPROVEMENTS	10-21	OCT 17,1980	12
SG 504 MAINTENANCE NOTES	10-20	OCT 3,1980	9
TM 500 - REAR INTERFACE ACCESS EXTENDER FOR PLUG-INS	10-10	MAY 16,1980	7
TM 500 SOCKET REWORK PROGRAM (CODE 18) DISCONTINUED	10-12	JUNE 13,1980	6
TM 501 & TM 503 TRANSFORMER LEAD COLOR CHANGES	10-21	OCT 17,1980	13
TM 506 CABINET TO RACKMOUNT CONVERSION	10-22	OCT 31,1980	6

1 JANUARY 1981

PAGE 18



WIZARDS WORKSHOP INDEX

5000 SERIES

TITLE	ISSUE	DATE	PAGE
067-0883-99/067-0919-99	10-16	AUG 8,1980	6
1502/1503 MANUALS REPRINTED	9-16	AUG 24,1979	6
5000 FLEXIBLE EXTENDER	10-08	APR 18,1980	7
5000 SERIES MODIFIED INSTRUMENTS 768 X, Y, T	7-06	MAR 18,1977	16
5000 SERIES OSCILLATING NEON BULBS	7-11	MAY 27,1977	18
5100/R, S/N B070029 & UP -30 VOLT POWER SUPPLY OSCILLATIONS	10-25	DEC 19,1980	6
5110/R, 5111/R, 5115/R.H.V. REGULATION	9-25	DEC 21,1979	15
5223 MEMORY CONTENTS L.E.D.'S	10-24	DEC 12,1980	7
5223 POSSIBLE POWER SUPPLY FAILURE B010145 & BELOW	10-20	OCT 3,1980	10
5400 SERIES READOUT	10-08	APR 18,1980	7
5440/5441 READOUT SHORTING TO MOUNTING SCREW	10-18	SEPT 5,1980	8
5440/R 5441/R READOUT MALFUNCTION	10-16	AUG 8,1980	5
5440/R 5441/R TRANSISTOR AVAILABILITY	10-16	AUG 8,1980	5
5440/R AND 5441/R FAN MODIFICATION	7-22	SEPT 23,1977	15
5441 AUTO FOCUS MOD DOCUMENTATION S/N B092860 & UP	10-22	OCT 31,1980	8
5441 ENGINEERING SPECIFICATION CHANGE	7-04	FEB 18,1977	15
5441 HANDLE SUPPORT	10-21	OCT 17,1980	16
5441 MANUAL ERROR	7-06	MAR 18,1977	18
5441 TRACE ROTATION	7-22	SEPT 23,1977	17
5A18N CHOPPED MODE OSCILLATIONS S/N B129148 & UP	10-20	OCT 3,1980	10
5A22N CAM SWITCH	9-25	DEC 21,1979	13
5A22N DIFFERENTIAL AMPLIFIER DC OFFSET	8-06	MAR 10,1978	21
5A48 ABNORMAL DECREASE IN GAIN AND BANDWIDTH	7-26	OCT 28,1977	23
5A48 CHANNEL 2 OSCILLATIONS	9-25	DEC 21,1979	13
5B10N RANDOM LOSS OF SWEEP S/N B099092 & UP	10-22	OCT 31,1980	7
5B12N,5A13N, 5B42,5B44 HELIDIAL SETTINGS	10-13	JUNE 27,1980	9
5B42 TRIGGER DIODES	7-10	MAY 13,1977	23
7B87 INSURE STARTING OF CLOCK OSCILLATOR	10-16	AUG 8,1980	8
SERVICE SUPPORT PRODUCT RESPONSIBILITY CHANGE(5000/7000 SERIES)	10-20	OCT 3,1980	10

WIZARDS WORKSHOP INDEX

7000 SERIES

TITLE	ISSUE	DATE	PAGE
067-0587-02 SIGNAL STANDARDIZER, OSCILLATOR CRYSTAL SHORTING	9-07	APR 20,1979	35
067-0655-00, SIGNAL PICK-OFF CABLE REPLACEMENT	10-13	JUNE 27,1980	12
7000 SERIES CRT WRITING SPEED CHANGES	10-19	SEPT 19,1980	14
7000 SERIES, REPLACEMENT CABLE ASSY FOR "SPOT-O-GOLD" CONNECTORS	10-07	APR 4,1980	5
7000 SERIES PART NUMBERS FOR WARNING TAGS	9-25	DEC 21,1979	20
7000 SERIES CRT CLAMP TIGHTENING PROCEDURE	7-11	MAY 27,1977	20
7000 SERIES MAINFRAME INTERFACE CONNECTOR COVERS	7-06	MAR 18,1977	20
7000 SERIES OSCILLOSCOPE--MANDATORY MODIFICATION	8-28	SEPT 29,1978	29
7104 7704A 7834 7844 7854 R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
7104 BACKGROUND SCINTILLATION	10-02	JAN 25,1980	11
7104 CRT CIRCUIT, C1796 ADDED, B010157 AND UP	10-01	JAN 11,1980	10
7104 CRT VOLTAGE SETTINGS	10-18	SEPT 5,1980	9
7104 INCOMPATIBILITY WITH 7B70,7B71 AND 7B92	9-08	MAY 4,1979	15
7104 INTENSITY UNIFORMITY	10-01	JAN 11,1980	10
7104 INTENSITY CHANGING WITH TIME	9-25	DEC 21,1979	20
7104 LOGIC CIRCUIT DIODE CHANGE S/N B010100-B010130	9-25	DEC 21,1979	21
7104 POWER SUPPLY START-UP	10-18	SEPT 5,1980	9
7104/7704A/7834/7844/7854/R7903 & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
7104/R836 ADJUSTMENT	10-05	MAR 7,1980	9
7313/7603/7613/7623A/7633/U973 INTERMITTENTS IN +5 SUPPLY	9-25	DEC 21,1979	20
7313/R 7613/R 7623/R 7633/R EMI MODIFICATION KIT	10-10	MAY 16,1980	9
7600 SERIES HORIZONTAL JITTER	7-05	MAR 4,1977	29
7603 CRT STATIC DISCHARGE	10-07	APR 4,1980	6
7603 FAN SYSTEM KIT	10-21	OCT 17,1980	16
7603 H.F. ADJUSTMENT	10-08	APR 18,1980	8
7603 PRODUCTION MOD, 30310 DEFICIENCY	7-30	DEC 9,1977	22
7603/7403N CAMERA POWER CABLE	8-10	APR 7,1978	19
7603/R CABLE CHANGE	10-06	MAR 21,1980	8
7603/R EMI MODIFICATION KIT	10-10	MAY 16,1980	9
7603/R7603 HIGH VOLTAGE CAPACITOR (C1241) FAILURES	9-22	NOV 16,1979	10
7623A/7633 STORAGE INCOMPATIBILITIES IN FAST MODES	10-01	JAN 11,1980	13
7623A/7633/7834 FLOOD GUN ANODE VOLTAGE SPECIFICATION WAIVER	10-22	OCT 31,1980	8
7623A/R, 7633/R GATED READOUT	10-17	AUG 22,1980	8
7623A/R, 7633/R MODIFICATION TO FRONT MESH CIRCUIT REMOVED	10-05	MAR 7,1980	10
7623A/R, 7633/R REDUCTION OF NOISE ON TRACE	9-25	DEC 21,1979	22
7633/R, 7623 A/R GATED READOUT	10-17	AUG 22,1980	8
7633/R7633 SERVICE MANUAL CHANGE	9-25	DEC 21,1979	23
7704A 7104 7834 7844 7854 R7903/7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
7704A/7104/7834/7844/7854/R7903 & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
7704A/7B53A INTENSIFIED MODE OPERATION	9-25	DEC 21,1979	23

WIZARDS WORKSHOP INDEX

7000 SERIES

TITLE	ISSUE	DATE	PAGE
7704A/R7903/7904 HI-VOLTAGE MULTIPLIER RELIABILITY PROBLEMS	7-27	NOV 11,1977	19
7834 -15V SUPPLY RESISTANCE CHECK	9-25	DEC 21,1979	23
7834 7104 7704A 7844 7854 R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
7834 STORAGE	7-07	APR 1,1977	21
7834 TRIGGER OSCILLATIONS (BELOW B010250)	7-10	MAY 13,1977	27
7834/7104/7704A/7844/7854/R7903 & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
7834/7633/7623A FLOOD GUN ANODE VOLTAGE SPECIFICATION WAIVER	10-22	OCT 31,1980	8
7834/7844/R7903/7904 WIRE LOOP INDUCTORS IN HF COMPENSATIONS	9-25	DEC 21,1979	24
7844 7104 7704A 7834 7854 R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
7844 INCORRECT PART NUMBER, MOUNTING SCREW FOR LV REGULATOR CHASSIS	9-23	NOV 30,1979	11
7844/7104/7704A/7834/7854/R7903 & 7904 DEFECTIVE CAPICATOR	10-10	MAY 16,1980	9
7844/7904 WRENCH FOR POWER ON SWITCH DODEC NUT	9-25	DEC 21,1979	24
7844/R, R7903 7904 TRANSFORMER REPLACEMENT	10-13	JUNE 27,1980	11
7854 7104 7704A 7834 7844 R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
7854 CALIBRATOR RISETIME AND FALLTIME	10-09	MAY 2,1980	5
7854 CONTROL RECTIFIER BOARD FAILURE	10-17	AUG 22,1980	8
7854 ROM BOARD JUMPER LOCATION	10-10	MAY 16,1980	10
7854/7104/7704A/7834/7844/R7903 & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
7904 5 VOLT LIGHT SUPPLY	10-06	MAR 21,1980	8
7904 H.F. ABERRATION SPECIFICATION CORRECTION	10-08	APR 18,1980	8
7904 H.F. ABERRATION SPECIFICATIONS	10-06	MAR 21,1980	8
7904 INCORRECT PART NUMBERS FOR LV REGULATOR MOUNTING HARDWARE	9-23	NOV 30,1979	12
7904/7104/7704A/7834/7844/7854/R7903 & DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
7A13 CALIBRATION PROCEDURE	7-32	DEC 23,1977	20
7A13 CALIBRATION PROCEDURE CORRECTION	8-01	JAN 20,1978	21
7A13 LOOSE CONNECTORS ON READOUT DISPLAY	10-05	MAR 7,1980	9
7A13 LOOSE CONNECTORS ON READOUT DISPLAY	9-23	NOV 30,1979	11
7A13 TRANSISTOR TYPE CHANGED FOR Q330, Q340, Q430 AND Q440	9-07	APR 20,1979	36
7A16A/7A26 INPUT CAPACITANCE INCREASE	9-25	DEC 21,1979	17
7A19 VARIABLE ATTENUATOR REPLACEMENT, HELPFUL HINT	7-09	APR 29,1977	16
7A22 U.S. NAVY INCOMING INSPECTION BANDPASS REJECTS	7-09	APR 29,1977	16
7A24 OSCILLATION IN ADD WITH TRIGGER SOURCE SET TO MODE	9-25	DEC 21,1979	18
7A26 B15XXXX AND B17XXXX INSTRUMENTS WITH B18XXXX MANUAL CHANGE INFORMATION	8-18	JUN 2,1978	13
7A26 H.F. ADJUSTMENT	10-11	MAY 30,1980	12
7AXX AND 7BXX PLUG-IN SIDE ELECTRICAL SHIELDS	10-18	SEPT 5,1980	8
7B10/7B15 7B10/7B15 POSSIBLE SWEEP OSCILLATIONS	10-09	MAY 2,1980	4
7B53A "B" SWEEP INOPERATIVE S/N B210000 & UP	10-10	MAY 16,1980	8
7B53A 7B71 7B921/A 7D11 HELIDIAL SETTINGS	10-14	JULY 11,1980	8

1 JANUARY 1981

PAGE 21

WIZARDS WORKSHOP INDEX

7000 SERIES

TITLE	ISSUE	DATE	PAGE
7B53A PROPAGATION DELAY	8-01	JAN 20,1978	22
7B71 7B53A 7B92/A 7D11 HELIDIAL SETTINGS	10-14	JULY 11,1980	8
7B92 TRIGGERING PROBLEMS	7-09	APR 29,1977	17
7B92/A 7BB53A 7B71 7D11 HELIDIAL SETTINGS	10-14	JULY 11,1980	8
7B92A -- 152-0153-00 VENDOR COMPATIBILITY	7-30	DEC 9,1977	21
7B92A TROUBLESHOOTING FIXTURE	8-05	MAR 3,1978	22
7D11 7B53A 7B71 7B92/A HELIDIAL SETTINGS	10-14	JULY 11,1980	8
7D12 A/D CONVERTER, U440, CORRECT PIN OUT ASSIGNMENT	10-17	AUG 22,1980	7
7D15 CALIBRATION PROCEDURE	7-11	MAY 27,1977	23
AUDIO CASSETTE TAPES AVAILABLE	7-03	FEB 4,1977	4
HARMONIC CONNECTORS AVAILABLE	8-04	FEB 17,1978	26
INTENSIFIED ZONE CONTRAST MODIFICATION FOR 7844/7904	7-05	MAR 4,1977	29
MOD #30219 TO 067-0587-01 AND 7A22	7-06	MAR 18,1977	19
R7844 RELIABILITY - MOD M30624	7-04	FEB 18,1977	15
R7903 7904 DEFECTIVE CAPACITOR	10-13	JUNE 27,1980	10
R7903 MANUAL CHANGE, CALIBRATION SECTION	9-25	DEC 21,1979	16
R7903/7104/7704A/7834/7844/7854/ & 7904 DEFECTIVE CAPACITOR	10-10	MAY 16,1980	9
REAR PANEL (PLUG-INS) MODIFIED	8-01	JAN 20,1978	20

WIZARDS WORKSHOP INDEX

MEDICAL PRODUCTS

COMMUNICATIONS DIVISION

TITLE	ISSUE	DATE	PAGE
067-0706-99 TEST UNIT MANUAL CORRECTION	10-22	OCT 31,1980	9
400 400 RECORDER MANUAL ERRORS	10-04	FEB 22,1980	8
400 CHART RECORDER GEAR PROBLEM	10-22	OCT 31,1980	9
400 MEDICAL MONITOR RECORDER COMBINATIONS	7-16	JUL 29,1977	18
400 MEDICAL RECORDER PRIOR TO B010600 REMOTE SAMPLE/MARK WIRING ERROR	7-15	JULY 22,1977	22
400 MEDICAL RECORDER PRIOR TO B010600 REMOTE SAMPLE/MARK	7-13	JUN 24,1977	26
400 MEDICAL RECORDER, DIGITAL PRINT PROBLEM	7-29	NOV 25,1977	7
400 MEDICAL RECORDER - NEW MANUAL 070-2429-00	8-06	MAR 10,1978	17
400 MEDICAL RECORDER, DIGITAL PRINT PROBLEM	7-29	NOV 25,1977	7
400 MEDICAL RECORDER - NEW MANUAL 070-2429-00	8-06	MAR 10,1978	17
400 MEDICAL RECORDER RUN CONTROL	8-11	APR 14,1978	9
400 MEDICAL RECORDER WRITING QUALITY	7-28	NOV 18,1977	15
400 OPT. 4 RECORDER WIRING ERROR	7-20	AUG 26,1977	10
400 PAPER DRIVE MOTOR P/N	9-16	AUG 24,1979	8
400 RECORDER, U1075 REPLACEMENT	10-05	MAR 7,1980	11
400 RECORDER TENSION GATE	10-16	AUG 8,1980	10
400 RECORDER TRIGGER PROBLEM	10-22	OCT 31,1980	9
400 RECORDER CHART RATE ADJUSTMENT	8-30	OCT 27,1978	27
400 RECORDER DRIVE MOTOR P/N	9-17	SEPT 7,1979	13
400 RECORDER FEMALE CONNECTOR	9-06	APR 6,1979	38
400 RECORDER IMPROVEMENTS	8-03	FEB 3,1978	11
400 RECORDER MODULES WILL CHANGE	7-27	NOV 11,1977	15
400 RECORDER MULTIPLEX CONCERN	8-32	NOV 24,1978	14
400 RECORDER NEW RUN CONTROL CARD	7-27	NOV 11,1977	16
400 RECORDER OVERPRINT	9-04	MAR 2,1979	16
400 RECORDER PRINT ERROR	9-06	APR 6,1979	38
400 RECORDER PRINT HEAD PART NUMBER	8-07	MAR 17,1978	17
400 RECORDER PRINT HEAD PLATEN	8-19	JUN 9,1978	20
400 RECORDER RUN CONTROL CORRECTION	9-02	FEB 2,1979	25
400 RECORDER STYLUS PART NUMBER	9-06	APR 6,1979	38
400 RECORDER STYLUS PART NUMBER	8-19	JUN 9,1978	21
400 RECORDER TRACE NOISE	8-28	SEPT 29,1978	23
400 SERIES MEDICAL MONITORS, UNDERSIZED CRT'S	10-22	OCT 31,1980	10
400 SERIES GALVANOMETER CARE AND HANDLING	7-02	JUN 21,1977	11
400 SERIES INTERIM MANUAL CALIBRATION PROCEDURE CORRECTION	7-02	JAN 21,1977	10
400 SERIES MEDICAL--INSTRUMENT COMBINATIONS	7-27	NOV 11,1977	13
400 SERIES MEDICAL MONITORS	7-24	OCT 7,1977	10
400 SERIES MEDICAL WIRING ERROR OF SOURCE SWITCH	7-02	JAN 21,1977	10
400 SERIES RECORDER MANUAL CORRECTION (PN 070-2145-00)	7-07	APR 1,1977	22
400 SERIES RECORDER PRINTOUT	7-10	MAY 13,1977	30
400 SERIES RECORDER POWER UPDATE	7-05	MAR 4,1977	30

WIZARDS WORKSHOP INDEX

MEDICAL PRODUCTS

TITLE	ISSUE	DATE	PAGE
400 SERIES SERVICE MANUAL	7-06	MAR 18,1977	23
401 DRM POWER SUPPLY SQUEGGING	10-11	MAY 30,1980	13
401 TO MONITOR BATTERY CONTROL	9-04	MAR 2,1979	17
401 TOP COVERS	8-22	JULY 7,1978	12
401/413/414 DIGITAL READOUT DISPLAY DEVICES	9-17	SEPT 7,1979	13
401/413/414 READOUT DEVICES	9-04	MAR 2,1979	17
401/413/OPT.2 SQI	9-09	MAY 18,1979	7
408 POWER CORD	10-12	JUNE 13,1980	7
408/412/414 D-CELL BATTERY PACK CONVERSION	10-04	FEB 22,1980	9
408/412/413/414 MED MON-CRT SOCKET RELIABILITY IMPROVEMENT	10-05	MAR 7,1980	13
408/412/414/S661 REPLACEMENT KIT	10-05	MAR 7,1980	12
408/412/414 CABINET FRAMES	10-11	MAY 30,1980	14
408/412/413/414 BATTERY CHARGE CURRENT CHANGE	9-04	MAR 2,1979	18
408/412/413/414 CHASSIS LEAKAGE CURRENT	9-15	AUG 10,1979	11
408/412/413/414 POWER WIRE TERMINATION STANDOFF	9-07	APR 20,1979	30
408/412/414 ARS GLITCH SUPPRESSION	9-15	AUG 10,1979	11
408/412/414 POWER SUPPLY IMPROVEMENT	9-04	MAR 2,1979	18
408/414 POWER SUPPLY CHANGE	10-23	NOV 21,1980	5
410 BATTERY PACK	9-16	AUG 24,1979	8
410 BATTERY POWER PACK REPLACEMENT	8-02	JAN 27,1978	10
410 CRT REPLACEMENT KIT	10-22	OCT 31,1980	10
410 LEAKAGE CURRENT	9-14	JUL 27,1979	13
410 LEAKAGE TEST UPDATE	9-16	AUG 24,1979	8
410 MEDICAL MONITOR SUPPORT	9-15	AUG 10,1979	12
410 PATIENT CABLES	10-14	JULY 11,1980	9
412/413/414 VERTICAL OUTPUT TRANSISTORS	8-19	JUN 9,1978	21
413 B/B CHANGE (ERRATA)	8-21	JUN 30,1978	18
413 B/B CHANGE	8-19	JUN 9,1978	22
413 CIRCUIT BOARD RETAINER	7-25	OCT 21,1977	10
413 ECG LEAD FAULT IMPROVEMENT	9-04	MAR 2,1979	19
413 ECG NOISE	8-10	APR 7,1978	10
413 EMI IMPROVEMENT	10-19	SEPT 19,1980	15
413 EMI IMPROVEMENT (CORRECTION)	10-22	OCT 31,1980	10
413 GLITCH CAUSED BY 555 TIMES	9-24	DEC 14,1979	10
413 IMPROVEMENTS	8-04	FEB 17,1978	16
413 INSPIRATION SENSITIVITY	9-06	APR 6,1979	39
413 KIT 040-0855-00	8-08	MAR 24,1978	9
413 MAIN BOARD, 670-5068-00, CHANGE	8-06	MAR 10,1978	17
413 MECHANICAL PART CHANGES	9-04	MAR 2,1979	19
413 MEDICAL MONITOR AUDIO TAPES AVAILABLE	7-20	AUG 26,1977	10
413 MEDICAL MONITOR MANUAL ERROR	7-15	JULY 22,1977	22
413 MEDICAL MONITOR WIRING ERROR	7-13	JUN 24,1977	26

WIZARDS WORKSHOP INDEX

MEDICAL PRODUCTS

TITLE	ISSUE	DATE	PAGE
413 MONITOR - POWER SUPPLY MODIFICATION (CODE 18)	10-12	JUNE 13,1980	8
413 POWER SUPPLY KIT	10-14	JULY 11,1980	10
413 PRESSURE CIRCUIT PROTECTION	9-04	MAR 2,1979	20
413 READOUT IMPROVEMENT	9-04	MAR 2,1979	20
413 RESPIRATION	10-04	FEB 22,1980	11
413 RESPIRATION MICROPHONICS	10-09	MAY 2,1980	6
413 RESPIRATION WAVEFORM IMPROVEMENT	9-04	MAR 2,1979	21
413/414 GAUGE FACTOR	9-04	MAR 2,1979	21
413/414 POWER SUPPLY TROUBLESHOOTING	9-10	JUN 1,1979	7
413/414 TEMPERATURE CIRCUIT CALIBRATION RESISTORS	8-18	JUN 2,1978	7
413/414 VERTICAL OFFSET	9-01	AUG 10,1979	12
413A QUESTIONS AND ANSWERS	10-24	DEC 12,1980	8
414 - NOISE ON THE PULSE INPUT	7-07	APR 1,1977	22
414 MAIN CIRCUIT BOARD	10-24	DEC 12,1980	10
414 MEDICAL MONITOR (OPT. 4)	10-11	MAY 30,1980	15
414 MOD TO RATE CONVERTER	9-05	MAR 16,1979	22
414 POWER CORD	10-11	JUNE 13,1980	7
414 RATE OVERRANGE INTERMITTENT - ERRATA	9-04	MAR 2,1979	22
414 RATE OVERRANGE INTERMITTENT	8-32	NOV 24,1978	15
414 RELIABILITY IMPROVEMENT (ERRATA)	8-19	JUN 9,1978	20
414 RELIABILITY IMPROVEMENT	8-17	MAR 26,1978	6
414 VERTICAL OUTPUT IMPROVEMENT	9-05	MAR 16,1979	22
414/408 POWER SUPPLY CHANGE	10-23	NOV 21,1980	5
606 MONITOR, HIGH VOLTAGE SHIELD	7-31	DEC 16,1977	16
AUDIO CASSETTE TAPE AVAILABLE	7-07	APR 1,1977	9
BATTERY PARTS AND MAINTENANCE	8-11	APR 14,1978	8
BIOPHYSICAL MEASUREMENTS CONCEPT BOOK	7-08	APR 15,1977	12
CHART PAPER TENSION GATE - TEK MADE MODULE	8-10	APR 7,1978	10
CORRECTING MED. MONITORS TO RECORDER TEST BOARD SOB OF 12-2-77, ISSUE 13-77	7-31	DEC 16,1977	17
CORRECTION ON 400 RECORDER IMPROVEMENTS ARTICLE	8-05	MAR 3,1978	17
CRT SOCKET KIT P/N 040-0876-01	10-16	AUG 8,1980	10
DIGITAL READOUT MODULE (DRM)	8-06	MAR 10,1978	14
DIGITAL VOLTMETER ANALOG IC SOCKET	8-30	OCT 27,1978	26
ECG SIGNAL GETTING INTO PULSE ON 414	7-07	APR 1,1977	22
GOULD-STATHAM PRESSURE TRANSDUCERS	10-18	SEPT 5,1980	10
IC SOCKET REPLACEMENT PARTS	9-05	MAR 16,1979	17
LITTLEFUSE FUSES 0.2A, 250V, 12 SEC. 3AG, P/N 159-0044-00	8-08	MAR 24,1978	8
MEDICAL CAL MONITOR MOUNTING	7-29	NOV 25,1977	6
MEDICAL MAINTENANCE	7-26	OCT 28,1977	22
MEDICAL MONITOR ACCESSORIES	10-11	MAY 30,1980	13
MEDICAL MONITORS SYSTEM CALIBRATION MANUAL	10-13	JUNE 27,1980	13
MEDICAL MONITOR PRESSURE CALIBRATIONS	8-07	MAR 17,1978	16

1 JANUARY 1981

WIZARDS WORKSHOP INDEX

MEDICAL PRODUCTS

TITLE	ISSUE	DATE	PAGE
MEDICAL MONITOR MOUNTING ADAPTER 014-0054-00	7-29	NOV 25,1977	6
MEDICAL MONITORS LOSING INTENSITY	7-29	NOV 25,1977	5
MEDICAL MONITOR GAUGE FACTOR MODS	8-24	AUG 4,1978	12
MEDICAL MONITOR SOCKET REPLACEMENT	8-20	JUN 23,1978	19
MEDICAL MONITOR STERILIZATION	7-32	DEC 23,1977	10
MEDICAL MONITOR BATTERY SOURCE	7-29	NOV 25,1977	5
MEDICAL MONITOR GAUGE FACTOR MODS	8-24	AUG 4,1978	12
MEDICAL MONITOR MECHANICAL CHANGES	8-06	MAR 10,1978	16
MEDICAL PRODUCTS-REFER OUTSIDE INQUIRIES TO BEAVERTON	8-13	APR 28,1978	17
MEDICAL PRODUCTS - WARRANTY POLICY (DOMESTIC ONLY)	9-25	DEC 21,1979	25
MEDICAL PRODUCTS - REFER OUTSIDE INQUIRIES TO BEAVERTON	8-13	APR 28,1978	17
MEDICAL TEMPERATURE CALIBRATION	8-07	MAR 17,1978	16
MEDICAL TRANSDUCERS - WARRANTY	9-04	MAR 2,1979	16
MONITOR BATTERY CHARGE FIXTURE	9-05	MAR 16,1979	20
MOUNTING ADAPTER FRICTION SCREWS	8-24	AUG 4,1978	12
POWER SUPPLY CAPACITOR CHANGE	9-02	FEB 2,1979	25
PULSE OSCILLATIONS	8-30	OCT 27,1978	26
RESPIRATION HETERODYNING	8-30	OCT 27,1978	27
RESPIRATION WAVEFORM SPIKES	8-30	OCT 27,1978	27
SERVICE COST FORECAST AND DEMO SUPPORT PACKAGE ERROR	8-08	MAR 24,1978	9
SWITCHES NOW FROM NEW VENDOR	8-31	NOV 10,1978	19
TENSION ADJUST NEW TEK-MADE MODULE	8-11	APR 14,1978	8
VIDEO CASSETTES AVAILABLE	7-07	APR 1,1977	9
WIRING ERROR ON NEW TEK MADE RECORDER MODULE	8-07	MAR 17,1978	17

SPECTRUM ANALYZERS

TITLE	ISSUE	DATE	PAGE
1501 1502 1503 BATTERY METER REPLACEMENT KITS	10-11	MAY 30,1980	16
1501/1503 NTENSITY RANGE IMPROVEMENT	10-04	FEB 22,1980	12
1502 1503 VERTICAL AMP/SLOW RAMP CIRCUIT BOARD REPLACEMENT	10-11	MAY 30,1980	17
1502 STATIC SUPPRESSOR	10-24	DEC 12,1980	13
1502/1503 IMPROPER CHARGING OF BATTERY PACKS	10-02	JAN 25,1980	13
1502/1503 OUTPUT AMPLIFIER CIRCUIT BOARD REPLACEMENT	10-04	FEB 22,1980	13
1502/1503 HIGH VOLTAGE POWER CIRCUIT BOARD REPLACEMENT	10-04	FEB 22,1980	12
1502/1503 FUSED BATTERY PACKS	10-23	NOV 21,1980	15
1503 OPTION 1/TEST PULSE LENGTH SELECTOR PUSHBUTTON	10-05	MAR 7,1980	18
1503 REPLACEMENT OF Q1558 OR Q1578	10-11	MAY 30,1980	17
492 - 33KHZ POWER SUPPLY SPURS	10-16	AUG 8,1980	11
492/492P SER VOL #2 - POWER SUPPLY DIAGRAM CORRECTION (REF PULL-OUT)	10-18	SEPT 5,1980	A-1
492/492P SERVICE POINTS	10-23	NOV 21,1980	15
5L4N NEW LATCH ASSY "ADDENDUM TO W2 ARTICLE-MAR 7,1980"	10-07	APR 4,1980	7
5L4N NEW LATCH ASSEMBLY	10-05	MAR 7,1980	14
5L4N REPLACEMENT KIT FOR CENTER FREQUENCY DIAL DRIVE GEAR	10-05	MAR 7,1980	15
5L4N REPLACEMENT KIT FOR K160 RELAY	10-04	FEB 22,1980	13
7L12 & 7L13 FL370 REPLACEMENT	8-20	JUN 23,1978	22
7L12 MOD HB	9-04	MAR 2,1979	26
7L12 THREE-LEGGED REGULATOR ON REF LEVEL READOUT INSERTED WRONG (M32661)	8-13	APR 28,1978	22
7L12, 7L13, L-1, & L-2 RELAY RELIABILITY IMPROVEMENT	7-10	MAY 13,1977	14
7L12/7L13 PART REPLACEMENT KIT FOR FL360	10-04	FEB 22,1980	14
7L12/7L13 ATTENUATORS	10-03	FEB 8,1980	15
7L12/7L13 INTERMITTENT EDGE CARD CONNECTOR	9-15	AUG 10,1979	13
7L12/7L13/7L18 INTERNAL RESOLUTION FILTER SHAPE SPECIFICATIONS	9-09	MAY 18,1979	9
7L13 PROM'S	8-12	APR 21,1978	15
7L13 REGULATOR MOD (32662) INSTALLED WRONG	8-15	MAY 12,1978	12
7L13, REPLACEMENT OF YIG OSCILLATOR	10-01	MAR 7,1980	16
7L18 - DIFFICULTY REMOVING FROM MAINFRAMES	9-05	MAR 16,1979	32
7L18 INTERMODULATION CHECK	8-11	APR 14,1978	9
7L18 MOD FB	9-04	MAR 2,1979	26
7L18 REPLACEMENT PARTS KIT FOR U825	10-04	FEB 22,1980	14
7L18 RETURN FOR REPAIR LABELS	8-18	JUN 2,1978	9
7L18 RF CABLES	10-03	FEB 8,1980	15
7L5 CHANGE TO SWEEP OFFSET CIRCUIT	10-05	MAR 7,1980	15
7L5 CR836 MARKED BACKWARDS ON PRINTED CIRCUIT BOARD	9-05	MAR 16,1979	32
7L5 MODIFICATION TO REPLACE U2235 OR U5070	9-05	MAR 16,1979	31
7L5 MODIFICATION TO REPLACE U830	9-05	MAR 16,1979	31
7L5 NEW STORAGE BOARD, ADDENDUM TO JAN 12, 1979 ARTICLE	10-06	MAR 21,1980	9
7L5 NEW STORAGE BOARD, 040-0672-01, PRICE INCREASE	10-22	OCT 31,1980	11
7L5 OPTION 21, CHANGE TO SWEEP OFFSET CIRCUIT	10-05	MAR 7,1980	17

WIZARDS WORKSHOP INDEX

SPECTRUM ANALYZERS

TITLE	ISSUE	DATE	PAGE
7L5 OPTIONS	8-20	JUN 23,1978	22
7L5 POTENTIAL RELIABILITY PROBLEM	7-06	MAR 18,1977	10
7L5 POTENTIAL RELIABILITY PROBLEM	7-10	MAY 13,1977	12
7L5 PRESET R665 AND R664	8-13	APR 28,1978	21
7L5 SPECIFICATION CHANGE	9-09	MAY 18,1979	8
7L5 SPECTRUM ANALYZER COMPATIBILITY PROBLEM	7-04	FEB 18,1977	12
7L5 STORAGE BOARD	9-01	JAN 12,1979	16
7L5 TRANSVERSE VERTICAL INTERFACE BOARD, P/N 670-3588-00	9-05	MAR 16,1979	32
7L5, R4722 ELECTRICAL PARTS LIST & SCHEMATIC CHANGE	9-09	MAY 18,1979	8
7L5,OPTION 25 TRACKING GENERATOR AVAILABLE AS KIT	10-01	JAN 11,1980	16
AN EXPLANATION OF THE MISSING SEGMENT IN THE 7L5 SPECTRUM ANALYZER DIGITAL STORA	7-15	JULY 22,1977	14
LEVELING OF HEWLETT PACKARD HP 8620C SYSTEM	10-23	NOV 21,1980	6
MEASURING HARMONIC DISTORTION WITH A SPECTRUM ANALYZER - CORRECTION	7-06	MAR 18,1977	24
PA1, REPLACEMENT OF Q3021, Q3022 AND Q4021	10-11	MAY 30,1980	16
RECOMMENDED EQUIPMENT FOR SIGNAL INSERTION ON SPECTRUM ANALYZERS	9-18	SEPT 21,1979	10
SPECTRUM ANALYZER SPOT-O-GOLD (SOG) CONNECTORS	10-22	OCT 31,1980	11
SPECTRUM ANALYZER C95 SOCKET REPAIR	10-22	OCT 31,1980	11
TUTORIAL - MEASURING HARMONIC DISTORTION WITH A SPECTRUM ANALYZER	7-05	MAR 4,1977	1

TITLE	ISSUE	DATE	PAGE
1441 1430 1440 1460 1461 MISSNG FIBER WASHER ON PWR SUPPLY BOARD	10-15	JULY 25,1980	10
140 SERIES - REGULATION OF +10V SUPPLY DURING CRYSTAL OVEN WARM-UP	9-18	SEPT 21,1979	14
140 SERIES - SUBCARRIER OSCILLATOR REPLACEMENT KITS	8-25	AUG 18,1978	10
140/144, SUBCARRIER OSCILLATOR REPLACEMENT	10-01	JAN 11,1980	18
1401 1401A BATTERY CHARGE LEVEL METER REPLACEMENT KIT	10-09	MAY 2,1980	9
1405 PARTS KIT FOR REPLACEMENT OF U500	10-09	MAY 2,1980	9
1405/VAR IN VF IN CR170,172,174,176 CAUSE SAMPL GATE IMBALANCE	10-25	DEC 19,1980	8
1410 - TSG-1 BELOW S/N B010169, RESIDUAL SUBCARRIER ON OUTPUT ELIMIN	7-27	NOV 11,1977	18
1410 - U800 MICA INSULATOR REPLACEMENT	8-16	MAY 19,1978	21
1410 - WIRING CORRECTION TO PROTECT 155-0145-00	8-32	NOV 24,1978	18
1410 -- PREMATURE FAILURE OF U-800	7-10	MAY 13,1977	14
1410 AND 1411 - CORRECT WIRING OF INTERCONNECT BOARD TO SUBCARRIER INPUT BOARD	8-23	JUL 21,1978	26
1410 AND 1411 SCHEMATIC CORRECTION	8-29	OCT 13,1978	14
1410 BLACK BURST - MOD FOR VARIABLE BLANKING	9-06	APR 6,1979	48
1410 BLANK PANEL PART NUMBER INFORMATION	7-04	FEB 18,1977	12
1410 CALIBRATION	7-31	DEC 16,1977	21
1410 LINE SELECTOR CIRCUIT BOARD	7-18	AUG 12,1977	10
1410 MANUAL	7-03	FEB 4,1977	14
1410 MANUAL CHANGE/OPERATOR TRAP	8-10	APR 7,1978	19
1410 MODULAR REPAIR	7-24	OCT 7,1977	11
1410 OSCILLATOR INSTABILITY	7-15	JULY 22,1977	16
1410 SERIES - SPG11, 12, 22 CAPACITOR FIT PROBLEM	10-22	OCT 31,1980	14
1410 SERIES/EXTENDER BOARDS AVAILBLE FOR SPG,TSG,PLUG-INS.	10-16	AUG 8, 1980	12
1410 SERIES - CHASSIS TOP COVER	9-03	FEB 16,1979	28
1410 SHORT TERM FREQUENCY STABILITY	7-16	JULY 29,1977	13
1410 SPG, TSG SERIES DEFECTIVE TRIMMER POT, PART NUMBER 311-1915-00	10-09	MAY 2,1980	9
1410/1411 - U129/U119 IC SOCKETS	9-02	FEB 2,1979	39
1410/1411 NEW PART NUMBER FOR CABINET FRAME	9-07	APR 20,1979	33
1410/1411 POWER SUPPLY CURRENT LIMIT	8-07	MAR 17,1978	19
1410/1411 POWER SUPPLY MODIFICATION KIT	9-06	APR 6,1979	50
1410/1411 SERIES - SPG TIMING ERRORS CAUSED BY TEMPERATURE SENSITIVE 74LS163	8-27	SEPT 15,1978	27
1410/1411 SPRING CLIPS FOR REMOTE PROGRAM PLUG	8-05	MAR 3,1978	21
142 CONVERGENCE - MANUAL CHANGE INFORMATION	8-16	MAY 19,1978	13
142,SUBCARRIER OSCILLATOR REPLACEMENT	10-01	JAN 11,1980	18
1420 POWER SUPPLY NOISE	10-22	OCT 31,1980	15
1420 SYNC STRIPPER MALFUNCTION AT HIGH TEMPERATURES	10-05	MAR 7,1980	21
1420 TRANSISTOR IDENTIFICATION	7-01	JAN 14,1977	12
1420-21-22 T.O. 126 LEAD CONFIGURATION ERROR	7-05	MAR 4,1977	23

TITLE	ISSUE	DATE	PAGE
1420/1421/1422 CRYSTAL SOCKET CHANGE	8-23	JUL 21,1978	27
143 - CIRCUIT BOARD PART NUMBER CHANGES	8-27	SEPT 15,1978	26
143 - RCA "GOLD CHIP" OP-AMP REPLACEMENT	8-27	SEPT 15,1978	26
143 CAPACITOR INSTALLED BACKWARDS	8-09	MAR 31,1978	16
143 INTERMITTENT POWER SUPPLY	9-06	APR 6,1979	45
1430 1440 1441 1460 1461 -MSSNG WASHR ON PWR SUPP BOARD, PART NO CORR	10-19	SEPT 19,1980	17
1430 INTERFACE	8-14	MAY 5,1978	12
1430 WIRING ERROR ON LINE SELECT SWITCH	9-04	MAR 2,1979	27
1430/1440/1441/1460/1461 MSG FIBER WASHER ON POWER SUPPLY BRD	10-15	JULY 25,1980	10
1430/1441 INCREASE SYNC LOCK UP RANGE	9-14	JULY 27,1979	14
1430/1441/1461 DIFFERENTIAL PHASE ADJUSTMENT	8-05	MAR 3,1978	21
1440 1430 1441 1460 1461 MISSNG FIBER WASHER ON PWR SUPPLY BOARD	10-15	JULY 25,1980	10
1440 1441 1430 1460 1461 -MISSNG WASHR ON PWR SUPP BOARD, PART NO CORR	10-19	SEPT 19,1980	17
1440 4H OSCILLATOR ADJUSTMENT RANGE	10-22	OCT 31,1980	16
1440 DECODED BOARD - VIRS RECO.	9-08	MAY 4,1979	18
1440 DECODER BOARD - VIRS RECOGNITION PROBLEM ADDENDUM	9-11	JUN 15,1979	6
1440 I2R, I3B, I3C VARIABLE SYNC WIDTH MODIFICATION	10-03	FEB 8,1980	16
1440 MANUAL CORRECTION	7-25	OCT 21,1977	13
1440 MOD 12R-13B-13C - MANUAL CORRECTION	8-19	JUN 9,1978	24
1440 MOD 13B SHIPPING ERROR	7-29	NOV 25,1977	10
1440 MODS 12R, 13R, 13C	10-22	OCT 31,1980	15
1440 ZERO CARRIER CHECK	7-03	FEB 4,1977	14
1440/741 -OP. -AMP. REPLACEMENT	7-06	MAR 18,1977	12
1440/741 OP - AMP FAILURE (156-0158-00)	7-05	MAR 4,1977	24
1441 - INTERMITTENT GROUND CONNECTIONS	8-25	AUG 18,1978	11
1441 SUBCARRIER LOCK UP OUT OF PHASE ELIMINATED	7-13	JUNE 24,1977	23
1441/1461 - RCA "GOLD CHIP" OP-AMP REPLACEMENT	8-27	SEPT 15,1978	27
145-M, SUBCARRIER OSCILLATOR REPLACEMENT	10-01	JAN 11,1980	18
145/R145 OSCILLATOR QUILTS AFTER TURNED OFF AND ON	7-07	APR 1,1977	17
1450 CABLE CLAMP LOOSENESS PROBLEM	10-23	NOV 21,1980	20
1450 PART NUMBER CHANGE FOR 151-0472-00	10-03	FEB 8,1980	19
1450 SERIES/AVAILABLE IN THE FIELD	10-21	OCT 17,1980	17
1450, PART NUMBER CHANGE FOR 151-0472-00	10-01	JAN 11,1980	27
1450-1 POWER LEVEL ADJUSTMENT	10-25	DEC 19,1980	10
145M - RCA "GOLD CHIP" OP-AMP REPLACEMENT	8-27	SEPT 15,1978	26
146, SUBCARRIER OSCILLATOR REPLACEMENT	10-01	JAN 11,1980	19
1460 1430 1440 1441 1461 MISNG FIBER WASHER ON PWR SUPPLY BRD	10-15	JULY 25,1980	10
1460 1461 1430 1440 1441 -MISSNG WASHR ON PWR SUPP BOARD, PART NO CORR	10-19	SEPT 19,1980	17
1460/BURST GAIN "BOUNCE" WITH SOUND IN SYNC	10-13	JUNE 27,1980	16

WIZARDS WORKSHOP INDEX

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
1461 - TEKTRONIX PART NUMBER FOR PROGRAMMED MICROCIRCUIT	6-27	SEPT 15,1978	28
1461 1430 1440 1441 1460 MISSNG FIBER WASHER ON PWR SUPPLY BRD	10-15	JULY 25,1980	10
147/149 PULSE TO BAR RATIO & CHROMA GAIN MEASUREMENT	9-14	JULY 27,1979	14
147/149A RIPPLE SPECIFICATIONS	10-25	DEC 19,1980	7
1470 CRYSTAL DRIFT	7-15	JULY 22,1977	16
1470 CRYSTAL DRIFT/1441 HUM/1410 SUBCARRIER PHASING	7-15	JULY 22,1977	17
1470 CRYSTALS P/N 158-0116-00	7-30	DEC 9,1977	19
1470 H. SYNC PROBLEM	7-04	FEB 18,1977	12
1470 LOSS OF FLATNESS IN MULTIBURST MODE	10-06	MAR 21,1980	11
1470 TROUBLESHOOTING HINT FOR LOSS OF SYNC IN GEN LOCK MODE	10-01	JAN 11,1980	27
1470/1474 CHANGES TO COLOR PHASE CONTROLLER BOARD	10-01	JAN 11,1980	28
1470/1474 FREQUENCY STABILIZATION	9-03	FEB 16,1979	28
1470/1474 POWER SUPPLY REGULATION	9-03	FEB 16,1979	28
1474 BURST GATE COINCIDENT WITH HORIZONTAL SYNC	10-02	JAN 25,1980	18
147A 148 148M 149A UNRELIABLE CAPACITOR, P/N 283-0192-00	10-15	JULY 25,1980	13
147A BREEZEWAY SPECS	10-22	OCT 31,1980	13
147A/148M/149A UNRELIABLE CAPACITOR,P/N 283-0192-00 (CORR)	10-19	SEPT 19,1980	16
147A/149A TEMPORARY CHANGE OF PART NUMBER FOR PWR LAMP ASSY	10-15	JULY 25,1980	14
147A/149A CORRECTION TO EXTERNAL VITS GAIN ADJUST	10-10	MAY 16,1980	12
147A/149A BREEZEWAY SPECS (CORRECTION)	10-24	DEC 12,1980	15
147A/149A MOD G8C, G8E, G9V SHIPPED TO CANADA	7-32	DEC 23,1977	18
147A/149A OSCILLATIONS ON THE SYNC PULSE	9-06	APR 6,1979	45
147A/149A VIDEO LINE 21, DELETE COLOR BARS OUT OF SPEC	9-06	APR 6,1979	46
147A/149A/650HR SERIES, CRYSTAL MAY SHORT CIRCUIT	10-24	DEC 12,1980	16
148 - R294 PART NUMBER CHANGE	8-23	JUL 21,1978	25
148-0034-XX RELAY REPLACEMENT	8-06	MAR 10,1978	18
148-0034-XX RELAYS REPLACEMENT	7-27	NOV 11,1977	18
148/148M,149A/147A UNRELIABLE CAPACITOR P/N 283-0192-00	10-15	JULY 25,1980	13
1480 - CORRECTED PART NUMBER FOR LATCH INDEX	8-18	JUN 2,1978	11
1480 C/R SERIES - IMPROVED 0.1 MICROSECOND SWEEP LINEARITY	9-14	JULY 27,1979	15
1480 CRT SETUP	7-18	AUG 12,1977	10
1480 INTERMITTENT TRIGGERS, B06000 AND UP	8-15	MAY 12,1978	14
1480 OPT. 8 - ERRATIC OPERATION OF 2 FIELD DISPLAY	8-22	JUL 7,1978	19
1480 OPTION 6 - BNC TO WECO ADAPTER	8-18	JUN 2,1978	11
1480 SERIES/DEFECTIVE HIGH VOLTAGE TRANSFORMER	10-12	JUNE 13,1980	9
1480 SERIES/SPACER REQUIRED FOR PUSHBUTTON SWITCHES	10-12	JUNE 13,1980	10
1480 SERIES CORRCTION FOR INCOMPLETE D.C. RESTORER	10-08	APR 18,1980	11
1480 SERIES, PART NUMBER FOR RUBBER WASHER UNDER CRT BEZEL	10-09	MAY 2,1980	10
1480 SERIES, D.C. RESTORER, WIZARD CORRECTION	10-23	NOV 21,1980	21
1480 SERIES - CANCEL INSTRUMENT MODIFICATION NOTICE	8-34	DEC 22,1978	21

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
1480 SERIES - CRT NECK CLAMP ADJUSTMENT	8-30	OCT 27,1978	34
1480 SERIES - HORIZONTAL TIMING PROCEDURE CHANGE	9-06	APR 6,1979	50
1480 SERIES - MOD KITS FOR REPLACEMENT OF VERTICAL CIRCUIT BOARDS	8-23	JUL 21,1978	27
1480 SERIES - SYNC SEPARATOR MOD, B06 AND UP	9-08	MAY 4,1979	20
1480 SERIES - VERTICAL GAIN DRIFTS WITH TEMPERATURE CHANGE	8-30	OCT 27,1978	35
1480 SERIES FAILURE TO FREE RUN IN TWO FIELD DISPLAY	9-18	SEPT 21,1979	15
1480 SERIES FRONT PANEL MOUNTED POTS	7-06	MAR 18,1977	12
1480 SERIES INSTRUCTION MANUAL FOR SERIAL NUMBER B06 AND UP	9-08	MAY 4,1979	20
1480 SERIES INTERMITTENT TRIGGERING IN CAL MODE	9-13	JULY 13,1979	8
1481/1485 OPTION 08 INTERMITTENT SINGLE FRAME RECOGNITION	10-19	SEPT 19,1980	20
149A,147A,148/148M UNRELIABLE CAPACITOR, P/N 283-0192-00	10-15	JULY 25,1980	13
149A/R149A NOISE SPIKE DURING VERTICAL BLANKING COLOR BARS	9-13	JULY 13,1979	9
1500 SERIES - SEALING BATTERY PACKS	9-03	FEB 16,1979	30
155-0032-01 REPLACED IN TV PRODUCTS	10-03	FEB 8,1980	19
155-0147-00, 155-0147-02,050 REPLACEMENT KITS FR TV PRODUCTS	10-09	MAY 2,1980	11
156-0388-00 DISQUALIFIED VENTOR	9-18	SEPT 21,1979	13
1900 INSTRUCTION MANUAL CORRECTION	10-24	DEC 12,1980	17
1900/CALIBRATION PRECAUTIONS	10-17	AUG 22,1980	9
1900/OPERATING PRECAUTIONS FOR 1900 TEST INSERTION GEN	10-13	JUNE 27,1980	14
1900/SUBCARRIER OUT TO FL/FELD OUT BRST PHSE RELTNSHIP MAY BE RANDOM	10-20	OCT 3,1980	12
1900/SUBCARRIER OUT/FULL FIELD OUT BURST PHASE RELATIONSHIP RANDON (CORN 1	10-22	OCT 31,1980	17
1980 POWER-UP DIAGNOSTICS	10-23	NOV 21,1980	22
290-0117-00 HIGH FAILURE RATE IN 670A AND 520 SERIES	8-15	MAY 12,1978	14
520 A CALIBRATION PROCEDURE CHANGE	10-08	APR 18,1980	9
520 SERIES DIFF GAIN TRACE NOISE	10-23	NOV 21,1980	16
520/R520 NTSC VECTORSCOPE	10-04	FEB 22,1980	20
520A ACCESS DOOR SLIDE	7-21	SEPT 9,1977	14
520A REPLACEMENT OF C1423	8-01	JAN 20,1978	19
520A SERIES, 1420 SERIES, INSULATORS FOR CRYSTALS	10-01	JAN 11,1980	19
520A SERIES, ELIMINATION OF "NEWTON RINGS" ON CRT SCALE	10-05	MAR 7,1980	20
520A/ PART NUMBER FOR SLIDE DOOR TRACK SPACER	10-14	JULY 11,1980	11
520A/521A/522A CHANGES	8-07	MAR 17,1978	18
520A/521A/522A CHANGES (CORRECTION)	8-13	APR 28,1978	23
520A/528/1480 SERIES - 283-0071-00 AND 283-0162-00	9-19	OCT 5,1979	7
520A/R520A, PART NUMBER CHANGE FOR PUSH BUTTON KNOBS	10-08	APR 18,1980	10
528 - C512 INTERMITTENT CONNECTION	8-28	SEPT 29,1978	27
528 - PART NUMBER CHANGE FOR HORIZONTAL OUTPUT TRANSISTOR	10-15	JULY 25,1980	14
528 - RGB RELAY - K370 MAY CAUSE INTERMITTENT OR TEMPERATURE RELATED MALFUNCTION	9-19	OCT 5,1979	8

WIZARDS WORKSHOP INDEX

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
528 - RINGING BETWEEN SYNC PULSE AND BURST	8-18	JUN 2,1978	10
528 INSUFFICIENT FOCUS CONTROL	7-01	JAN 14,1977	12
528 OPTION 2 PARTS LIST	8-30	OCT 27,1978	34
528 POWER SUPPLY - BURNED IN PART FOR C472	9-15	AUG 10,1979	16
528 Q520 RELIABILITY	10-25	DEC 19,1980	8
528 RELIABILITY IMPROVEMENT MOD, M24530	7-05	MAR 4,1977	24
528 RESISTOR RELIABILITY PROBLEM	10-22	OCT 31,1980	12
528 SYNC SWITCH & DC RESTORER SWITCH CHANGED TO CORRECT INTER. MALFCTN.	10-08	APR 18,1980	10
528 TRANSISTOR HEAT SINK CHANGES	9-03	FEB 16,1979	27
528 UNDERRATED POWER SUPPLY CAPACITOR C472	10-01	JAN 11,1980	20
528 VERTICAL, NOISE ON TRACE	10-23	NOV 21,1980	18
529/RM529 UPDATE FOR CRT REPLACEMENT KIT	10-08	APR 18,1980	10
630, EHT SUPPLY PART NUMBER	10-01	JAN 11,1980	20
632 MONITORS C495 CHANGES	7-21	SEPT 9,1977	15
650 EHT AND 741 OP. AMP FAILURES	7-04	FEB 18,1977	13
650 HR SERIES - MANUAL CORRECTION	8-32	NOV 24,1978	17
650 HR, PART NUMBER FOR CRT	10-01	JAN 11,1980	20
650 SERIES IMPROVED CONVERGENCE PROCEDURE	8-16	MAY 19,1978	15
650 SERIES RELIABILITY MOD KIT UPDATE	7-05	MAR 4,1977	25
650 SERIES: WIRE CRIMP PROBLEM	8-14	MAY 5,1978	12
650/650A POWER SUPPLY BOARD SHORTING HAZARD	7-11	MAY 27,1977	16
650/650A/650HR SERIES EHT	10-20	OCT 3,1980	11
650/670 YOKE: GLUE REMOVAL	8-20	JUN 23,1978	23
650/670/650A/670A COLOR TEMPERATURE SETUP LEVELS	7-10	MAY 13,1977	15
650A - APERTURE SWITCH	8-18	JUN 2,1978	11
650A - BLUE ONLY MALFUNCTION	7-12	JUNE 10,1977	17
650A MANUAL	7-06	MAR 18,1977	13
650A SERIES/DEFECTIVE CAPACITORS P/N 290-0521-00	10-20	OCT 3,1980	11
650A SERIES, CRT PART NUMBER CHANGE	10-01	JAN 11,1980	21
650A SERIES - +5 VOLT FUSE BLOWING	9-05	MAR 16,1979	33
650A SERIES - MOD TO ELIMINATE EXCESSIVE ELECTRO MAGNETIC ...CUSHION TRANSFORMER	9-08	MAY 4,1979	16
650A SERIES - SLIGHT HOOK IN VERTICAL CONVERGENCE LINES	9-10	JUN 1,1979	9
650A SERIES - VISIBLE LINE ON CRT	8-19	JUN 9,1978	24
650A SERIES CIRCUIT BOARDS COMPATIBLE WITH 650HR SERIES	9-08	MAY 4,1979	16
650A SLIDE ASSEMBLY	7-22	SEPT 23,1977	11
650A/650HR SERIES, MODIF TO REEVENTP PSPOTNBURNGTOFUCRTNPHOSPHOR	10-11	MAY 30,1980	19
650A/650HR SERIES, PARTS KITS AVAIL. TO PREVENT SPOT BURNING OF CRT	10-23	NOV 21,1980	20
650A/651A/652A/653A COLOR TEMPERATURE SETUP	7-31	DEC 16,1977	21
650A/653A SERIES - CONVERGENCE IMPROVEMENT	8-23	JUL 21,1978	26
650A/670A DEFECTIVE EHT'S	10-16	AUG 8, 1980	12

1 JANUARY 1981

PAGE 33

WIZARDS WORKSHOP INDEX

TELEVISION PRODUCTS

TIITLLE	ISSUE	DATE	PAGE
650A/670A COLOR MONITORS, PART NO CHNGE FOR Q5126/Q5915/Q6137	10-11	MAY 30, 1980	24
650A/670A SYNC STRIPPER MALFUNCTION AT HIGH TEMPERATURES	10-01	JAN 11, 1980	21
650A/670A SERIES, NEW PART FOR EHT TO CORRECT CONVERGENCE DRIFT	10-05	MAR 7, 1980	20
650A/670A/670AL COLORIMITRY, MOD PROPOSAL CTV0325	8-12	APR 21, 1978	16
650A/REWORK OF 119-0320-04 EHT SUPPLIES	10-12	JUNE 13, 1980	9
650HR/147A/149A SERIES, CRYSTAL MAY SHORT CIRCUIT	10-24	DEC 12, 1980	16
653A/656A CIRCUIT BOARDS COMPATIBLE WITH 653HR/656HR CIRCUIT BOARDS	9-08	MAY 4, 1979	18
670 CRT REPLACEMENT KIT	10-25	DEC 19, 1980	8
670 FAMILY DEFLECTION YOKE MOUNTING	8-28	SEPT 29, 1978	27
670 H.V. PHASING PROBLEMS	7-01	JAN 14, 1977	13
670 SERIES RELIABILITY IMPROVEMENT	7-05	MAR 4, 1977	26
670/670A-1 CR5021 NOT GROUNDED	7-09	APR 29, 1977	14
670/671/672 DEFLECTION COIL PARTS REPLACEMENT KIT	10-01	JAN 11, 1980	27
670A - MOD 31454 CORRECTS MOMENTARY CHANGE OF PICTURE SIZE	7-29	NOV 25, 1977	11
670A SCAN FAILURE	8-07	MAR 17, 1978	19
670A SERIES, MODIF TO HORIZNTL OUTPUT CIRCUITS REPLCMT ARTICLE	10-11	MAY 30, 1980	24
670A SERIES, REPLACEMENT OF U5770, U5860, U5945, U5946	10-01	JAN 11, 1980	26
670A SERIES, MODIFICATION TO HORIZONTAL OUTPUT CIRCUITS	10-09	MAY 2, 1980	7
670A SETUP PROCEDURE	8-27	SEPT 15, 1978	27
670A TIP-OUT DOOR	7-05	MAR 4, 1977	26
670A/670A-1/671A, POWER SUPPLY FILTER CAPACITOR MOUNTING BASE	10-01	JAN 11, 1980	26
670A/670A-1 671A/ CR5020 5021 PART NUMBER CHANGE	10-02	JAN 25, 1980	20
670A/670A1/671A BURNING R5230	8-07	MAR 17, 1978	19
670A/670A1/671A BURNING R5230 CORRECTION	8-10	APR 7, 1978	18
670A/671A UNWANTED VERTICAL LINE IN YELLOW COLOR BAR	10-11	MAY 30, 1980	26
670A/671A/670A-1 REPLACEMENT OF CR5020 OR CR5021	10-04	FEB 22, 1980	20
ADAPTER PART NUMBER	7-21	SEPT 9, 1977	14
AMPEX TV PRODUCTS REPAIR	7-17	AUG 5, 1977	13
APPLICATION NOTE 22 CORRECTION	7-25	OCT 21, 1977	12
AVAILABILITY OF CRT SPECS	7-29	NOV 25, 1977	15
C95 SOCKET CORRECTIVE ACTION FOR TV PRODUCTS	9-22	NOV 16, 1979	13
COLOR TEMPERATURE OF 650A/670A SERIES PICTURE MONITORS	7-17	AUG 5, 1977	14
CORRECTION TO 613 HIGH VOLTAGE BOARD ARTICLE	10-02	JAN 25, 1980	21
DISPOSITION OF NCR MICROCARD 833 READERS	7-29	NOV 25, 1977	15
EQUIPMENT REQUIRED FOR A SECAM SYSTEM TV TEST BENCH	9-15	AUG 10, 1979	14
EQUIPMENT REQUIRED FOR A PAL SYSTEM TELEVISION TEST BENCH	9-06	APR 6, 1979	42
FAILING CRYSTALS	7-13	JUNE 24, 1977	23
GMA101A/ GMA102A STORAGE ASSEMBLY MODIFICATIONS 37884, 38046 & 38234	10-02	JAN 25, 1980	21
IC INTERMITTENT FAILURES MAY BE DUE TO DEFECTIVE SOCKETS	9-02	FEB 2, 1979	38

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
LEADLESS SOCKET DISCONTINUED	7-30	DEC 9,1977	20
MICROFICHE STATUS UPDATE	7-29	NOV 25,1977	13
MICROFICHE USER REPRESENTATIVES	7-29	NOV 25,1977	16
MODIFIED 1440 AND INTERFACE COMPATIBILITY	7-07	APR 1,1977	16
MOISTURE ABSORPTION IN COMPOSITION RESISTORS	10-25	DEC 19,1980	7
NEW PERFORMANCE ASSURANCE ENGINEER FOR TV PRODUCTS	10-24	DEC 12,1980	14
R147A/147A, R149A/149A, EQUALIZING PULSE WIDTH	10-01	JAN 11,1980	17
R147A/147A, R149A/149A INCOMPLETE DELETION OF LINE 21, FIELD ONE	10-04	FEB 22,1980	15
R147A/R149A DEFECTIVE CRYSTALS P/N 158-0069-00	10-02	JAN 25,1980	14
R520/R521A/R522A - CRT RETAINER CLAMP BREAKAGE	9-03	FEB 16,1979	26
RECOMMENDED TELEVISION TEST EQUIPMENT - ADDENDUM	9-01	JAN 12,1979	18
RECOMMENDED TELEVISION TEST EQUIPMENT	8-33	DEC 8,1978	15
SHIPPING CARTON KITS FOR 1410 SERIES, L1,L3,PA1,1101,7603 NMS	10-17	AUG 22,1980	9
SPG 1,2,3,11,12,13,22 CHANGE TO SYNC TIMING BOARD	10-04	FEB 22,1980	18
SPG 1/SPG 2, ADJUSTING VARIABLE H BLANKING START AND STOP	10-04	FEB 22,1980	18
SPG 11/12 - WIRE REVERSAL ON P170 REMOTE PLUG	8-28	SEPT 29,1978	26
SPG-1/SPG-2 HORIZONTAL DELAY CHANGES WITH TEMPERATURE CHANGE	9-02	FEB 2,1979	38
SPG/TSP, PART NUMBER FOR CABLE SETS & WIRING HARNESS	10-11	MAY 30,1980	18
SPG1, 2,3,11,12,13,22 CHANGE TO SYNC TIMING BOARD	10-01	JAN 11,1980	17
T.V. GENERAL 151-0164-00	7-07	APR 1,1977	17
TDC SERIES/PART NUMBER 441-1376-00	10-18	SEPT 5,1980	10
TELEVISION PRODUCTS, REMOVAL OF SELECTED TRANSISTOR SOCKETS	10-04	FEB 22,1980	19
TELEVISION BLANKING STANDARDS	8-29	OCT 13,1978	12
TELEVISION PRODUCTS	8-14	MAY 5,1978	11
TRAINING SURVEY FOR TV TECHNICIANS- (REF. PULL-OUT)	10-24	DEC 12,1980	B-1
TSG-1 IMPROVE COLOR BAR OUTPUT ACCURACY	8-25	AUG 18,1978	10
TSG-1 MANUAL CHANGE INFORMATION	9-02	FEB 2,1979	A-1
TSG-1 REDUCING SPURIOUS SUBCARRIER ON WHITE BAR	10-02	JAN 25,1980	14
TSG-12 CORRECT LINEARITY GRATICULE	9-13	JULY 13,1979	8
TSG-16 MULTIBURST FREQUENCY CHANGED	9-16	AUG 24,1979	9
TSG-2 WRONG MANUALS	8-22	JUL 7,1978	18
TSG-5/TSG-6/TSG-15/TSG-16 - MISSING SIGNAL DUE TO SPG TIMING ERROR	9-18	SEPT 21,1979	12
TSG-6/TSG-16/TSG26 TEST FIXTURE UPDATE	9-13	JULY 13,1979	8
TSG16/TSG26 AMPLITUDE VARIATION IN TRIANGLE OUTPUT	9-20	OCT 19,1979	6
TSG2 MANUAL CALIBRATION PROCEDURE ERROR, B020470 AND UP	10-06	MAR 21,1980	11
TSG3 LINEARITY LUMINANCE AMPLITUDE	8-28	SEPT 29,1978	26
TSG5/TSG15 - INTERMITTENT SWITCHES ON THE LOGIC BOARD	8-30	OCT 27,1978	33
TSG5/TSG15 COMPATABILITY PROBLEM WITH OTHER TSG'S	8-13	APR 28,1978	24
TSG6/CABLE HARNESS FRM FRONT PANEL FREQ CONTROL MAY BE CUT	10-19	SEPT 19,1980	15

WIZARDS WORKSHOP INDEX

TELEVISION PRODUCTS

TITLE	ISSUE	DATE	PAGE
TSP-1 CORRECTING PULSE OVERSHOOT	10-02	JAN 25,1980	16
TSP-1/TSP-11 LOSS OF SYNC & BURST INSERTION ON CHANNEL A IN REMOTE OPERATION	9-18	SEPT 21,1979	14
TV GENS/REPLCMNT OF TEK MADE SYNC & TIMING CHIPADDENDUM	10-13	JUNE 27,1980	14
VIDEO CASSETTE ON 653 COLOUR MONITOR	7-06	MAR 18,1977	4
VIDEO TAPE AVAILABLE	7-05	MAR 4,1977	11

WIZARDS WORKSHOP INDEX

COMMUNICATIONS DIVISION (1980)

TITLE	ISSUE	DATE	PAGE
"SCR" PHENOMENA EXHIBITED BY NVM BOARD (ANS.SERVICE BULLETIN #7)	10-17	AUG 22,1980	38
1980 - 1900 COMPATIBILITY (ANSWER SERVICE BULLETIN #10)	10-23	NOV 21,1980	46
ADDITIONAL RECOMMENDED EQUIP FOR 1980 SERV (ANSWER B#2)	10-13	JUNE 27,1980	40
ANSWER SERVICE BULLETIN #1	10-13	JUNE 27,1980	40
FALSE "FPULSE" ERRORS (ANSWER B#4)	10-13	JUNE 27,1980	41
HEAT RELATED CSKIP-F ERROR (ANSWER SERVICE BULLETIN #6)	10-17	AUG 22,1980	38
IMPROPER SETTING OF AIR JUMPER OF NVM BOARD - ANSWER BULLETIN #8	10-21	OCT 17,1980	39
OPTIONAL PATCH ALLOWS GRAPHING VIDEO LINE 263 (ANS.SERV BULLTN#5)	10-16	AUG 8,1980	28
RETURN TO MEASUREMENT ROUTINES AFTER SYSTEM INTERRUPTION(ANSWER B#3)	10-13	JUNE 27,1980	42



WIZARDS WORKSHOP INDEX

SERVICE INSTRUMENT DIVISION

ACCESSORIES

TITLE	ISSUE	DATE	PAGE
1101 POWER SUPPLY RIPPLE	10-10	MAY 16,1980	14
1101 PROBE POWER SUPPLY RELIABILITY	9-15	AUG 10,1979	18
282 TYPE PROBE ADAPTER	10-06	MAR 21,1980	14
AM 503 AC BANDWIDTH IMPROVED	7-31	DEC 16,1977	19
AM 503 CURRENT PROBES AMPLIFIER RELIABILITY	7-02	JAN 21,1977	12
AM 503 CURRENT/DIV SWITCH	9-07	APR 20,1979	31
AM 503 DEGAUSS OSCILLATOR	9-07	APR 20,1979	32
AM 503 PERFORMANCE CHECK AND ADJUSTMENT PROCEDURE CORRECTION	9-08	MAY 4,1979	22
AM 503 POWER SUPPLY OSCILLATION	9-07	APR 20,1979	32
AM 503 POWER SUPPLY NOISE ELIMINATED	7-06	MAR 18,1977	22
AM 503 PRODUCT RELIABILITY MODIFICATION	7-04	FEB 18,1977	18
AM 503/P6302 ADJUSTMENT PROCEDURE CLARIFICATION	7-01	JAN 14,1977	16
C-12/27/30/31 CAMERAS	8-16	MAY 19,1978	11
C-50 SERIES CAMERA CURRENT SURGE	10-22	OCT 31,1980	18
C-51 CAMERA	10-08	APR 18,1980	14
C-51/C-53/C-59 CAMERA OCCLUDER ASSEMBLIES	10-22	OCT 31,1980	18
C28 CAMERA	10-14	JULY 11,1980	12
C52/C53 APERTURE ADJUST GEARS (ARTICLE REPEATED)	9-20	OCT 19,1979	A-1
C52/C53 APERTURE ADJUST GEARS	9-19	OCT 5,1979	11
C5A CAMERA LIGHT LEAK	7-04	FEB 18,1977	16
EFFECTIVE MODULAR-PROBE CABLES	7-10	MAY 13,1977	31
J-16 REPLACEMENT KIT	10-20	OCT 3,1980	21
J6511 SENSITIVITY	10-13	JUNE 27,1980	20
MODULAR PROBE FAILURE REPORTS	7-24	OCT 7,1977	10
P6010 PROBE R103 REPLACEMENT KITS	10-24	DEC 12,1980	18
P6013/P6013A SUPPORT POLICY	10-09	MAY 2,1980	12
P6042 CABLE REPLACEMENT KIT	10-05	MAR 7,1980	25
P6045 FET REPLACEMENT	10-18	SEPT 5,1980	11
P6045 FET REPLACEMENT	10-21	OCT 17,1980	18
P6046, Q123 PARTS REPLACEMENT KIT	10-22	OCT 31,1980	19
P6058 PROBE TIP REPLACEMENT AND UPDATE KIT	10-11	MAY 30,1980	28
P6065A REPLACED BY P6105	9-04	MAR 2,1979	25
P6108 PROBE	10-08	APR 18,1980	15
P61XX PROBE PARTS	7-10	MAY 13,1977	32
P61XX PROBE PARTS CORRECTION	7-11	MAY 27,1977	26
P6201 Q100 REPLACEMENT	10-22	OCT 31,1980	19
P6201 WIRING ERROR	10-21	OCT 17,1980	19
P6202 AND P6420	8-20	JUN 23,1978	21
P6302/P6042 HALL DEVICE EPOXY PROBLEM	10-22	OCT 31,1980	19
P6303 REPLACEMENT TRANSFORMERS	10-03	FEB 8,1980	21
P6303/AM503 PERFORMANCE CHECK AND ADJUSTMENT PROCEDURE CORRECTION	9-08	MAY 4,1979	24
P6451 LABEL	10-04	FEB 22,1980	22

WIZARDS WORKSHOP INDEX

ACCESSORIES

TITLE	ISSUE	DATE	PAGE
P6451 WIRING ERROR	10-07	APR 4,1980	9
PROBE CODE DATE MARKINGS - ACTIVE AND PASSIVE PROBES	7-06	MAR 18,1977	23
PROBE CROSS REFERENCE INDEX	10-13	JUNE 27,1980	21
PROBE CROSS REFERENCE INDEX - CORRECTION	10-14	JULY 11,1980	13
PROBE DATE CODES	10-13	JUNE 27,1980	21
PROBES AND ACCESSORIES FAILURE REPORTS	7-01	JAN 14,1977	16
PROBES, MODULAR, BNC REPLACEMENT	9-14	JUL 27,1979	17

WIZARDS WORKSHOP INDEX

DIGITAL SERVICE INSTRUMENTS

TITLE	ISSUE	DATE	PAGE
067-0878-00 "RS-232 SELF TEST ADAPTER" -- CROSSTALK	10-18	SEPT 5,1980	12
832 833 -- SLIDE SWITCH CONTACTS IN BACKWARDS	10-18	SEPT 5,1980	12
832 CLARIFICATION OF OPTION 2 FIELD MOD KIT-P/N 040-0897-00	10-14	JULY 11,1980	14
833 - TIMING SIGNAL JITTER	10-18	SEPT 5,1980	12
851 "50 MEG OHM RANGE" - (DIFFICULTY MEETING SPECS)	10-17	AUG 22,1980	11
851 "CLEAR TEST" - OPERATOR TRAP	10-14	JULY 11,1980	16
851 "FREQ-RATIO CLEAR AND SAVE TEST" - (IMPROVE RELIABILITY)	10-17	AUG 22,1980	11
851 CALIBRATION AID	10-14	JULY 11,1980	15
851 INTERMITTENT DISPLAYS	10-14	JULY 11,1980	16

DATA COMMUNICATION ANALYZERS

832 833 SLIDE SWITCHES	10-21	OCT 17,1980	22
832 INTERMITTENT ERROR CODE 16 AND/OR PARITY ERRORS	10-11	MAY 30,1980	29
832 MAIN POWER SUPPLY BOARD/SWITCH CHANGE	9-19	OCT 5,1979	14
832 OPERATING INFORMATION	9-25	DEC 21,1979	B-1
832 OPTION 2:040 KIT CORRECTION	10-24	DEC 12,1980	18A
832 OPTION 2 INSTALLATION FOR INFOREX, INC.	9-21	NOV 2,1979	9
832 OPTION STATUS	9-15	AUG 10,1979	19
832 POTENTIAL LOW LINE FAILURE OF THE +12 VOLT SUPPLY	9-19	OCT 5,1979	14
834 SELF TEST ADAPTER	10-20	OCT 3,1980	21
834 USER GUIDE MANUAL ERROR	10-21	OCT 17,1980	20
851 CAPACITOR CHANGE FOR INCREASED PART RELIABILITY	9-19	OCT 5,1979	15
851 POWER SUPPLY PERFORMANCE IMPROVEMENT	10-25	DEC 19,1980	12
SIMULATING 832/833 ASYNCHRONOUS ECHO MODE IN THE 834	10-25	DEC 19,1980	11
USING THE 834 DIAGNOSTICS	10-21	OCT 17,1980	20



WIZARDS WORKSHOP INDEX

LOGIC ANALYZERS

TITLE	ISSUE	DATE	PAGE
067-0872-99 NOW AVAILABLE	10-05	MAR 7,1980	27
156-0229-00 PIN 9 HIGH	8-13	APR 28,1978	16
2942 FAN MOD NOW AVAILABLE	9-12	JUN 29,1979	18
308 AUTO UPDATE MODE	10-09	MAY 2,1980	14
308 OVERHEATING CAPACITORS CAUSES DAMAGE	10-13	JUNE 27,1980	22
4641 PRINTER, RIBBON TENSION	9-18	SEP 21,1979	34
4641 PRINTER, POWER BOARD BURNING OR FUSES BLOWING	9-18	SEP 21,1979	33
672 NEW PART NUMBERS	8-20	JUN 23,1978	18
7D01 "IC SOCKET UPDATE PROGRAM"	8-34	DEC 22,1978	14
7D01 "SOCKET UPDATE PROGRAM"	9-15	AUG 10,1979	20
7D01 - 7903/7904 MECHANICAL INCOMPATIBILITY	7-10	MAY 13,1977	24
7D01 CURSOR SWITCH FIELD MOD CORRECTION	7-31	DEC 16,1977	14
7D01 CURSOR SWITCH FIELD MOD	7-30	DEC 9,1977	18
7D01 CURSOR SWITCH INFORMATION	7-12	JUNE 10,1977	20
7D01 CURSOR SWITCH REPLACEMENT	7-32	DEC 23,1977	9
7D01 ENGINEERING INSTRUMENT SPECIFICATION CHANGE NOTICE	7-31	DEC 16,1977	14
7D01 NOISY CURSOR SWITCH FIX	7-24	OCT 7,1977	16
7D01 OUTPUT BOARD MODIFICATIONS	9-16	AUG 24,1979	11
7D01 POWER SUPPLY CIRCUIT BOARD REPLACEMENT S/N B010100-B020274	8-26	SEPT 1,1978	30
7D01 POWER SUPPLY RELIABILITY MODIFICATION	7-11	MAY 27,1977	22
7D01 RESET CAUSED BY STATIC DISCHARGE	8-09	MAR 31,1978	14
7D01 SOCKET UPDATE CODE 18 TERMINATION PLAN	10-19	SEPT 19,1980	23
7D01 SOCKET UPDATE PROGRAM WORK RECOGNIZER BOARD AND CURSOR BOARD	9-19	OCT 5,1979	16
7D01 SPECIFICATION CHANGED	8-20	JUN 23,1978	18
7D01 SPECIFICATION CHANGE CORRECTION	8-23	JUL 21,1978	24
7D01 STATIC DISCHARGE PROBLEMS	9-01	JAN 12,1979	15
7D01 STATIC DISCHARGE PROBLEM	9-06	APR 6,1979	37
7D01 TROUBLESHOOTING CHART	7-26	OCT 28,1977	20
7D01/7D01F SET UP AND HOLD TIMES	8-06	MAR 10,1978	14
7D01F BLANKING OF TIMING DIAGRAM	8-13	APR 28,1978	17
7D01F COMPONENT RELIABILITY	7-27	NOV 11,1977	13
7D02 FAILURE TO POWER UP	10-23	NOV 21,1980	27
7D02 PERSONALITY MODULE LOOPBACK	10-23	NOV 21,1980	30
BATTERY POWER FOR THE 308	10-09	MAY 2,1980	13
DF1 - 156-0291-00 DEFECTIVE DATE CODES "SIGNETICS"	7-22	SEPT 23,1977	18
DF1 - 156-0882-00 DEFECTIVE DATE CODE "GI BRAND"	7-22	SEPT 23,1977	18
DF1 MICROPROCESSOR MOD KIT	7-32	DEC 23,1977	9
DF1 S/N B033535 & UP REPLACEMENT OF C568	8-21	JUN 30,1978	16
DF1 SUPPORT	7-07	APR 1,1977	20
DF1 U263 REPLACEMENT	8-20	JUN 23,1978	17
DF1 USER INPUT	7-27	NOV 11,1977	13
DF1 WITH EXTRA DOTS IN MAP AFTER REPLACEMENT OF 6800-CPU	7-24	OCT 7,1977	12

WIZARDS WORKSHOP INDEX

LOGIC ANALYZERS

TITLE	ISSUE	DATE	PAGE
DF1/DF2 DIAGNOSTIC TEST PACKAGE	8-33	DEC 8,1978	14
DF1/DF2 INTERMITTENT MICROPROCESSOR U264 (SYMPTOM SIMILAR TO DEFECTIVE SOCKET)	9-06	APR 6,1979	36
DF1/DF2 U 422 REPLACEMENT	8-21	JUN 30,1978	16
DF1/DF2 U264 REPLACEMENT	8-21	JUN 30,1978	16
DF1/DF2 USE CHECKED 2101 ROM'S	8-13	APR 28,1978	16
DF1/DF2, INTERMITTENT U412 (SYMPTOM SIMILAR TO DEFECTIVE SOCKET)	9-06	APR 6,1979	36
DF2 ASCII CONVERSION TABLE	8-33	DEC 8,1978	14
DF2 MANUAL ERROR (CORRECTION TO WIZARDS WORKSHOP ISSUE 9-5, MAR 15, 1979)	9-06	APR 6,1979	37
DF2 MANUAL ERROR	9-05	MAR 16,1979	16
DL 2 SPECIFICATION CHANGE	8-21	JUN 30,1978	17
DL 502 SPECIFICATION CHANGE	8-21	JUN 30,1978	17
LA 501 -- COLLECTOR OF Q910 SHORTING	8-06	MAR 10,1978	11
LA 501 CAPACITORS PHYSICALLY TOO LARGE	8-06	MAR 10,1978	11
LA 501 CURE FOR FRONT PANEL...INTERMITTENT (R690,R695, R740 & R745)	7-16	JULY 29,1977	17
LA 501 PART NUMBER ERROR	8-06	MAR 10,1978	12
LA 501, DF1/2, WR 501 DL 502 CAPACITOR FAILURES	8-21	JUN 30,1978	17
LA 501/LA 501W RELIABILITY IMPROVEMENTS	8-06	MAR 10,1978	12
LA 501W WIRING DIAGRAM FOR INTERCONNECT CABLES	8-06	MAR 10,1978	12
LA 501W/OSCILLOSCOPE COMPATABILITY LIST	7-26	OCT 28,1977	18
LA501 NEW MANUAL	10-09	MAY 2,1980	13
LOGIC ANALYZER CANNON PLUGS P/N 131-1345-00--DEFECTIVE -"PURGE".	10-18	SEPT 5,1980	13
LOGIC ANALYZER DEMO AID/TEST AID	8-13	APR 28,1978	16
S-3000 SERIES MICROFICHE NOW AVAILABLE	9-12	JUN 29,1979	15
S-3200 PDP/34-XE STANDARD CONFIGURATION	9-12	JUN 29,1979	16
S-3200-5V POWER SUPPLY REPLACEMENT	9-12	JUN 29,1979	18
S-3455 AUDIO TAPES	9-12	JUN 29,1979	18
VIDEO TAPES AVAILABLE	7-03	FEB 4,1977	6

PORTABLES

TITLE	ISSUE	DATE	PAGE
1105 BATTERY SET REPLACEMENT	10-09	MAY 2,1980	17
200 SERIES "APPARENT" WET SPOTS ON CRT FACEPLATE	8-04	FEB 17,1978	16
200 SERIES BATTERY PACK REPLACEMENT	8-27	SEPT 15,1978	23
200 SERIES OSCILLOSCOPE SWEEP AND TRIGGER GENERATOR IC REPLACEMENT HISTORY	8-22	JUL 7,1978	13
200 SERIES OSCILLOSCOPE TRIGGER/SWEEP GENERATOR REPLACEMENT KITS	8-29	OCT 13,1978	11
200 SERIES TRACE ROTATION COILS, CORRECTION	7-25	OCT 21,1977	11
200 SERIES TRACE ROTATION COILS	7-23	SEPT 30,1977	10
211 212 213 214 221 POWER CORD	10-16	AUG 8,1980	13
212/214 HORIZONTAL MAGNIFICATION POT	10-24	DEC 12,1980	19
212/214 REPLACING Q388 AND SELECTING R388	10-24	DEC 12,1980	20
212/214 SHORTENED SWEEP CAUSED BY U370 OSCILLATING	8-19	JUN 9,1978	22
212/214 SHORTENED SWEEP	9-13	JULY 13,1979	12
212/214 VERTICAL NOISE	9-13	JULY 13,1979	14
212/214 VERTICAL INPUT FET CHANGE	9-23	NOV 30,1979	15
212/221 IMPROVED BATTERY RELIABILITY	7-25	OCT 21,1977	11
213 - 155-0114-00 - DEFECTIVE DATE CODES	8-07	MAR 17,1978	18
213 SHORTENED SWEEP CAUSED BY U335 OSCILLATING	8-19	JUN 9,1978	23
214 - U320 INSERTED INCORRECTLY	10-18	SEPT 5,1980	14
214 FREE RUNS IN SINGLE SWEEP AT HIGH SWEEP SPEEDS	10-24	DEC 12,1980	21
214 POWER SUPPLY LOADING IN STORAGE MODE	10-03	FEB 8,1980	22
214 UNRELIABLE TRIGGER IN SINGLE SWEEP MODE	8-19	JUN 9,1978	23
221 211 212 213 214 POWER CORD	10-16	AUG 8,1980	13
221 CHARGER CIRCUIT IMPROVEMENT	8-17	MAY 26,1978	6
221 TRANSFORMER SHIELD ASSEMBLY CORRECTION	10-14	JULY 11,1980	17
221 VERTICAL DRIVE TRANSISTOR PROTECTION	8-13	APR 28,1978	18
305 HIGH VOLTAGE MODULE WITH CONNECTORS	10-06	MAR 21,1980	17
305 NOISE ON SQUARE WAVE SIGNAL	9-15	AUG 10,1979	25
305 VERTICAL GAIN CHANGES	9-13	JULY 13,1979	16
305DMM RESISTANCE MEASUREMENT ERROR	9-15	AUG 10,1979	24
314 - NO INTENSITY DUE TO Q703, Q704 FAILURE	9-19	OCT 5,1979	17
314 ADJUSTING INTENSITY LIMIT	9-17	SEPT 7,1979	14
314 IMPROVE MAGNIFIED TIMING LINEARITY	8-13	APR 28,1978	19
314 READY LIGHT REMAINS ON	7-04	FEB 18,1977	17
314 RELIABILITY MOD: 31023	7-01	JAN 14,1977	13
314--GEOMETRY ADJ. FULLY CW AND +170V SUPPLY RIPPLE IS MARGINAL	7-17	AUG 5,1977	19
314/335 CRT MOUNTING SCREWS	7-12	JUNE 10,1977	21
323 DIFFICULT TO AMPLIFY 4 MHZ SIGNAL TO SIX DIVISIONS	8-08	MAR 24,1978	10
323 IMPROVE MAGNIFIED TIMING LINEARITY	8-13	APR 28,1978	19
323--IMPROVE HIGH VOLTAGE REGULATION	7-17	AUG 5,1977	19
326 - CIRCUIT IMPROVEMENTS AND Q464 AND Q474 REPLACEMENT	8-12	APR 21,1978	12
326 CRT PART NUMBER CHANGE ADDENDUM	8-33	DEC 8,1978	15

PORTABLES

TITLE	ISSUE	DATE	PAGE
326 CRT PART NUMBER CHANGE	8-31	NOV 10,1978	19
326 IMPROVED CH. 2, 1 VOLT, 10 MHZ BANDWIDTH	8-24	AUG 4,1978	17
326 POWER SUPPLY TRANSFORMER FAILURE	9-10	JUN 1,1979	10
335 - VERTICAL OUTPUT AMPLIFIER OSCILLATES	8-08	MAR 24,1978	11
335 DELAY TIME MULTIPLIER POT	9-17	SEPT 7,1979	15
335 DRIFT IMPROVEMENT OF EXTERNAL HORIZONTAL VARIABLE BALANCE	7-01	JAN 14,1977	14
335 FREQUENCY RESPONSE AND STEP RESPONSE SPECIFICATION CHANGES	8-13	APR 28,1978	20
335 IMPROVE HIGH VOLTAGE REGULATION	7-30	DEC 9,1977	18
335 IMPROVE RELIABILITY OF THE X2 HV MULTIPLIER	7-17	AUG 5,1977	20
335 MOD WP "FOLLOW UP"	8-18	JUN 2,1978	9
335 NEW CUSTOM MODIFICATION - "WP"	8-13	APR 28,1978	20
335 PREVENT VARIABLE TIME/DIVISION COUPLER FROM LOOSENING	8-08	MAR 24,1978	10
335 SELECTING R1218 WHEN CHANGING THE CRT	9-23	NOV 30,1979	20
335 UNSTABLE TRIGGERING IN AUTO AT 20HZ	9-18	SEPT 21,1979	19
335, 070-1943-00, MANUAL CORRECTION (CORRECTION)	7-17	AUG 5,1977	6
335, 070-1943-00, MANUAL CORRECTION	7-15	JULY 22,1977	23
335--PLASTIC SLEEVE PART NUMBERED	8-01	JAN 20,1978	16
335--SWEEP LENGTH IS MARGINAL, OPERATING TIME OF LOW LINE INDICATOR IS TOO SHORT	7-17	AUG 5,1977	20
400 SERIES TIMING SWITCH CHANGE (A REFERENCE PULLOUT)	8-31	NOV 10,1978	1
434 BELOW B50, CHANNEL 2 INTERMITTENT POSITIONING	10-05	MAR 7,1980	28
434 CHANNEL 2, 1MV ABERRATION IMPROVEMENT	7-32	DEC 23,1977	10
434 DIODE BREAKAGE PRIOR TO SERIAL NUMBER B500000	7-04	FEB 18,1977	18
434 INCORRECT POWER SUPPLY BURST MODE	9-05	MAR 16,1979	25
434 INTENSITY MODULATION B528370-B528420	8-06	MAR 10,1978	18
434 INTERMITTENT BURST MODE	10-12	JUNE 13,1980	13
434 POTENTIAL POWER SUPPLY SHUT DOWN IF U1910 IS REPLACED	9-05	MAR 16,1979	25
434 POWER SUPPLY SHUTDOWN CORRECTION	8-01	JAN 20,1978	17
434 POWER SUPPLY SHUTDOWN, B0527800 TO B0528170	7-31	DEC 16,1977	17
434 PROBE CODING LIGHTS	9-15	AUG 10,1979	25
434/475 POLYSULFONE	7-01	JAN 14,1977	15
434/485 POWER SUPPLY REGULATOR, 155-0067-02	9-20	OCT 19,197	9
442 AND T900 SERIES, Q458 REPLACEMENT	9-16	AUG 24,1975	12
442 AND T900 SERIES INTERMITTENT CHASSIS MOUNTED TRANSISTORS	8-04	FEB 17,1978	17
442 CALIBRATION SHIELD	8-13	APR 28,1978	21
442 FUSE HOLDER IS REWIRED	10-24	DEC 12,1980	21
442 H.V. OSCILLATOR, Q458 HEAT SINKING	10-05	MAR 7,1980	29
442 HALO - SUPPRESSANT CRT MOD KIT P/N (050-1150-00)	9-15	AUG 10,1979	27
442 HALO SUPPRESSANT CRT	8-24	AUG 4,1978	18
442 MANUAL NOW AVAILABLE	7-22	SEPT 23,1977	4
442 PILOT CHANGE CORRECTION	8-24	AUG 4,1978	18
442 PILOT CHANGES - ADDENDUM	8-12	APR 21,1978	13

WIZARDS WORKSHOP INDEX

PORTABLES

TITLE	ISSUE	DATE	PAGE
442 PILOT CHANGES	8-10	APR 7,1978	11
442 Q4388 CASE SHORTING	8-24	AUG 4,1978	19
442 TRACE FLICKER AT 2MS/DIV	8-24	AUG 4,1978	19
442 TRIGGER SWITCH BINDING	10-06	MAR 21,1980	18
442 TRIGGER CIRCUIT NOISE REDUCTION	8-24	AUG 4,1978	20
442 TROUBLESHOOTING CHART (REF PULL-OUT)	10-12	JUNE 13,1980	A-1
442 Z AXIS TRANSIENT RESPONSE IMPROVED	8-24	AUG 4,1978	20
442/T912/T922/T932/T935/T932A/T935A/442 DOUBLE TRIGGERING	9-15	AUG 10,1979	23
442/T932A/T935A VERTICAL DRIFT	9-21	NOV 2,1979	10
453'S FILAMENT WINDING LEAD DRESS ON HIGH-VOLTAGE TRANSFORMERS	7-07	APR 1,1977	27
453/453A REPLACEMENT VERTICAL PREAMP & ATTENUATOR ASSEMBLIES	8-31	NOV 10,1978	20
453/454 SPECIFICATION CHANGE	7-10	MAY 13,1977	30
454/454A CALIBRATION TEST EQUIPMENT CHANGE (109/113)	7-02	JAN 21,1977	13
454/R REPLACEMENT OF P/N 151-0213-00, 151-0222-00 TRANSISTORS	10-05	MAR 7,1980	30
455 +5V LATCH UP	7-23	SEPT 30,1977	10
455 A2 & B2 MODULE CONNECTOR INTERMITTENT	8-09	MAR 31,1978	14
455 EXTENDER CABLE	7-06	MAR 18,1977	22
455 HIGH VOLTAGE BURSTING	7-05	MAR 4,1977	31
455 SCALE FACTOR LED PART NUMBER CHANGE	9-04	MAR 2,1979	23
455 SWEEP GENERATOR IC PROTECTION BELOW B050000	7-32	DEC 23,1977	11
455 U4160, PART NUMBER CHANGE	7-25	OCT 21,1977	11
455 VERTICAL INPUT CIRCUIT CAPACITOR ADDITION ADDENDUM	8-04	FEB 17,1978	18
455 VERTICAL INPUT CIRCUIT CAPACITOR ADDITION	8-02	JAN 27,1978	11
455, IMPROVED NORMAL TRIGGER AT 50 MHZ	8-24	AUG 4,1978	21
455/465M AND USM 465: TROUBLESHOOTING THE HIGH VOLTAGE	9-02	FEB 2,1979	26
455/465M/USM425 INTERMITTENT VERTICAL IC'S	7-25	OCT 21,1977	12
455/465M/USM425: FOCUS POT VENDOR CHANGE	8-22	JUL 7,1978	16
455/465M/USM425; LEAD CONFIGURATION OF P/N 151-1090-02	9-05	MAR 16,1979	26
455A2B2 EXCESSIVE BANDWIDTH (>70MHZ)	9-18	SEPT 21,1979	20
455A2B2/465 +5 VOLT LATCH UP	9-15	AUG 10,1979	27
455A2B2/465M Q552 PART NUMBER CHANGE	9-15	AUG 10,1979	27
455AB F736 BLOWS	7-02	JAN 21,1977	13
460 AND 470 SERIES BANDWIDTH LIMIT--TRIGGER VIEW SWITCH REPLACEMENT AID	8-06	MAR 10,1978	18
460 AND 470 SERIES PORTABLES ELECTROLYTIC CAP FAILURES ADDENDUM	8-05	MAR 3,1978	19
460 AND 470 SERIES PORTABLES ELECTROLYTIC CAP FAILURES	8-04	FEB 17,1978	18
460/470 SERIES JUMPY VERTICALS	9-03	FEB 16,1979	23
464 466 VERTICAL OSCILLATIONS	10-19	SEPT 19,1980	24
464 BELOW B132140 -- 466 BELOW B134620	7-11	MAY 27,1977	25
464,465,466,475/A 485 PRESS NUTS USED TO MOUNT REAR FEET	10-13	JUNE 27,1980	24
464/465/465B/475/475A ACCESSORY POUCH PARTS BREAKDOWN	9-25	DEC 21,1979	29

WIZARDS WORKSHOP INDEX

PORTABLES

TITLE	ISSUE	DATE	PAGE
464/465/466 BURNED CONTACT ON TIMING BOARD	9-03	FEB 16,1979	23
464/465/466 CONTACT 15 BURNED	7-01	JAN 14,1977	15
464/465/466 DM 44 1/TIME COUNT DRIFT	7-09	APR 29,1977	19
464/465/466 DOUBLE TRIGGERING	7-08	APR 15,1977	14
464/465/466 JUMPY VERTICALS	7-09	APR 29,1977	20
464/465/466 VARIABLE VOLT/DIV POT, P/N 311-1364-00	9-15	AUG 10,1979	28
464/465/466/475 HEAT STAKING PIN FOR INSTALLING BANDWIDTH LIMIT AND TRIGGER	8-27	SEPT 15,1978	23
464/465/466/475/475A HIGH VOLTAGE CAP. CHANGE	9-13	JULY 13,1979	16
464/465/466/475/475A SERIES - FAN MOTOR BOARD CHANGES	9-13	JULY 13,1979	18
464/465/466/475A TIMING SWITCH ADDENDUM	9-16	AUG 24,1979	13
464/466 ABNORMAL VARIABLE VIEW TIME OPERATION	9-04	MAR 2,1979	24
464/466 BRIDGE RECTIFIER BATCH PROBLEM	7-13	JUNE 24,1977	27
464/466 LOW FREQUENCY COMPENSATION	8-14	MAY 5,1978	9
464/466 LOW FREQUENCY COMPENSATION	7-07	APR 1,1977	27
464/466 OPTION 10 MANUAL	9-13	JULY 13,1979	24
464/466 REAR CORD WRAP MOD	9-20	OCT 19,1979	9
464/466 SN B010100 TO B120000 INTENSITY FLICKER ELIMINATED	7-07	APR 1,1977	26
465 +110 VOLT SUPPLY SHUTDOWN	9-08	MAY 4,1979	29
465 - 311-1430-00 - ERRATIC, INTERMITTENT AND/OR DRIFT	8-04	FEB 17,1978	18
465 INTERMITTENT INPUT	7-01	JAN 14,1977	16
465 LOOSE HARDWARE ON BNC CONNECTORS	7-02	JAN 21,1977	14
465 MAJOR FAILURE:...SWEEP GENERATOR & POWER SUPPLY	8-30	OCT 27,1978	28
465 MAJOR FAILURE ADDENDUM	8-34	DEC 22,1978	17
465 MOD UC INCORRECT IC PART NUMBER	10-14	JULY 11,1980	19
465 OPTION 5 MANUAL SUPPLEMENT	8-30	OCT 27,1978	29
465 REPLACE C1220 IN UNITS BELOW B294620	10-07	APR 4,1980	10
465 TRANSISTOR CHANGES IN CHOP AND UNBLANKING CIRCUITS	9-05	MAR 16,1979	28
465 VERTICAL OSCILLATIONS, HF COMPENSATIONS	10-05	MAR 7,1980	30
465 VOLTAGE SUPPLY FAILURES AND INTERMITTENTS	9-03	FEB 16,1979	25
465/465B VERTICAL OSCILLATIONS	10-05	MAR 7,1980	31
465/475 TO 465/475DM44 MOD KITS	9-24	DEC 14,1979	11
465/475/475A HIGH VOLTAGE ARCING	7-30	DEC 9,1977	19
465/475A VERTICAL AND HORIZONTAL OSCILLATIONS	9-14	JULY 27,1979	18
465B ADJUSTING H.F. ABERRATIONS AFTER CHANGING INPUT FET	10-09	MAY 2,1980	15
465B DTM JITTER	10-23	NOV 21,1980	32
465B FAST SWEEP LINEARITY	10-09	MAY 2,1980	16
465B INTERMITTENT RISE TIME IN 5 VOLTS/DIV	10-24	DEC 12,1980	21
465B RISETIME AT 5 VOLTS/DIV IMPROVED	10-19	SEPT 19,1980	27
465B UNSTABLE B TRIGGERING	10-09	MAY 2,1980	16
465B/DM44 FIELD INSTALLATION KIT	9-24	DEC 14,1979	11
465B44, 475A44 PROPER DESIGNATIONS	10-13	JUNE 27,1980	25
465M PARTS LIST	8-08	MAR 24,1978	11